

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 7106D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL GATE	DENTED / BENT	1,787.00	1,787.00
1	TAIL GATE INNER LOCK	NOT NECESSARY	371.20	-
1	REAR W/SCREEN INNER MOULDING	NECESSARY	313.30	285.90
1	REAR END PANEL OUTER	TO REPAIR SEE LABOUR	581.10	-
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	671.90	-
1	REAR BUMPER	DENTED	671.50	488.20
1	REAR END PANEL TOP PLATE	NOT NECESSARY	139.20	-
1	REAR EXHAUST SILENCER BOX	SERVICEABLE	876.00	-
1	SPARE TYRE CARRIAGE	TO REPAIR SEE LABOUR	298.70	-
1	TAIL LAMP RH	SERVICEABLE	374.10	-
1	TAIL LAMP LH	NOT NECESSARY	374.10	-
1	TAIL LAMP LOWER PANEL RH	TO REPAIR SEE LABOUR	181.00	-
1	TAIL LAMP LOWER PANEL LH	DENTED	181.00	181.00
2	REAR BUMPER BRACKET @\$90.20	SERVICEABLE	180.40	-
2	REAR BUMPER SIDE RETAINER @\$69.00	SERVICEABLE	138.00	-
1	TAIL GATE OUTER GARNISH	NOT NECESSARY	169.20	-
	LESS 25% DISCOUNT		-1,826.93	-685.53
			5,480.77	2,056.57
1	BOOT WHEATHERSTRIP (SN) (50%)	NECESSARY / DEFORMED	328.50	164.25
	LESS 25% DISCOUNT		-82.13	-
			246.37	164.25
	NETT ITEMS			
1	TOYOTA LOGO (N)	NECESSARY	68.00	68.00
	LESS 25% DISCOUNT		-	-17.00
			68.00	51.00

Report Ref No. CS1/MSG21001142/Dqe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	MALFUNCTION / DISTORTED	250.00	200.00
1	REAR W/SCREEN SEALANT (SN)	NECESSARY	65.00	40.00
1	70KM/H STICKER (SN)	NECESSARY	25.00	15.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	15.00
1	TAIL GATE ADV STICKER (SN)	NECESSARY	500.00	400.00
1	FLOOR PANEL (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
1	TAIL LAMP PANEL LH (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
			870.00	670.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, PANEL BEATING, CUT AND WELD AND REPOSITION. (REAR). INCLUSIVE OF THE REPAIR OF REAR END PANEL OUTER, REAR END PANEL INNER, SPARE TYRE CARRIAGE, TAIL LAMP LOWER PANEL RH, FLOOR PANEL AND TAIL LAMP PANEL LH.		1,200.00	600.00
	TO PUTTY AND SPRAY PAINT THE REPAIRED AND REPLACED PARTS, CLEANING AND SANDING OF SURFACE, FINAL POLISHING AND WAXING (REAR).		1,200.00	600.00
	TO CHECK REAR LIGHTING AND WIRING SYSTEM.		80.00	30.00
	TO REMOVE AND REFIT REAR UPHOLSTERY, CARPET, TRIM ETC.		100.00	50.00
	TO REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	TO REMOVE AND REPLACE REVERSE SENSORS.		100.00	40.00
	TO SPRAY RUST PROOFING AND UNDER COATING.		80.00	40.00
			2,910.00	1,480.00
	GRAND TOTAL		9,575.14	4,421.82

RECOMMENDED COST OF LUMP SUM REPAIRS		3,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS1/MSG21001142/Dqe2

ANG PRYAN TAI

ANG BRYAN TANI

Automotive Assessor / Investigator