



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2103507

INV Date 18/05/2021

Reference CC4/LPC21001143/Upa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKZ 3639X

Insured Veh. SJB 4077Z

Claim No. 21/21/21/VP05/028122

Policy No. Z21VP05028122

Accident Date 22/01/2021

Inspection Date 25/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21001143/Upa3q2 Date: 18/05/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJB 4077Z	Veh. Inspected	SKZ 3639X	
Policy No.	Z21VP05028122	Coverage (\$)	0.00	
Claim No.	21/21/21/VP05/028122	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	25/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI (A)	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	SJNFEAJ11U1571325	Colour	PURPLE	
Odometer	61003 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	TOYO	6 mm	
L/H Front Tyre	215/60 R17	TOYO	6 mm	
R/H Rear Tyre	215/60 R17	TOYO	6 mm	
L/H Rear Tyre	215/60 R17	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/01/2021	Inspection Date	25/01/2021	
Survey held at	NPH AUTO SERVICE BLK 9005 TAMPINES STREET 93 #01-246/254 SINGAPORE 528839			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 3639X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT (N)	DENTED/ BUCKLED	3,062.60	3,062.60
1	REAR BOOT CENTER LOGO (N)	NECESSARY	70.00	70.00
1	REAR BOOT QASHQAI EMBLEM (N)	NECESSARY	94.40	94.40
1	REAR BOOT LAMP LH (N)	SCRATCHED	231.60	231.60
2	REAR LAMP ASSEMBLY L&R @\$346.90 (N)	N/S CRACKED	693.80	346.90
2	REAR BOOT DAMPE L&R @\$250.00(N)	NOT NECESSARY	500.00	-
1	REAR BOOT LOCK (N)	TWISTED	190.50	190.50
1	SET REAR BOOT FINISHER CLIPS (N)	NECESSARY	51.00	51.00
1	REAR BUMPER ASSEMBLY (N)	DISTORTED	796.70	796.70
2	REAR BUMPER SIDE RETAINER L&R @\$42.00 (N)	BENT	84.00	84.00
2	REAR BUMPER REFLECTOR LAMP L&R @\$68.10 (N)	N/S CRACKED	136.20	68.10
1	REAR BUMPER TOWING HOOK COVER(N)	TORN	24.00	24.00
1	REAR BOOT RUBBER (N)	TWISTED	167.00	167.00
1	REAR BONNET LOCK LOWER CATCH (N)	NOT NECESSARY	46.00	-
1	REAR BUMPER ENFORCEMENT (N)	BENT	691.50	691.50
1	REAR BUMPER SPONGE (N)	TORN	162.00	162.00
1	REAR LAMP CENTER PANEL (N)	BADLY DENTED / BENT	482.60	482.60
1	REAR LAMP CENTER PANEL INNER GARNISH (N)	NOT NECESSARY	78.00	-
1	REAR SPARE TYRE TOOL FOAM (N)	NOT NECESSARY	325.00	-
1	REAR SPARE TYRE BOARD (N)	NOT NECESSARY	506.00	-
1	REAR EXHAUST BOX (N)	TO REPAIR SEE LABOUR	632.00	-
1	REAR WHEELARCH GARNISH LH (N)	NOT NECESSARY	540.50	-
1	SET REAR BUMPER CLIPS (N)	NECESSARY	112.00	45.00
1	REAR BUMPER SPONGE INNER SENSOR (N) (ADDITIONAL)	CRACKED	111.00	111.00
2	REAR BUMPER ENFORCEMENT BRACKET @\$141.00 (N) (ADDITIONAL)	DENTED	282.00	282.00
1	REAR EXHAUST MOUNTING RUBBER (N) (ADDITIONAL)	TORN	22.00	22.00
	LESS 10% DISCOUNT		-1,009.24	-698.29
			9,083.16	6,284.61

Report Ref No. CC4/LPC21001143/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE WITH CASING (SN)	SERVICEABLE	45.00	-
1	SET REAR BUMPER PARKING SENSOR (SN)	SHORTED	400.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	45.00	40.00
			490.00	240.00
	<u>LABOUR</u>			
	REMOVE AND INSTALL REAR WINDSCREEN .		150.00	120.00
	REMOVE AND INSTALL REAR SEAT CARPET ,ROOFTOP UPHOLSTERY .		150.00	80.00
	CHECK WIRING SYSTEM.		35.00	20.00
	RENEW PARKING SENSOR .		100.00	50.00
	REMOVE AND INSTALL REAR BOOT ,REAR LAMP ,REAR BUMPER ,CUT OUT AND RENEW REAR LAMP CENTER PANEL ,KNOCKING SPARE TYRE PANEL & RESTRAIGHTEN BODY AND CHASSIS .INCLUSIVE OF THE REPAIR OF REAR EXHAUST BOX.		1,300.00	1,080.00
	SPRAY PAINTING .		1,300.00	1,080.00
	REMOVE AND INSTALL REAR EXHAUST BOX .		100.00	60.00
			3,135.00	2,490.00
GRAND TOTAL			12,708.16	9,014.61
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,200.00

Report Ref No. CC4/LPC21001143/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 3639X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 3639X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 3639X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 3639X

RE-INSPECTION

