

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III21001145/UGS3Q2**Date:** 25/06/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	GBE7844K	<b>Insured Vehicle No :</b>	SHD3504C
Date of Loss:	16/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120313

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBE7844K</b>	Engine No:	ZD30009667N
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Chassis No:	JN1SC2F24Z0858312
Reg. Date:	29/03/2016 (Man. Year: 2016)	Odometer:	217184 km
Colour:	Silver		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/75 R15	Rear Tyre Size:	155 R13 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Yokohama 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	22,833.00	2,126.04	20,706.96	90.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,790.00	2,020.00	2,770.00	57.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>27,623.00</b>	<b>4,146.04</b>	<b>23,476.96</b>	<b>84.99</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,300.00</b>		

<b>Nett Amount (S\$)</b>	<b>27,623.00</b>	<b>3,300.00</b>	<b>24,323.00</b>	<b>88.05</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>		300.00		
<b>Nett Liability (S\$)</b>		<b>3,600.00</b>		

INSPECTION

Date of Assignment: 25/01/2021

Date Inspected: 25/01/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Choo Motor Spray Painter (HQ)  
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit  
Singapore 417883

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 21 May 2021)	
<b>Parts:</b>	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE7844K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,668.00 F	*- FL
2	1		*TAILGATE ,NISSAN STICKER	Necessary	175.00 F	*175.00 FL
3	1		*TAILGATE LOWER MEMBER	Bent	688.00 F	*522.10 FL
4	2		*TAILGATE LOCK LATCHS	Not Necessary	430.00 F	*- FL
5	2		*TAILGATE HINGES	Not Necessary	100.00 F	*- FL
6	2		*TAILGATE L LOWER PANELS	Not Necessary	290.00 F	*- FL
7	2		*TAILGATE L LOWER PANEL STOPPERS	Not Necessary	242.00 F	*- FL
8	2		*TAILLAMPS	Cracked	416.00 F	*416.00 FL
9	2		*TAILLAMP BRACKETS	No such part	330.00 F	*- FL
10	2		*DROP SIDEGATES	Not Necessary	5,996.00 F	*- FL
11	2		*DROP SIDEGATE LOWER PANELS	Not Necessary	1,962.00 F	*- FL
12	1		*REAR SPARE TYRE CHAIN & BRACKET	Bent / Jammed	4,551.00 F	*322.50 FL
13	1		*CHASSIS FRAME O/S	Repair	3,800.00 F	*- FL
14	1		*SET 70KM/H 13 PAX STICKER	Necessary	25.00 FS	*20.00 FS
15	1		*SET REAR REVERSE SENSOR	Cracked	280.00 FS	*200.00 FS
16	1		*SET REAR STEP PANEL BRACKET	Bent	850.00 FS	*600.00 FS
17	1		*REAR LICENCE PLATE	Bent	30.00 FS	*14.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>22,833.00</b>	<b>2,269.60</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>	0.00	143.56
<b>Total Parts (\$)</b>	<b>22,833.00</b>	<b>2,126.04</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO LIFT UP REAR CARGO DECK FOR REPAIR CHASSIS	New	880.00	300.00
4	TO SPRAY RUST PROOFING	New	180.00	50.00
5	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	1,000.00
6	TO PUTTY & SPRAY PAINTING	New	1,800.00	600.00
			<b>Gross Labour Cost (S\$)</b>	<b>2,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >