



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2104048

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/06/2021
Reference CC6/CTI21001148/Ura3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SJY 808L
Insured Veh. SMM 4664K
Claim No. SNM21D200433
Policy No. DMPCSNW00059562000
Accident Date 23/01/2021
Inspection Date 25/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21001148/Ura3q2 Date: 10/06/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMM 4664K	Veh. Inspected	SJY 808L
	Policy No.	DMPCSNW00059562000	Coverage (\$)	0.00
	Claim No.	SNM21D200433	Excess (\$)	0.00
	Assign From		Assign Date	25/01/2021
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 318i (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	WBAPF72060A143481	Colour	GREY
	Odometer	272370 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/35Z R19	CONTINENTAL	6 mm
	L/H Front Tyre	235/35Z R19	CONTINENTAL	6 mm
	R/H Rear Tyre	235/35Z R19	CONTINENTAL	6 mm
	L/H Rear Tyre	235/35Z R19	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/01/2021	Inspection Date	25/01/2021
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 808L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR O/S	DENTED / BENT	2,210.00	1,920.00
1	FRONT DOOR GLASS OUTER MOULDING O/S	NECESSARY	205.00	192.00
1	FRONT DOOR GLASS REGULATOR & MOTOR O/S	NOT NECESSARY	485.00	-
1	SET FRONT DOOR FRAME BLACK STICKER O/S	NECESSARY	110.00	70.00
1	FRONT DOOR INNER LOCK O/S	NOT NECESSARY	392.00	-
1	FRONT DOOR INNER TRIM BOARD O/S	CRACKED	1,080.00	820.00
1	FRONT DOOR INNER RUBBER O/S	NECESSARY	366.00	266.00
1	FRONT DOOR OUTER HANDLE O/S	NOT NECESSARY	292.00	-
2	FRONT DOOR HINGES @\$150.00	NOT NECESSARY	300.00	-
1	FRONT DOOR CHECK O/S	NOT NECESSARY	182.00	-
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	1,455.00	-
1	REAR BUMPER	NOT NECESSARY	1,205.00	-
1	CENTRE PILLAR OUTER O/S	DENTED / BENT	1,020.00	895.00
1	ROCKER PANEL O/S	TO REPAIR SEE LABOUR	988.00	-
1	ROCKER PANEL GARNISH O/S	DEFORMED / TORN	950.00	650.00
1	REAR DOOR O/S	DISTORTED	1,950.00	1,880.00
1	REAR DOOR GLASS OUTER MOULDING O/S	NECESSARY	202.00	190.00
1	REAR DOOR GLASS REGULATOR & MOTOR O/S	BENT / SHORTED	465.00	465.00
1	SET REAR DOOR FRAME BLACK STICKER O/S	NECESSARY	110.00	78.00
1	REAR DOOR INNER LOCK O/S	SHORTED	390.00	390.00
1	REAR DOOR INNER TRIM BOARD O/S	DEFORMED / CRACKED	980.00	800.00
1	REAR DOOR INNER RUBBER O/S	NECESSARY	366.00	265.00
1	REAR DOOR OUTER HANDLE O/S	NOT NECESSARY	292.00	-
2	REAR DOOR HINGES @\$150.00	BENT	300.00	300.00
1	REAR DOOR CHECKER O/S	TWISTED	182.00	181.00
	LESS 10% DISCOUNT		-	-936.20
			16,477.00	8,425.80



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR SPORT RIM O/S (SN)	TO REPAIR SEE LABOUR	800.00	-
1	SET FRONT DOOR INNER TRIM BOARD CLIPS O/S (SN)	NECESSARY	50.00	50.00
1	SET REAR DOOR INNER TRIM BOARD CLIPS O/S (SN)	NECESSARY	50.00	50.00
1	SET ROCKER PANEL GARNISH CLIPS O/S (SN)	NECESSARY	50.00	50.00
			950.00	150.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR .	NOT NECESSARY	80.00	-
	TO DISMANTLE & REFIX SEAT ,CUSHION ,UPHOLSTERY .		120.00	80.00
	TO TRANSFER BOTH DOOR MECHANISM .		120.00	120.00
	TO SPRAY RUST PROOFING .		150.00	90.00
	TO CONDUCT WHEEL ALIGNMENT .		150.00	60.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER O/S ,ROCKER PANEL O/S AND REAR SPORT RIM O/S .		2,000.00	800.00
	TO PUTTY & SPRAY PAINTING .		1,500.00	1,100.00
			4,170.00	2,270.00
GRAND TOTAL			21,597.00	10,845.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,600.00

Report Ref No. CC6/CT121001148/Ura3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJY 808L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJY 808L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJY 808L

RE-INSPECTION

