

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21001151/KVD3Q2

Date: 01/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SMP7601G

Insured Vehicle No : SKE203A

Date of Loss: 23/01/2021

Nature of Claim: TP

Claim No: 4581220469SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP7601G**

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A)

Engine No: LEB7105348

Reg. Date: 15/10/2019 (Man. Year: 2018)

Chassis No: GP72004141

Colour: Metallic Black

Odometer: 98701 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15

Rear Tyre Size:

185/60R15

Front Left Side: West Lake 9 mm

Rear Left Side:

West Lake 9 mm

Front Right Side: West Lake 9 mm

Rear Right Side:

West Lake 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,234.92	6,538.08	2,696.84	29.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,065.00	2,590.00	1,475.00	36.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,299.92	9,128.08	4,171.84	31.37
Approved Total (Overridden) (S\$)		7,300.00		
Nett Amount (S\$)	13,299.92	7,300.00	5,999.92	45.11

INSPECTION

Date of Assignment: 25/01/2021

Date Inspected: 25/01/2021 Inspected At:

Massive Trading & Auto - Amk (HQ)

Blk 225 #07-579 Ang Mo Kio Ave 1

Singapore 560225

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE ASSY	Bent	1,281.10 FL	*1,193.70 FL
2	1		*REAR TAIL-GATE GLASS MOULDING	Necessary	105.20 FL	*105.20 FL
3	1		*REAR TAIL-GATE EMBLEM SHUTTLE	Necessary	65.10 FL	*65.10 FL
4	1		*REAR TAIL-GATE EMBLEM HYBRID	Necessary	57.20 FL	*57.20 FL
5	1		*REAR TAIL-GATE EMBLEM H	Necessary	40.10 FL	*40.10 FL
6	1		*REAR TAIL-GATE OUTER CHROME GARNISH	Serviceable	385.70 FL	*- FL
7	1		*REAR TAIL-GATE INNER LOCK	Dented	305.10 FL	*201.80 FL
8	1		*REAR TAIL-GATE INNER TRIM BOARD	Buckled/Dented	287.40 FL	*287.40 FL
9	1		*REAR TAIL-GATE POCKET	Dented	45.10 FL	*45.10 FL
10	2		*REAR TAIL-GATE REFLECTOR	Dented/Mtg Cracked	840.20 FL	*770.20 FL
11	1		*REAR TAIL-LAMP	N/s Cut/O/s Serviceable	975.80 FL	*487.90 FL
12	1		*REAR BOOT RUBBER	Distorted/Dented	195.70 FL	*195.70 FL
13	1		*REAR END PANEL	Bent	588.60 FL	*546.70 FL
14	1		*REAR END PANEL INNER GARNISH	Distorted	185.90 FL	*185.90 FL
15	1		*REAR END PANEL LOWER COVER	Distorted	87.10 FL	*87.10 FL
16	1		*REAR BUMPER	Bent	965.70 FL	*965.70 FL
17	1		*REAR BUMPER TOW COVER	Dented	48.20 FL	*48.20 FL
18	2		*REAR BUMPER SIDE RETAINER	Serviceable	76.40 FL	*- FL
19	2		*REAR BUMPER REFLECTOR	Serviceable	310.40 FL	*- FL
20	2		*REAR BUMPER REFLECTOR GARNISH	Serviceable	213.40 FL	*- FL
21	2		*REAR BUMPER REFLECTOR SPONGE	Cracked	164.20 FL	*164.20 FL
22	1		*RADIO ANTENNA	Dented	125.60 FL	*125.60 FL
23	1		*REAR FENDER INNER TRIM BOARD	O/s Cracked	970.40 FL	*399.60 FL
24	1		*REAR SPARE TYRE PANEL	Bent/Buckled	1,072.50 FL	*1,072.50 FL
25	1		*REAR SPARE TOOL CONSOLE BOX	Cracked	205.60 FL	*205.60 FL
26	1		*REAR BOOT TOP COVER BOARD	Cracked	297.10 FL	*297.10 FL
27	1		*REAR EXHAUST SILENCER (LOCAL REPAIR)	Dented	684.08 FS	*220.00 FS
28	1		*REAR REVERSE SENSOR	Dented/Shorted	200.00 FS	*200.00 FS
29	1		*REAR REVERSE CAMERA	Serviceable	300.00 FS	*- FS
30	1		*REAR TAIL-GATE GLASS SEALANT	Necessary	55.00 FS	*40.00 FS
31	20		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
32	1		*REAR NO PLATE	Serviceable	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,213.88	8,047.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,978.96	1,509.52
Total Parts (\$\$)	9,234.92	6,538.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	1,600.00	1,200.00
2	TO PUTTY AND SPRAY PAINT	New	1,600.00	900.00
3	CHECK & RECONNECT WIRING	New	45.00	20.00
4	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	120.00	90.00
5	REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	100.00	100.00
6	REMOVE/REFIT REAR TAIL-GATE MECHANISM TO NEW DOOR	New	150.00	60.00
7	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	100.00	100.00
8	REMOVE/RENEW REAR EXHAUST SILENCER	New	120.00	60.00
9	REMOVE/REFIT FUEL TANK TO FACILITATE REPAIR	New	150.00	60.00
10	REMOVE/REFIT REAR O/S FENDER GLASS TO FACILITATE REPAIR	New	80.00	0.00
Gross Labour Cost (\$)			4,065.00	2,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >