

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001152/EVF3Q2

Date: 19/02/2021

REFERENCE

Insured/Claimant: ABDUL HALEEN BIN MOHAMED ALI
Date of Loss: 25/01/2021

Policy No: 2070007253

Nature of Claim: OD

Claim No: 2058255713SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCW748U**

Make & Model: MITSUBISHI OUTLANDER, 2.0 (A)

Engine No: 4J11BM9998

Reg. Date: 21/01/2020 (Man. Year: 2019)

Chassis No: GF7W0602178

Colour: Grey

Odometer: 18566 km

Engine Capacity: 1998 cc

Market Value/New Car Price: S\$106,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R18

Rear Tyre Size: 225/55R18

Front Left Side: Toyo 5 mm

Rear Left Side: Toyo 5 mm

Front Right Side: Toyo 5 mm

Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,676.00	2,015.03	2,660.97	56.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,445.00	2,345.00	1,100.00	31.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,121.00	4,360.03	3,760.97	46.31
+ GST 7.00/7.00% (S\$)	568.47	305.20	263.27	46.31
Nett Amount (S\$)	8,689.47	4,665.23	4,024.24	46.31

INSPECTION

Date of Assignment: 25/01/2021

Date Inspected: 25/01/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,RR BUMPER	Dented	807.00 F	*807.00 FL
2	1		*BRKT,R/BMPR FACE SIDE,RH	Not Necessary	12.00 F	*- FL
3	1		*BRKT,R/BMPR FACE SIDE,LH	Broken	12.00 F	*12.00 FL
4	1		*REINFORCEMENT,RR BUMPER,LH	Not Necessary	79.00 F	*- FL
5	1		*REINFORCEMENT,RR BUMPER,RH	Not Necessary	79.00 F	*- FL
6	1		*EXTENSION,RR BUMPER	Crushed	292.00 F	*292.00 FL
7	1		*PANEL ASSY,TAILGATE	Dented	984.00 F	*984.00 FL
8	1		*DAM,TAILGATE LWR	Necessary	41.00 F	*41.00 FL
9	2		*STOPPER,WINDSHIELD GLASS	Necessary	6.00 F	*6.00 FL
10	4		*FASTENER,WINDSHIELD	Necessary	24.00 F	*24.00 FL
11	2		*DAM,TAILGATE SIDE	Necessary	54.00 F	*54.00 FL
12	1		*DAM,TAILGATE,UPR	Necessary	13.00 F	*13.00 FL
13	1		*W/STRIP,TAILGATE OPENING	Not Necessary	213.00 F	*- FL
14	1		*LATCH,TAILGATE	Not Necessary	475.00 F	*- FL
15	1		*TRIM,RR END	Not Necessary	113.00 F	*- FL
16	1		*REFLECTOR,TAIL LAMP,LH	Cut	100.00 F	*100.00 FL
17	1		*LAMP ASSY,COMB,RR LH	Not Necessary	600.00 F	*- FL
18	1		*LAMP ASSY,TAIL,LH	Not Necessary	506.00 F	*- FL
19	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
20	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
21	1		*BUZZER, KEYLESS OPERATIO, RR (Supplementary)	Broken	91.00 F	*91.00 FL
22	10		*CLIPS (Supplementary)	Necessary	20.00 F	*20.00 FL
23	1		*MARK,OUTLANDER (Supplementary)	Necessary	95.00 F	*95.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,676.00	2,599.00
- List Item Discount on L Items 0.00/23.00% (\$\$)	0.00	583.97
Total Parts (\$\$)	4,676.00	2,015.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW TAILGATE,REAR BUMPER,REPAIR REAR END PANEL	New	1,350.00	900.00
2	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
3	REMOVE & INSTALL REAR WINDSCREEN	New	240.00	240.00
4	APPLY SEALANT FOR REAR WINDSCREEN	New	80.00	80.00
5	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
6	REMOVE & INSTALL TAILGATE TRIMS AND REAR COMPARTMENT TRIMS	New	300.00	-
7	SPRAY PAINT FOR REAR BUMPER,TAILGATE,REAR END PANEL.REAR AIRDAM	New	1,225.00	875.00
8	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (\$\$)			3,445.00	2,345.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >