



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 25.01.2021
Emailed : 17.02.2021, 10.20am
Date Survey : 25.01.2021

VEHICLE NO : SCW 748 U
MODEL : MIT OUTLANDER 2.0
WIP : 62243

Material	:	\$	1,955.03
Labour	:	\$	2,405.00
Sub-Total	:	\$	4,360.03
	:	\$	-
Less Excess	:	\$	-
Total	:	\$	4,360.03
GST 7%	:	\$	305.20
Grand Total	:	\$	4,665.23
Finalise By/Date	:	<u>LOI / 17/02/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 25/01/2021	Cust No/Name	KCV15310/ABDUL HALEEM BIN MOHAMED ALI
	Reg No/Reg Date	SCW748U / 21/01/2020
	Date In/Mileage	25/01/2021/ 18575
	Chassis/Package	GF7W0602178 /DC17P
	Engine No	4J11BM9998
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	17/02/2021/ 10:01	BLC	260 / AiTing	62243			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE TAILGATE, REAR BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 900.00
E PNT88000 REMOVE & INSTALL REAR PARKING SENSOR TO FACILITATE REPAIR								✓ 60.00
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST								✓ 240.00
M SUNDRY APPLY SEALANT ON REAR WINDSCREEN GLASS								✓ 80.00
M SUNDRY SUPPLY C&C LOGO								✓ 40.00
M SUNDRY APPLY SEALANT ON ACCIDENT PORITONS								✓ 40.00
E PNT98000 RESPRAY ON REAR BUMPER, TAILGATE, REAR AIR DAM, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 875.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUNDRIES								✓ 20.00
X	FACE,RR BUMPER				1.00	✓ 807.00	23.00	621.39
X	BRKT,R/BMPR FACE SIDE,LH				1.00	✓ 12.00	23.00	9.24
X	EXTENSION,RR BUMPER				1.00	✓ 292.00	23.00	224.84
X	PANEL ASSY,TAILGATE				1.00	✓ 984.00	23.00	757.68
X	DAM,TAILGATE,LWR				1.00	✓ 41.00	23.00	31.57
X	STOPPER,WINDSHIELD GLASS				2.00	✓ 3.00	23.00	4.62
X	FASTENER,WINDSHIELD				4.00	✓ 6.00	23.00	18.48
X	DAM,TAILGATE SIDE				2.00	✓ 27.00	23.00	41.58
X	DAM,TAILGATE,UPR				1.00	✓ 13.00	23.00	10.01
X	REFLECTOR,TAIL LAMP,LH				1.00	✓ 100.00	23.00	77.00

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 25/01/2021	Cust No/Name	KCV15310/ABDUL HALEEM BIN MOHAMED ALI
	Reg No/Reg Date	SCW748U / 21/01/2020
	Date In/Mileage	25/01/2021/ 18575
	Chassis/Package	GF7W0602178 /DC17P
	Engine No	4J11BM9998
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	17/02/2021/ 10:01	BLC	260 / AiTing	62243

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BUZZER,KEYLESS OPERATIO,RR	1.00	91.00	23.00	70.07
X CLIP,ENG ROOM COVER	10.00	2.00	23.00	15.40
X MARK,OUTLANDER	1.00	95.00	23.00	73.15
Z TEXT AI GOD CLAIM. DOA : 25.01.21 SURVEYOR STEVE LKK 25.01.21 POLICY NO : 2070007253				
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	1,955.03	Nett	4,360.03
Labour	2,225.00	7% GST on	305.20
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	4,665.23
Sundry/Others	180.00		
Total(w/o GST)	4,360.03		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys


INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SCW 748 U

<u>Materials</u>		<u>Cost (\$)</u>
1	Buzzer, keyless operatio, RR	91.00
2	Clips (x10)	20.00
3	Mark, Outlander	95.00
Total		206.00
Less 23% discount		47.38
Total after discount		158.62
7% GST		11.10
Grand total		<u>\$ 169.72</u>

Thank You.

Yours faithfully


LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

2021.02.01

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2019MY

SCS 11811
After work, please visit to Base all the time.
Done.

All DTCs

2021.02.01

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCs	
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs	
AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCs	
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs	
SRS-AIR BAG	ORC_81047302		No DTCs	
Air Conditioner	AC_80080011		No DTCs	
ETACS	ETACS_83040801		No DTCs	
Meter	MTR_84084001		No DTCs	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
AND	AND_8C080002		Non-equipped System or Communication Error	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN	ETACS_83040801		Non-target System	
Power Gate	ETG_92080000	U0184	AUDIO CAN timeout	Active

All DTCs

2021.02.01

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/Keyless	KOS_8A880020		No DTCs	
OSS	OSS_9588000B		No DTCs	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCs	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	