

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001153/T1GS3Q2
Date: 09/09/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SMK7273X

Date of Loss: 12/01/2021

Policy No:

Insured Vehicle No :

YP1520D

Nature of Claim:

TP

Claim No:

0725492215SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMK7273X**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A)

Reg. Date: 23/04/2019 (Man. Year: 2018)

Colour: Silver

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 3A92UHHJ0984

Chassis No: MMBSTA13AJH003958

Odometer: 84094 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 185/55 R15

Front Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Tyre Size:

185/55 R15

Rear Left Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,818.05	4,640.16	6,177.89	57.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,190.00	2,340.00	3,850.00	62.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,008.05	6,980.16	10,027.89	58.96
Approved Total (Overridden) (S\$)		5,600.00		

(S\$)	17,008.05	5,600.00	11,408.05	67.07
+ GST 7.00/7.00% (S\$)	1,190.56	392.00	798.56	67.07
Nett Amount (S\$)	18,198.61	5,992.00	12,206.61	67.07
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,599.45		

INSPECTION

Date of Assignment: 25/01/2021

Date Inspected: 25/01/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Teamwork Garage Pte Ltd (HQ)
 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
 Singapore 408934

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	814.20 FL	*708.00 FL
2	1		*REAR BUMPER LOWER GARNISH	Not Necessary	437.00 FL	*- FL
3	1		*REAR BUMPER BRACKET	N/S Deformed / O/S Not Necessary	201.80 FL	*100.90 FL
4	1		*REAR BUMPER RETAINER	N/S Deformed / O/S Not Necessary	69.00 FL	*34.50 FL
5	2		*REAR BUMPER REFLECTOR	Not Necessary	276.00 FL	*- FL
6	1		*END PANEL	Bent	807.30 FL	*402.00 FL
7	1		*END PANEL TOP GARNISH	Deformed	236.00 FL	*104.74 FL
8	1		*END PANEL KEYLESS SENSOR SPEAKER	Distorted	138.00 FL	*138.00 FL
9	1		*KEYLESS SENSOR	Cracked	172.50 FL	*172.50 FL
10	1		*TAILLAMP	N/S Cracked / O/S Not Necessary	862.00 FL	*245.00 FL
11	1		*TAILLAMP PANEL	N/S Bent / O/S Not Necessary	192.00 FL	*96.00 FL
12	1		*TAILLAMP SEALER	N/S Necessary/O/S Not Necessary	72.00 FL	*36.00 FL
13	1		*BOOTLID	Bent	952.20 FL	*828.00 FL
14	1		*BOOTLID LOCK	Bent	247.20 FL	*139.00 FL
15	1		*BOOTLID LOCK STRIKER	Not Necessary	24.00 FL	*- FL
16	1		*BOOTLID CHROME OUTER GARNISH	Cracked	365.70 FL	*266.00 FL
17	1		*BOOTLID WEATHERSTRIP	Twisted	170.20 FL	*170.20 FL
18	1		*BOOTLID EMBLEM -ATTRAGE	Necessary	25.30 FL	*25.30 FL
19	1		*BOOTLID EMBLEM -MIVEC	Necessary	39.50 FL	*39.50 FL
20	1		*BOOTLID -LOGO	Necessary	47.15 FL	*47.15 FL
21	2		*BOOTLID HINGE	Repair	441.60 FL	*- FL
22	1		*BOOTLID INNER TRIM	Not Necessary	172.50 FL	*- FL
23	1		*SPARE TYRE TOP BOARD	Deformed	212.75 FL	*182.30 FL
24	1		*FLOOR PANEL	Repair	1,410.20 FL	*- FL
25	1		*REAR FENDER	N/S Buckled / O/S Not Necessary	1,662.90 FL	*715.00 FL
26	1		*REAR FENDER INNER TRIM	Deformed	281.70 FL	*178.00 FL
27	2		*REAR FENDER AIR VENT	Not Necessary	187.40 FL	*- FL
28	1		*REAR WINDSCREEN MOULDING	Necessary	92.00 FL	*92.00 FL
29	1		*MUD FLAP	Not Necessary	96.00 FL	*- FL
30	1		*REAR AIRDUCT	Not Necessary	67.20 FL	*- FL
31	1		*REAR AIRDUCT COVER	Cracked	91.20 FL	*91.20 FL
32	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
33	2		*SET REAR FENDER INNER TRIM CLIP	Necessary	120.00 FS	*30.00 FS
34	1		*SET BOOTLID INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
35	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
37	1		*BOT BRAKE FUIID	Not Necessary	60.00 FS	*- FS
38	1		*SET REVERSE SENSOR	Not Working	500.00 FS	*200.00 FS
39	1		*REAR NUMBER PLATE GARNISH	Not Necessary	60.00 FS	*- FS
40	1		*END PANEL TOP GARNISH CLIP	Necessary	60.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,904.50	5,121.29
- List Item Discount on L Items 10.00/10.00% (S\$)	1,086.45	481.13
Total Parts (S\$)	10,818.05	4,640.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	120.00	30.00
2	REMOVE,REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	60.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	30.00
4	REMOVE AND REFIT FUEL TANK	New	300.00	0.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
6	TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	60.00
7	REMOVE AND RENEW FLOOR INSULATOR	New	120.00	0.00
8	PANEL BEATING ON AFFECTED AREAS	New	2,400.00	1,000.00
9	SPRAY PAINTING ON AFFECTED AREAS	New	2,400.00	1,000.00
10	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	40.00
Gross Labour Cost (S\$)			6,190.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >