

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG21001154/EVF3E2

**Date:** 10/02/2021

### REFERENCE

Insured/Claimant:	CHAU KING YIU	Policy No:	1800136636		
Date of Loss:	23/01/2021	Nature of Claim:	OD	Claim No:	5069714468SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU5908H		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11AA1549
Reg. Date:	16/11/2018 (Man. Year: 2018)	Chassis No:	GF7W0600112
Colour:	Blue	Odometer:	26042 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$91,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 4 mm	Rear Left Side:	Toyo 4 mm
Front Right Side:	Toyo 4 mm	Rear Right Side:	Toyo 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,717.74	2,619.52	2,098.22	44.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,430.00	3,960.00	2,470.00	38.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,147.74</b>	<b>6,579.52</b>	<b>4,568.22</b>	<b>40.98</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>780.34</b>	<b>460.57</b>	<b>319.77</b>	<b>40.98</b>
<b>Nett Amount (S\$)</b>	<b>11,928.08</b>	<b>7,040.09</b>	<b>4,887.99</b>	<b>40.98</b>

### INSPECTION

Date of Assignment:	25/01/2021		
Date Inspected:	25/01/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*LAMP ASSY, COMB, RR LH	Cut	600.00 FL	*600.00 FL
3	1		*REFLECTOR, TAIL LAMP, LH	Cut	100.00 FL	*100.00 FL
4	1		*LAMP ASSY, TAIL, LH	Not Necessary	506.00 FL	*- FL
5	1		*REINFORCEMENT, RR BUMPER, LH	Bent	79.00 FL	*79.00 FL
6	1		*REINFORCEMENT, RR BUMPER, RH	Not Necessary	79.00 FL	*- FL
7	1		*BRKT, R/BMPR FACE SIDE, LH	Broken	12.00 FL	*12.00 FL
8	1		*BRKT, R/BMPR FACE SIDE, RH	Not Necessary	12.00 FL	*- FL
9	1		*FACE, RR BUMPER	Dented	807.00 FL	*807.00 FL
10	1		*EXTENSION, RR BUMPER	Crushed	292.00 FL	*292.00 FL
11	1		*PANEL, RR END	Not Necessary	324.00 FL	*- FL
12	1		*DAM, TAILGATE, UPR	Necessary	13.00 FL	*13.00 FL
13	2		*FASTENER, WINDSHIELD	Necessary	12.00 FL	*12.00 FL
14	2		*DAM, TAILGATE SIDE	Necessary	54.00 FL	*54.00 FL
15	1		*GLASS, TAILGATE WINDOW	Not Necessary	654.00 FL	*- FL
16	1		*GARNISH, TAILGATE	Not Necessary	494.00 FL	*- FL
17	1		*PANEL ASSY, TAILGATE	Dented	984.00 FL	*984.00 FL
18	1		*W/STRIP, TAILGATE OPENING	Not Necessary	213.00 FL	*- FL
19	1		*W/STRIP, TAILGATE OPENING	Not Necessary	213.00 FL	*- FL
20	1		*MARK, OUTLANDER	Necessary	95.00 FL	*95.00 FL
21	1		*TRIM, RR END	Not Necessary	113.00 FL	*- FL
22	1		*EXTN, QTR PANEL, RR LWR LH	Not Necessary	78.00 FL	*- FL
23	1		*BUZZER, KEYLESS OPERATION,RR (Supplementary)	Broken	91.00 FL	*91.00 FL
24	1		*MOULDING,RR WHEEL ARCH,LH (Supplementary)	Necessary	160.00 FL	*160.00 FL
25	6		*CLIP,RR BUMPER (Supplementary)	Necessary	36.00 FL	*36.00 FL
26	1		*DAM,TAILGATE,LWR (Supplementary)	Necessary	41.00 FL	*41.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,112.00	3,396.00
- List Item Discount on L Items 23.00/23.00% (S\$)	1,394.26	776.48
Total Parts (S\$)	4,717.74	2,619.52

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE REAR BUMPER, TAILGATE, TAILLAMP PANEL, END PANEL & AFFECTED REAR. REPAIR ON REAR LH FENDER	New	2,250.00	900.00
2	PAINT WORK ON REAR BUMPER, TAILGATE, REAR LH TAILLAMP PANEL, END PANEL & REAR LH FENDER	New	1,750.00	1,050.00
3	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	120.00
4	TO SUPPLY REAR PARKING ASSIST	New	220.00	0.00
5	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	0.00
6	TO TRANSFER TAILGATE ATTACHMENT TO NEW PANEL	New	120.00	120.00
7	TO APPLY BODY SEALANT ON AFFECTED AREA	New	80.00	40.00
8	PERFORM RUST PREVENTION	New	40.00	0.00
9	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
10	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
11	REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR	New	240.00	240.00
12	TO APPLY WINDSCREEN SEALANT	New	80.00	80.00
13	TO APPLY ZERTONA COATING ON AFFECTED AREA	New	240.00	240.00
14	SUPPLY ONE SET OF REVERSE SENSOR (Supplementary)	New	220.00	220.00
15	REPAIR REAR END PANEL (Supplementary)	New	450.00	450.00
16	SPRAY PAINT REAR END PANEL (Supplementary)	New	350.00	350.00
<b>Gross Labour Cost (S\$)</b>			<b>6,430.00</b>	<b>3,960.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >