



CYCLE & CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



o Reg No : 1977014696

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV09706/CHAU KING YIU
	Reg No/Reg Date	SKU5908H / 16/11/201
	Date In/Mileage	25/01/2021/ 0
	Chassis No	GF7W0600112
	Engine No	4J11AA1549
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KAX00008	Credit	25/01/2021/ 11:22	QUK	282 / Kevin Leong	62244				
Description of Goods / Services						Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, TAILGATE, TAILLAMP PANEL, END PANEL & AFFECTED REAR REPAIR ON REAR LH FENDER						450 X 2			999 2250.00
E PNT98000 PAINT WORK ON REAR BUMPER, TAILGATE, REAR LH TAILLAMP PANEL, END PANEL & REAR LH FENDER						359 X 3			1059 1750.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST									120.00
M SUNDRY TO SUPPLY REAR PARKING ASSIST									220.00 X
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR									120.00 X
E PNT88000 TO TRANSFER TAILGATE ATTACHMENT TO NEW PANEL									120.00 X
M SUNDRY TO APPLY BODY SEALANT ON AFFECTED AREA									49 80.00
M SUNDRY PERFORM RUST PREVENTION									40.00 X
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM									30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST									120.00
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR									240.00
M SUNDRY TO APPLY WINDSCREEN SEALANT									80.00
M SUNDRY TO APPLY ZERTONA COATING ON AFFECTED AREA									240.00
M SUNDRY SUNDRIES									20 50.00
M LAMP ASSY, COMB, RR LH / CUT						1.00	600.00	23.00	462.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CLE & CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 1977014696

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV09706/CHAU KING YIU Reg No/Reg Date SKU5908H / 16/11/201 Date In/Mileage 25/01/2021/ 0 Chassis No GF7W0600112 Engine No 4J11AA1549 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	25/01/2021/ 11:22	QUK	282 / Kevin Leong	62244

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M REFLECTOR, TAIL LAMP, LH / CUT	1.00	100.00	23.00	77.00
M LAMP ASSY, TAIL, LH X NM	1.00	506.00	23.00	389.62
M REINFORCEMENT, RR BUMPER, LH ? X NM bent	1.00	79.00	23.00	60.83
M REINFORCEMENT, RR BUMPER, RH ? X NM	1.00	79.00	23.00	60.83
M BRKT, R/BMPR FACE SIDE, LH / OR	1.00	12.00	23.00	9.24
M BRKT, R/BMPR FACE SIDE, RH X NM	1.00	12.00	23.00	9.24
M FACE, RR BUMPER / OD	1.00	807.00	23.00	621.39
M EXTENSION, RR BUMPER / CR4	1.00	292.00	23.00	224.84
M PANEL, RR END ? X NM	1.00	324.00	23.00	249.48
M DAM, TAILGATE, UPR / RC	1.00	13.00	23.00	10.01
M FASTENER, WINDSHIELD / RC	2.00	6.00	23.00	9.24
M DAM, TAILGATE SIDE / RC	2.00	27.00	23.00	41.58
M GLASS, TAILGATE WINDOW X NM	1.00	654.00	23.00	503.58
M GARNISH, TAILGATE X NM	1.00	494.00	23.00	380.38
M PANEL ASSY, TAILGATE / OD	1.00	984.00	23.00	757.68
M W/STRIP, TAILGATE OPENING X NM	1.00	213.00	23.00	164.01
M W/STRIP, TAILGATE OPENING X NM	1.00	213.00	23.00	164.01
M MARK, OUTLANDER / RC	1.00	95.00	23.00	73.15
M TRIM, RR END ? X NM	1.00	113.00	23.00	87.01
M EXTN, QTR PANEL, RR LWR LH ? X NM	1.00	78.00	23.00	60.06

# Estimate

Steve (LKK)

25/1/21, 4.30pm

OO-NM AWL

EXCISE - ?

PIP

AS RM SN

75 days

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To resurvey damaged parts during resurvey

Confirm & accepted by

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Authorized signatory and company stamp

Nett	9,875.18
7% GST on	9875.18
Total Payable	10,566.44

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.