



CYCLE & CARRIAGE

AIG - OD (REVERT)
SURVEY: 25/01/21
LKK - STEVE

VEHICLE NO : SKU 5908 H

MODEL : MIT/OUTLANDER 2.0

WIP : 62244

Material	:	\$	<u>2,599.52</u>
Labour	:	\$	<u>3,980.00</u>
Sub-Total	:	\$	<u>6,579.52</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>6,579.52</u>
GST 7%	:	\$	<u>460.57</u>
Grand Total	:	\$	<u>7,040.09</u>
Finalise By/Date : <u>Larry ON 02/02/21</u>			



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 07 WORKING DAYS + 2 days (wk.end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 25/01/2021	Cust No/Name	KCV09706/CHAU KING YIU
	Reg No/Reg Date	SKU5908H / 16/11/2018
	Date In/Mileage	01/02/2021/ 26042
	Chassis/Package	GF7W0600112 /CS3P
	Engine No	4J11AA1549
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	02/02/2021/ 15:22	BLK	884 / Lauro Songcuan	62244

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, TAILGATE & AFFECTED AREAS				900.00 ✓
E PNT98000 SPRAY PAINT ON REAR BUMPER, TAILGATE AND REAR LH FENDER				1050.00 ✓
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST				120.00 ✓
E PNT88000 TRANSFER TAILGATE ATTACHMENT TO NEW PANEL				120.00 ✓
M SUNDRY APPLY BODY SEALANT ON AFFECTED AREAS				40.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				120.00 ✓
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR				240.00 ✓
M SUNDRY APPLY REAR WINDSCREEN SEALANT				80.00 ✓
M SUNDRY APPLY ZERTONA COATING ON AFFECTED AREAS				240.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY ONE SET OF REVERSE SENSOR (OUTLANDER)				220.00 X
E PNT88000 REPAIR REAR END PANEL				450.00 X
E PNT98000 SPRAY PAINT REAR END PANEL				350.00 X
X LAMP ASSY, COMB, RR LH X	1.00	600.00	23.00	462.00 ?
X REFLECTOR, TAIL LAMP, LH ✓	1.00	100.00	23.00	77.00 ✓
X REINFORCEMENT, RR BUMPER, LH ?	1.00	79.00	23.00	60.83 ?
X BRKT, R/BMPR FACE SIDE, LH ✓	1.00	12.00	23.00	9.24 ✓

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV09706/CHAU KING YIU Reg No/Reg Date SKU5908H / 16/11/2018 Date In/Mileage 01/02/2021/ 26042 Chassis/Package GF7W0600112 /CS3P Engine No 4J11AA1549 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK
25/01/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	02/02/2021/ 15:22	BLK	884 / Lauro Songcuan	62244

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X FACE,RR BUMPER ✓	1.00	807.00	23.00	621.39 ✓
X EXTENSION,RR BUMPER ✓	1.00	292.00	23.00	224.84 ✓
X DAM,TAILGATE,UPR ✓	1.00	13.00	23.00	10.01 ✓
X FASTENER,WINDSHIELD ✓	2.00	6.00	23.00	9.24 ✓
X DAM,TAILGATE SIDE ✓	2.00	27.00	23.00	41.58 ✓
X PANEL ASSY,TAILGATE ✓	1.00	984.00	23.00	757.68 ✓
X MARK,OUTLANDER ✓	1.00	95.00	23.00	73.15 ✓
X BUZZER,KEYLESS OPERATIO,RR	1.00	91.00	23.00	70.07 X
X MOULDING,RR WHEEL ARCH,LH	1.00	160.00	23.00	123.20 X
X CLIP,RR BUMPER	6.00	6.00	23.00	27.72 X
X DAM,TAILGATE,LWR	1.00	41.00	23.00	31.57 X
TEXT				
AIG OD CLAIM - REVERT				
DOA: 23/01/2021				
SURVEY: STEVE (LKK) 25/01/2021				
07 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	2,599.52		Nett	6,579.52
Labour	3,380.00			
Standard Menu	0.00	7% GST on	6579.52	460.57
Specialist Job	220.00			
Diagnostics Job	0.00		Total Payable	7,040.09
Sundry/Others	380.00			
Total(w/o GST)	6,579.52			

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SKU 5908 H

Materials

- | | |
|---|-------------------------------|
| 1 | Buzzer, Keyless Operation, RR |
| 2 | Moulding, RR Wheel Arch, LH |
| 3 | Clip, RR Bumper (6 pcs) |
| 4 | Dam, Tailgate, LWR |

Cost \$

91.00	✓ BR
160.00	✓ nec
36.00	✓ nec
41.00	✓ nec

328.00

23% Discount

75.44

252.56

Labour

- | | |
|---|----------------------------------|
| 1 | Supply One Set of Reverse Sensor |
| 2 | Repair Rear End Panel |
| 3 | Spray Paint Rear End panel |

220.00 ✓

450.00 ✓

350.00 ✓

1,020.00

Labour & Materials

1,272.56

7% GST

89.08

Total

1,361.64

Thank You.

Yours faithfully

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SKU 5908HWIP: 62244

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	REINFORCEMENT, RR BUMPER LH	? / SUPP	<i>[Signature]</i>	1 BT	Steve 26/1/21 6572A681
2	BUTTER, KEYLESS	? / SUPP	<i>[Signature]</i>	1 BR	
3	MOULDING RR WHEEL ARCH LH	? / SUPP	<i>[Signature]</i>	1 MC	
4	CLIP, CHAIRS (X 6)	? / SUPP	<i>[Signature]</i>	1 BR	
5	Reverse Sensor Set	? / SUPP	<i>[Signature]</i>	1	Steve 26/1/21 6572A681
6	Repair End Panel	? / SUPP	<i>[Signature]</i>	1	
7	Painting End Panel	? / SUPP	<i>[Signature]</i>	1	
8		? / SUPP			
9	Add 02 day - Total 07 day	? / SUPP		1	Steve 26/1/21 6572A681
10		? / SUPP	<i>[Signature]</i>		
11	CNC LOGO	? / SUPP	<i>[Signature]</i>		
12	DASH, TRIL GATE, L/R	? / SUPP			
13		? / SUPP			Steve 26/1/21 6572A681
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			Steve 26/1/21 6572A681
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	27/1/21	Steve
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Outlander 2.0SURVEYOR: Steve - LKL

All DTCS

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2019MY

SKU5908H

Before use MUT-3a VCI unit to check all the found

2021.02.01

All DTCs

2021.02.01

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
MPi/GDI/DIESEL	GAS_0E640000		No DTCs		
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs		
AT/CVT/A-MT/C-SST	CVT_14080300		No DTCs		
AUTO CRUISE	GAS_0E640000		Non-target System		
4WS/Electric Power Steering	EPS_45880040		No DTCs		
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs		
SRS-AIR BAG	ORC_81047302		No DTCs		
Air Conditioner	AC_80080011		No DTCs		
ETACS	ETACS_83040801		No DTCs		
Meter	MTR_84084001		No DTCs		
Steering Angle Sensor	GS_SAS_47000100		Non-target System		
AND	AND_8C080002		Non-equipped System or Communication Error		
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error		
LIN	ETACS_83040801		Non-target System		
Power Gate	ETG_92080000		Non-equipped System or Communication Error		

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/MMO/Keyless	KOS_8A880020	B240C	Tail gate antenna(outdoor) open	Stored
OSS	OSS_9588000B		No DTCS	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSEFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000	C2253	EPB SW malfunction	Stored
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	

All DTCS

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GFTW 2019MY

3KJ59084
 After use MUT-3x not to see all the sound

2021.02.01

All DTCs

2021.02.01

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
MPI/GDI/DIESEL	GAS_0E640000		No DTCs		
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs		
AT/CVT/A-MT/C-SST	CVT_14080300		No DTCs		
AUTO CRUISE	GAS_0E640000		Non-target System		
4WS/Electric Power Steering	EPS_45880040		No DTCs		
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs		
SRS-AIR BAG	ORC_81047302		No DTCs		
Air Conditioner	AC_80080011		No DTCs		
ETACS	ETACS_83040801		No DTCs		
Meter	MTR_84084001		No DTCs		
Steering Angle Sensor	GS_SAS_47000100		Non-target System		
AND	AND_8C080002		Non-equipped System or Communication Error		
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error		
LIN	ETACS_83040801		Non-target System		
Power Gate	ETG_92080000		Non-equipped System or Communication Error		

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/MMMO/Keyless	KOS_8A880020		No DTCs	
OSS	OSS_9588000B		No DTCs	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSCFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCs	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	