



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 8415U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DISTORTED	1,323.65	1,151.30
1	FRONT BUMPER RETAINER LH	BENT	45.20	45.20
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	665.85	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	132.40	-
1	FRONT BUMPER COVER LH	NOT NECESSARY	68.40	-
1	FRONT GRILLE	NOT NECESSARY	182.00	-
1	FRONT GRILLE EMBLEM	NOT NECESSARY	83.60	-
1	FRONT GRILLE CHROME MOULDING	CRACKED	184.40	184.40
1	FRONT HEADLAMP LH	SCRATCHED	1,207.45	963.50
1	FRONT FENDER LH	BADLY DENTED	559.60	383.70
1	FRONT FENDER INNER SHIELD LH	TORN	136.80	105.90
1	BONNET	NOT NECESSARY	1,453.60	-
2	BONNET HINGE	NOT NECESSARY	54.05	-
1	FRONT SHOCK ABSORBER LH	NOT NECESSARY	506.00	-
1	FRONT KNUCKLE ARM LH	NOT NECESSARY	477.25	-
1	FRONT KNUCKLE ARM BEARING LH	NOT NECESSARY	732.55	-
1	FRONT LOWER ARM LH	NOT NECESSARY	579.60	-
	LESS 20% DISCOUNT		-1,678.48	-566.80
			6,713.92	2,267.20
<u>SPECIAL NETT ITEMS</u>				
1	RIM (SCRATCHED)(SN)	NOT CONSISTENT WITH THE IMPACT	600.00	-
1	BOT BRAKE FLUID (SN)	NOT NECESSARY	60.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	30.00	30.00
			720.00	60.00
<u>LABOUR</u>				
	CHECK WIRING AND LIGHTNING SYSTEM.		60.00	20.00
	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-

Report Ref No. CS/SMO21001157/Uqd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS.	NOT NECESSARY	200.00	-
	PANEL BEATING ON AFFECTED AREAS.		1,200.00	300.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	450.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	30.00
			2,960.00	800.00
GRAND TOTAL			10,393.92	3,127.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CS/SMO21001157/Uqd3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.