

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001165/EVD3Q2**Date:** 09/03/2021REFERENCE

Insured/Claimant: LIN CHENGWEI, DAVID

Policy No:

Date of Loss: 24/01/2021

Nature of Claim: OD Claim No: 2943748533SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMK789X**

Make & Model: KIA CERATO, 1.6 (A)

Engine No: G4FGJH720099

Reg. Date: 08/05/2019 (Man. Year: 2018)

Chassis No: KNAF3416MK5040753

Colour: Red

Odometer: 28527 km

Engine Capacity: 1591 cc

Market Value/New Car Price: S\$73,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Kumho 5 mm

Rear Left Side: Kumho 5 mm

Front Right Side: Kumho 5 mm

Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,842.00	9,886.00	2,956.00	23.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,430.00	6,690.00	3,740.00	35.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,272.00	16,576.00	6,696.00	28.77
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	22,972.00	16,276.00	6,696.00	29.15
+ GST 7.00/7.00% (S\$)	1,608.04	1,139.32	468.72	29.15
Nett Amount (S\$)	24,580.04	17,415.32	7,164.72	29.15

INSPECTION

Date of Assignment: 25/01/2021

Date Inspected: 25/01/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COOLANT (4L)	Necessary	26.00 FL	*26.00 FL
2	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
3	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 FL	*- FL
4	1		*BLOWER ASSY	Broken	656.00 FL	*656.00 FL
5	1		*CAP ASSY-RADIATOR	Not Necessary	24.00 FL	*- FL
6	1		*RADIATOR ASSY	Bent	646.00 FL	*646.00 FL
7	1		*CONDENSER ASSY-COOLER	Bent	687.00 FL	*687.00 FL
8	1		*GUARD-AIR,LH	Broken	28.00 FL	*28.00 FL
9	1		*GUARD-AIR,LH	Broken	28.00 FL	*28.00 FL
10	1		*LAMP ASSY-HEAD,LH	Broken	1,219.00 FL	*1,219.00 FL
11	1		*LAMP ASSY-HEAD,RH	Broken	1,219.00 FL	*1,219.00 FL
12	1		*PAD-HOOD INSULATING	Crushed	156.00 FL	*156.00 FL
13	1		*ROD ASSY-HOOD STAY	Not Necessary	35.00 FL	*- FL
14	1		*LATCH ASSY-HOOD	Bent	103.00 FL	*103.00 FL
15	1		*PANEL ASSY-HOOD	Dented	1,502.00 FL	*1,502.00 FL
16	1		*HINGE ASSY-HOOD,RH	Bent	43.00 FL	*43.00 FL
17	1		*HINGE ASSY-HOOD,LH	Bent	43.00 FL	*43.00 FL
18	1		*INSULATOR-FENDER LH	Not Necessary	27.00 FL	*- FL
19	1		*PANEL-FENDER,LH	Dented	430.00 FL	*430.00 FL
20	1		*INSULATOR-FENDER RH	Not Necessary	27.00 FL	*- FL
21	1		*PANEL-FENDER,RH	Dented	430.00 FL	*430.00 FL
22	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
23	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
24	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
25	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 FL	*84.00 FL
26	1		*AIR DUCT-FR BUMPER,LH	Not Necessary	14.00 FL	*- FL
27	1		*AIR DUCT-FR BUMPER,RH	Not Necessary	14.00 FL	*- FL
28	1		*LAMP ASSY-SIDE REPEATER,LH	Not Necessary	143.00 FL	*- FL
29	1		*LAMP ASSY-SIDE REPEATER,RH	Not Necessary	143.00 FL	*- FL
30	1		*MOULDING-FRONT BUMPER,LH	Not Necessary	36.00 FL	*- FL
31	1		*MOULDING-FRONT BUMPER,RH	Not Necessary	36.00 FL	*- FL
32	1		*LAMP ASSY-FRONT FOG,LH	Not Necessary	303.00 FL	*- FL
33	1		*LAMP ASSY-FRONT FOG,LH	Repeated	303.00 FL	*- FL
34	1		*GARNISH-RADIATOR GRILLE	Broken	38.00 FL	*38.00 FL
35	6		*CLIP	Necessary	6.00 FL	*6.00 FL
36	1		*GRILLE ASSY-RADIATOR	Broken	328.00 FL	*328.00 FL
37	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
38	1		*GRILLE-FRONT BUMPER	Broken	262.00 FL	*262.00 FL
39	1		*CAP-FRONT HOOK	Cut	9.00 FL	*9.00 FL
40	1		*COVER-FR BUMPER FOG LAMP,LH	Not Necessary	15.00 FL	*- FL
41	1		*COVER-FR BUMPER FOG LAMP,RH	Not Necessary	15.00 FL	*- FL
42	1		*DUCT ASSY-AIR	Broken	55.00 FL	*55.00 FL
43	1		*SHIELD-AIR INTAKE	Not Necessary	9.00 FL	*- FL
44	1		*DUCT-EXTENSION	Missing	5.00 FL	*5.00 FL
45	2		*RETAINER-COWL TOP COVER MTG	Necessary	4.00 FL	*4.00 FL
46	1		*MANIFOLD ASSY-INTAKE	Not Necessary	906.00 FL	*- FL
47	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FL	*1,297.00 FL
48	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
49	1		*BRACKET ASSY-RR BPR SIDE UPR,L	Not Necessary	25.00 FL	*- FL
50	1		*BRACKET ASSY-RR BPR SIDE UPR,R	Not Necessary	31.00 FL	*- FL
51	1		*STAY-RR BUMPER,LH	Bent	65.00 FL	*65.00 FL
52	1		*STAY-RR BUMPER,RH	Bent	65.00 FL	*65.00 FL
53	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*BEAM-RR BUMPER	Broken	318.00 FL	*318.00 FL
55	1		*BRACKET-RR BEAM UPR MTG,LH	Not Necessary	9.00 FL	*- FL
56	1		*BRACKET-RR BEAM UPR MTG,RH	Not Necessary	9.00 FL	*- FL
57	1		*BRACKET-RR BEAM LWR,CTR	Not Necessary	6.00 FL	*- FL
58	2		*BRACKET-RR BEAM LWR MTG	Not Necessary	12.00 FL	*- FL
59	1		*EXTN WIRING ASSY-BWS	Not Necessary	207.00 FL	*- FL
60	1		*LAMP ASSY-SIDE T/SIGNAL,LH	Not Necessary	181.00 FL	*- FL
61	1		*LAMP ASSY-SIDE T/SIGNAL,RH	Not Necessary	181.00 FL	*- FL
62	1		*COVER-RR BUMPER FOG LAMP,LH	Not Necessary	19.00 FL	*- FL
63	1		*COVER-RR BUMPER FOG LAMP,RH	Not Necessary	19.00 FL	*- FL
64	4		*RETAINER	Necessary	8.00 FL	*8.00 FL
65	2		*GROMMET ASSY-SCREW	Necessary	4.00 FL	*4.00 FL
66	8		*CLIP	Necessary	8.00 FL	*8.00 FL
67	1		*COVER-RR BUMPER	Broken	651.00 FL	*651.00 FL
68	1		*COVER-RR BUMPER LWR	Broken	241.00 FL	*241.00 FL
69	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
70	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
71	1		*REAR PARKING SENSOR	Not Necessary	220.00 FL	*- FL
72	1		*CLEANER ASSY-AIR (Supplementary)	Broken	174.00 FL	*174.00 FL
73	6		*RETAINER (Supplementary)	Necessary	12.00 FL	*12.00 FL
74	1		*HORN ASSY-LOW PITCH (Supplementary)	Broken	74.00 FL	*74.00 FL
75	10		*CLIPS (Supplementary)	Necessary	10.00 FL	*10.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,030.00	12,340.00
- List Item Discount on L Items 20.00/20.00% (\$)	3,188.00	2,454.00
Total Parts (\$)	12,842.00	9,886.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL,FRONT BONNET,RH FRONT FENDER,LH FRONT FENDER,FRONT BUMPER FACE	New	2,000.00	1,600.00
2	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK	New	100.00	100.00
3	TOP UP A/CON GAS AND CHECK A/CON SYSTEM	New	80.00	80.00
4	PAINT WORK SPRAY FRONT BONNET,FRONT BUMPER,RH FRONT FENDER,LH FRONT FENDER,RH FRONT DOOR,LHF FRONT DOOR AND AFFECTED PORTION	New	3,360.00	1,920.00
5	RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID,REAR BUMPER FACE,REPAIR REAR END PANEL	New	1,200.00	800.00
6	REMOVE AND INSTAL PARKING ASSIST	New	60.00	60.00
7	REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK	New	120.00	0.00
8	PAINT WORK SPRAY REAR END PANEL,REAR BOOT LID,REAR BUMPER FACE AND AFFECTED PORTION	New	1,920.00	960.00
9	REMOVE AND INSTALL REAR SPOILER LIP AFTER REPAIR	New	80.00	60.00
10	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
11	RENEW MANIFOLD ASSY-INTAKE	New	400.00	0.00
12	SUPPLY FRONT NUMBER PLATE WITH FRAME	New	50.00	50.00
13	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
14	REPAIR REAR END PANEL (Supplementary)	New	400.00	400.00
15	REMOVE & INSTALL BOTH AIR DAM (Supplementary)	New	160.00	160.00
16	RESPRAY ON REAR END PANEL (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$)			10,430.00	6,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >