

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV09632/LIN CHENGWEI, DAVID Reg No/Reg Date SMK789X*KC17P/ 08/05/201 Date In/Mileage / 28527 Chassis No KNAF3416MK5040753 Engine No G4FGJH720099 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	25/01/2021/ 13:12	QUD	247 / DonBong	27973
Description of Goods / Services				Qty	Unit Price Disc% Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT ² SUPPORT PANEL, 490 X 4 FRONT ¹ BONNET, RH FRONT FENDER, LH FRONT FENDER, FRONT BUMPER FACE 1/2 1/2					1609 2000.00
E PNT88000 REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK					100.00
M SUNDRY TOP UP A/CON GAS AND CHECK A/CON SYSTEM					80.00
E PNT98000 PAINT WORK SPRAY FRONT ¹ BONNET, FRONT ¹ BUMPER, 4 X 480 (CR5 colour) RH ¹ FRONT FENDER, LH ¹ FRONT FENDER, RH FRONT DOOR, LHF FRONT DOOR AND AFFECTED PORTION					1920 3360.00
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON REAR ¹ BOOT LID, REAR ¹ BUMPER FACE, 490 X 2 REPAIR REAR END PANEL					800 1200.00
E PNT88000 REMOVE AND INSTAL PARKING ASSIST					60.00
E PNT88000 REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK					120.00
E PNT98000 PAINT WORK SPRAY REAR END PANEL, REAR ¹ BOOT LID, 480 X 2 (CR5 colour) REAR ¹ BUMPER FACE AND AFFECTED PORTION					960 1920.00
E PNT88000 REMOVE AND INSTALL REAR SPOILER LIP AFTER REPAIR					60 80.00
M SUNDRY SUPPLY REAR PARKING SENSOR					220.00
M SUNDRY SUPPLY C&C LOGO					40.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM					30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST					120.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV09632/LIN CHENGWEI, DAVID Reg No/Reg Date SMK789X*KC17P/ 08/05/201 Date In/Mileage / 28527 Chassis No KNAF3416MK5040753 Engine No G4FGJH720099 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/01/2021/ 13:12	QUD	247 / DonBong	27973			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
USING HI-SCAN PRO TEST								50.00
M SUNDRY								
SUPPLY FRONT NUMBER PLATE WITH FRAME 200								400.00
A 20000001								
RENEW MANIFOLD ASSY-INTAKE								50.00
M SUNDRY								
SUNDRIES								
M CARRIER ASSY-FRONT END MODULE BR					1.00	675.00	20.00	540.00
M BEAM COMPLETE-FR BUMPER ? X NAI					1.00	497.00	20.00	397.60
M BLOWER ASSY C. for core BR					1.00	656.00	20.00	524.80
M CAP ASSY-RADIATOR X NAI					1.00	24.00	20.00	19.20
M RADIATOR ASSY BT					1.00	646.00	20.00	516.80
M CONDENSER ASSY-COOLER BT					1.00	687.00	20.00	549.60
M GUARD-AIR, LH BR					1.00	28.00	20.00	22.40
M GUARD-AIR, LH BR					1.00	28.00	20.00	22.40
M COOLANT (4L) AC					1.00	26.00	23.00	20.02
M LAMP ASSY-HEAD, LH BR					1.00	1219.00	20.00	975.20
M LAMP ASSY-HEAD, RH BR					1.00	1219.00	20.00	975.20
M PAD-HOOD INSULATING CRU					1.00	156.00	20.00	124.80
M ROD ASSY-HOOD STAY X NAI					1.00	35.00	20.00	28.00
M LATCH ASSY-HOOD BT					1.00	103.00	20.00	82.40
M PANEL ASSY-HOOD DO					1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD, RH BT					1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD, LH BT					1.00	43.00	20.00	34.40
M INSULATOR-FENDER LH X NAI					1.00	27.00	20.00	21.60
M PANEL-FENDER, LH DO					1.00	430.00	20.00	344.00
M INSULATOR-FENDER RH X NAI					1.00	27.00	20.00	21.60
M PANEL-FENDER, RH DO					1.00	430.00	20.00	344.00
M BRACKET-FR BUMPER UPR SIDE MTG ? X NAI					1.00	22.00	20.00	17.60
M BRACKET-FR BUMPER UPR SIDE MTG ? X NAI					1.00	22.00	20.00	17.60
M STIFFNER-FR BPR LWR X NAI					1.00	114.00	20.00	91.20
M ABSORBER-FRONT BUMPER ENERGY BR					1.00	84.00	20.00	67.20
M AIR DUCT-FR BUMPER, LH ? X NAI					1.00	14.00	20.00	11.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel 65684555 Fax 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV09632/LIN CHENGWEI, DAVID Reg No/Reg Date SMK789X*KC17P/ 08/05/201 Date In/Mileage / 28527 Chassis No KNAF3416MK5040753 Engine No G4FGJH720099 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	25/01/2021/ 13:12	QUD	247 / DonBong	27973
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M AIR DUCT-FR BUMPER,RH ? X NAI		1.00	14.00	20.00	11.20
M LAMP ASSY-SIDE REPEATER,LH ? X NAI		1.00	143.00	20.00	114.40
M LAMP ASSY-SIDE REPEATER,RH X NAI		1.00	143.00	20.00	114.40
M MOULDING-FRONT BUMPER,LH ? X NN		1.00	36.00	20.00	28.80
M MOULDING-FRONT BUMPER,RH ? X NAI		1.00	36.00	20.00	28.80
M LAMP ASSY-FRONT FOG,LH ? X NAI		1.00	303.00	20.00	242.40
M LAMP ASSY-FRONT FOG,LH X Reported		1.00	303.00	20.00	242.40
M GARNISH-RADIATOR GRILLE — GR CTP conv		1.00	38.00	20.00	30.40
M CLIP — NPC		6.00	1.00	20.00	4.80
M GRILLE ASSY-RADIATOR — GR		1.00	328.00	20.00	262.40
M COVER-FR BUMPER — GR		1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER — GR		1.00	262.00	20.00	209.60
M CAP-FRONT HOOK — CUT ? X NAI		1.00	9.00	20.00	7.20
M COVER-FR BUMPER FOG LAMP,LH ? X NAI		1.00	15.00	20.00	12.00
M COVER-FR BUMPER FOG LAMP,RH X NAI		1.00	15.00	20.00	12.00
M DUCT ASSY-AIR — GR		1.00	55.00	20.00	44.00
M SHIELD-AIR INTAKE ? X NAI		1.00	9.00	20.00	7.20
M DUCT-EXTENSION ? — MIS		1.00	5.00	20.00	4.00
M RETAINER-COWL TOP COVER MTG — NPC		2.00	2.00	20.00	3.20
M MANIFOLD ASSY-INTAKE ? X NAI		1.00	906.00	20.00	724.80
M PANEL ASSY-TRUNK LID — DO		1.00	1297.00	20.00	1037.60
M EMBLEM-CERATO — NPC		1.00	28.00	20.00	22.40
M BRACKET ASSY-RR BPR SIDE UPR,L ? X NAI		1.00	25.00	20.00	20.00
M BRACKET-ASSY RR BPR SIDE UPR,R ? X NAI		1.00	31.00	20.00	24.80
M STAY-RR BUMPER LH ? — OT		1.00	65.00	20.00	52.00
M STAY-RR BUMPER RH ? — OT		1.00	65.00	20.00	52.00
M ANTENNA ASSY-SMARTKEY ? X NAI		1.00	46.00	20.00	36.80
M BEAM-RR BUMPER ? — GR		1.00	318.00	20.00	254.40
M BRACKET-RR BEAM UPR MTG,LH ? X NAI		1.00	9.00	20.00	7.20
M BRACKET-RR BEAM UPR MTG,RH ? X NAI		1.00	9.00	20.00	7.20
M BRACKET-RR BEAM LWR,CTR ? X NAI		1.00	6.00	20.00	4.80
M BRACKET-RR BEAM LWR MTG ? X NAI		2.00	6.00	20.00	9.60
M EXTN WIRING ASSY-BWS X NAI		1.00	207.00	20.00	165.60

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table border="1"> <tr> <td>Cust No/Name</td> <td>LCV09632/LIN CHENGWEI, DAVID</td> </tr> <tr> <td>Reg No/Reg Date</td> <td>SMK789X*KC17P/ 08/05/201</td> </tr> <tr> <td>Date In/Mileage</td> <td>/ 28527</td> </tr> <tr> <td>Chassis No</td> <td>KNAF3416MK5040753</td> </tr> <tr> <td>Engine No</td> <td>G4FGJH720099</td> </tr> <tr> <td>Make/Model</td> <td>KIA/CERATO 1.6 A EX G333</td> </tr> <tr> <td>Colour/Trim</td> <td>CR5 RUNWAY RED / WK SATURN BLACK</td> </tr> </table>	Cust No/Name	LCV09632/LIN CHENGWEI, DAVID	Reg No/Reg Date	SMK789X*KC17P/ 08/05/201	Date In/Mileage	/ 28527	Chassis No	KNAF3416MK5040753	Engine No	G4FGJH720099	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK
Cust No/Name	LCV09632/LIN CHENGWEI, DAVID														
Reg No/Reg Date	SMK789X*KC17P/ 08/05/201														
Date In/Mileage	/ 28527														
Chassis No	KNAF3416MK5040753														
Engine No	G4FGJH720099														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/01/2021/ 13:12	QUD	247 / DonBong	27973			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
					1.00	181.00	20.00	144.80
M	LAMP ASSY-SIDE T/SIGNAL,LH	?	X	NAI	1.00	181.00	20.00	144.80
M	LAMP ASSY-SIDE T/SIGNAL,RH	X		NAI	1.00	19.00	20.00	15.20
M	COVER-RR BUMPER FOG LAMP,LH	?	X	NAI	1.00	19.00	20.00	15.20
M	COVER-RR BUMPER FOG LAMP,RH	X		NAI	4.00	2.00	20.00	6.40
M	RETAINER	—	NAI		2.00	2.00	20.00	3.20
M	GROMMET ASSY-SCREW	—	NAI		8.00	1.00	20.00	6.40
M	CLIP	—	NAI		1.00	651.00	20.00	520.80
M	COVER-RR BUMPER	—	BR		1.00	241.00	20.00	192.80
M	COVER-RR BUMPER LWR	—	BR					

Estimate

SURVEYOR NAME: Steve (LKK) 25/1/21, 3.10pmSURVEYOR SIGNATURE: DD-NM ALDATE: EXPRS - ?REMARKS: P/P
Ry Bel sy
12 days

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before further spray painting

- Confirm & accepted by damaged part(s) during resurvey
- Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Nett	22,189.22
7% GST on	22189.22
Total Payable	23,742.47

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.