

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG21001167/EQF3E2

Date: 11/02/2021

REFERENCE

Insured/Claimant:	SRI RAM KJ	Policy No:	2000000191	Claim No:	6520158356SG
Date of Loss:	25/01/2021	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR5296G	Engine No:	G4FGKH753055
Make & Model:	KIA CERATO, 1.6 EX (M)	Chassis No:	KNAF3416ML5065293
Reg. Date:	13/01/2020 (Man. Year: 2019)	Odometer:	9754 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$79,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,630.00	1,580.00	1,050.00	39.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	1,290.00	200.00	13.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,120.00	2,870.00	1,250.00	30.34
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	3,520.00	2,270.00	1,250.00	35.51
+ GST 7.00/7.00% (S\$)	246.40	158.90	87.50	35.51
Nett Amount (S\$)	3,766.40	2,428.90	1,337.50	35.51

INSPECTION

Date of Assignment:	25/01/2021	
Date Inspected:	25/01/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY-FRONT DOOR,RH	Dented	1,277.00 F	*1,277.00 FL
2	1		*HINGE ASSY-FRONT DOOR,RH	Not Necessary	30.00 F	*- FL
3	1		*HINGE ASSY-DOOR LOWER,RH	Not Necessary	27.00 F	*- FL
4	1		*BLACK TAPE-FR DR RR,RH	Necessary	13.00 F	*13.00 FL
5	1		*MIRROR ASSY-OUTSIDE RR VIEW,RH	Cut	559.00 F	*559.00 FL
6	1		*MOTOR ASSY-FRONT POWER WDW,RH	Not Necessary	362.00 F	*- FL
7	1		*PANEL ASSY-FRONT DR MODULE,RH	Not Necessary	241.00 F	*- FL
8	1		*MOULDING ASSY-FRT DR FRAME,RH	Necessary	37.00 F	*37.00 FL
9	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
10	1		*W/STRIP ASSY-FR DR BELT O/S RH	Cut	64.00 F	*64.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,630.00	1,970.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	390.00
Total Parts (\$)	2,630.00	1,580.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT DOOR RH,WIND MIRROR RH	New	400.00	400.00
2	REMOVE & INSTALL FRT DOOR TRIMS AND GLASS	New	180.00	120.00
3	SPRAY PAINT FOR FRT DOOR RH,WIND MIRROR RH	New	720.00	580.00
4	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (\$\$)			1,490.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >