

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INS	PECTION REPOR	Г	
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21001169/Qqf3e2	
	8 SHENTON WAY TOWERSINGAPO		Date	01/02/2021	
	ATTN : YU DOMIN	IC YISHAN	Code	: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 7474J	Veh. Inspected	FBR 8547T	
	Policy No.	VFX/P2419140	Coverage (\$)	0.00	
	Claim No.	S1M03198	Excess (\$)	0.00	
	Assign From	YU DOMINIC YISHAN	Assign Date	25/01/2021	
2.	. Vehicle Particulars & Condition				
	Make & Model	YAMAHA AEROX 155A	c.c	155	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	MLESG584111051441	Colour	MULTI COLOUR	
	Odometer	5207 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	80/90 R17	PIRELLI	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	80/90 R17	PIRELLI	5 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSBODY.	STAINED DAMAGES AT THE REAR PORTION AND O/S			
5.	General Information				
	Accident Date	13/01/2021	Inspect Date / Time	25/01/2021 (03:47 PM)	
	Survey held at	61 WOODLAND INDUSTRIAL F	PARK E9 # 01-14 E9		
	Repairer	GP MOTORING PTE LTD			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000				
5b.	b. Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			

Report Ref No. CS3/ASM21001169/Qqf3e2

Inspected By

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser