

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO21001172/Kvd3e2	
	50 RAFFLES PLAC TOWER SINGAPO		Date:	03/02/2021		
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YN 3498H	Veh. Inspected	t	GBJ 6759D	
	Policy No.	D20MTPCVE002902	Coverage (\$)		0.00	
	Claim No.	CMTD2100252/AGC	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		25/01/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA DYNA (M)	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	KDY2318038738	Colour		SILVER	
	Odometer	7151 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15X8	BRIDGESTONE		9 mm	
	L/H Front Tyre	195 R15X8	BRIDGESTONE		9 mm	
	R/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE		9/9 mm	
	L/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE		9/9 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
5.	General Information					
	Accident Date	18/01/2021	Inspect Date /	Time	26/01/2021 (11:59 AM)	
	Survey held at	Survey held at TEAM AUTOPRO PTE LTD				
	160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b.	•	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		5 Work	ing Days	

Report Ref No. CS3/SMO21001172/Kvd3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser