

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001173/BVF3E2

Date: 19/04/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00097112002
Claimant Vehicle No : SLU20P Insured Vehicle No : GBH8412B
Date of Loss: 22/01/2021 Nature of Claim: TP Claim No: SNM21D200411/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU20P**
Make & Model: BMW M235I, 3.0 COUPE ABS D/AB 2WD DSC HID NAV (A) Engine No: 06068824N55B30A
Reg. Date: 28/04/2014 (Man. Year: 2014) Chassis No: WBA1J72050V228275
Colour: White Odometer: 69214 km
Engine Capacity: 2979 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35 R19 Rear Tyre Size: 235/35 R19
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,585.54	7,377.25	13,208.29	64.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,600.00	1,220.00	3,380.00	73.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,185.54	8,597.25	16,588.29	65.86
Approved Total (Overridden) (S\$)		6,850.00		
(S\$)	25,185.54	6,850.00	18,335.54	72.80
+ GST 7.00/7.00% (S\$)	1,762.99	479.50	1,283.49	72.80
Nett Amount (S\$)	26,948.53	7,329.50	19,619.03	72.80

INSPECTION

Date of Assignment: 26/03/2021
Date Inspected: 27/01/2021 Inspected At: Team Autopro Pte Ltd (Sin Ming)
160 SIN MING DR
#01-14 SIN MING AUTO CITY
SINGAPORE 575722
Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Apr 2021)

Parts: M1-COUPE BMW M235I 3.0 COUPE ABS D/AB 2WD DSC HID NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLU20P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,147.35 FL	*- FL
2	1		*BOOT LID LOGO	Necessary	71.50 FL	*71.50 FL
3	1		*BOOTLID EMBLEM M	Necessary	81.75 FL	*81.75 FL
4	1		*BOOTLID EMBLEM 235I	Necessary	82.75 FL	*82.75 FL
5	1		*BOOTLID INNER TRIM BOARD	Not Damaged	156.10 FL	*- FL
6	1		*BOOTLID LOCK MECHANISM	Not Damaged	186.40 FL	*- FL
7	1		*BOOTLID WEATHERSTRIP	Not Damaged	126.80 FL	*- FL
8	1		*REAR BUMPER	Dented	1,029.75 FL	*1,029.75 FL
9	1		*REAR BUMPER DIFFUSER (CARBON FIBRE)	Not Necessary	1,332.60 FL	*- FL
10	2		*REAR BUMPER SIDE RETAINER	Necessary	112.20 FL	*112.20 FL
11	1		*REAR BUMPER INNER SPONGE	No such part	61.65 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	418.60 FL	*418.60 FL
13	2		*REAR BUMPER REINFORCEMENT BRACKET	No such part	240.00 FL	*- FL
14	2		*REAR BUMPER BRACKET	No such part	123.31 FL	*- FL
15	1		*REAR BUMPER REFLECTOR	N/S Broken	97.00 FL	*37.30 FL
16	1		*REAR BUMPER TOW CAP	Not Damaged	39.95 FL	*- FL
17	1		*REAR BUMPER CENTRE BEAM	Broken	383.00 FL	*383.00 FL
18	1		*REAR BUMPER UNDER COVER	No such part	50.45 FL	*- FL
19	1		*REAR BUMPER REVERSE SENSOR (4PCS)	Short Circuit (3Pcs Only)	957.00 FL	*717.75 FL
20	1		*REAR END PANEL	Not Damaged	507.45 FL	*- FL
21	1		*REAR END PANEL TOP GARNISH	Not Damaged	117.45 FL	*- FL
22	2		*TAILLAMP	Not Damaged	811.70 FL	*- FL
23	2		*TAILLAMP GARNISH	Not Damaged	89.90 FL	*- FL
24	1		*REAR EXHAUST	Not Damaged	1,451.35 FL	*- FL
25	2		*REAR EXHAUST MOUNTING	Not Damaged	62.90 FL	*- FL
26	1		*REAR AIR VENT	Not Damaged	32.15 FL	*- FL
27	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
28	1		*BOOTLID SEALANT	Not Necessary	100.00 FS	*- FS
29	1		*BOOTLID SPOILER (CARBON FIBRE)	Cut	1,800.00 FS	*1,078.13 FS
30	1		*BOOTLID SPOILER M PERFORMANCE (CARBON FIBRE)	Cut	5,900.00 FS	*1,000.00 FS
31	1		*BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
32	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
33	1		*REAR BUMPER DIFFUSER (CARBON FIBRE)	Dented	2,400.00 FS	*2,271.25 FS
34	1		*REAR BUMPER DIFFUSER CLIPS	Necessary	60.00 FS	*30.00 FS
35	1		*REAR BUMPER UNDER COVER CLIPS	Not Necessary	60.00 FS	*- FS
36	1		*REAR BUMPER REVERSE SENSOR SEAL (4PCS)	Necessary (3Pcs Only)	240.00 FS	*180.00 FS
37	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
38	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
39	2		*TAILLAMP CLIPS	Not Necessary	120.00 FS	*- FS
40	2		*TAILLAMP SEAL	Not Necessary	200.00 FS	*- FS
41	1		*REAR EXHAUST HEAD SHIELD	Not Damaged	66.35 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 21,077.41 7,523.98

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 5.00/5.00% (S\$)					491.87	146.73
Total Parts (S\$)					20,585.54	7,377.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BOOTLID COMPONENT	New	150.00	0.00
2	R&R REVERSE SENSOR	New	150.00	60.00
3	CHECK WIRING	New	120.00	40.00
4	DIAGNOSTIC RESET FAULT CODE	New	300.00	120.00
5	CONDUCT WATER LEAK TEST	New	180.00	0.00
6	UPHOLSTERY	New	300.00	0.00
7	PANEL BEAT	New	1,600.00	600.00
8	RUST PROOFING	New	200.00	0.00
9	SPRAY PAINT	New	1,600.00	400.00
Gross Labour Cost (S\$)			4,600.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >