

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001183/EQD3Q2
Date: 19/03/2021

REFERENCE

Insured/Claimant: CHEW YONG HAN MELVIN Policy No: 1900242618
Date of Loss: 25/01/2021 Nature of Claim: OD Claim No: 8055343012SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ3505Y**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGKH748635
Reg. Date: 12/11/2019 (Man. Year: 2019) Chassis No: KNAF3416MK5052160
Colour: Black Odometer: 19166 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$77,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18
Front Left Side: Cinturato 5 mm Rear Left Side: Cinturato 5 mm
Front Right Side: Cinturato 5 mm Rear Right Side: Cinturato 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,283.20	4,904.00	2,379.20	32.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,685.00	5,125.00	560.00	9.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,968.20	10,029.00	2,939.20	22.66
+ GST 7.00/7.00% (S\$)	907.77	702.03	205.74	22.66
Nett Amount (S\$)	13,875.97	10,731.03	3,144.94	22.66

INSPECTION

Date of Assignment: 25/01/2021
Date Inspected: 25/01/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 11.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-REAR COMB INSIDE,LH	Cut	608.00 FL	*608.00 FL
2	1		*LAMP ASSY-REAR COMB OUTSIDE,LH	Cut	675.00 FL	*675.00 FL
3	1		*LAMP ASSY-CENTER GARNISH	Not Necessary	690.00 FL	*- FL
4	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FL	*1,297.00 FL
5	1		*HINGE ASSY-TRUNK LID,LH	Not Necessary	97.00 FL	*- FL
6	1		*HINGE ASSY-TRUNK LID,RH	Not Necessary	97.00 FL	*- FL
7	1		*PANEL ASSY-BACK	Dented	324.00 FL	*324.00 FL
8	1		*PANEL ASSY-QUARTER OUTER,LH	Dented	1,349.00 FL	*1,349.00 FL
9	1		*PANEL ASSY-RR COMB LAMP HSG,LH	Dented	139.00 FL	*139.00 FL
10	1		*TRIM ASSY-RR TRANSVERSE	Not Necessary	41.00 FL	*- FL
11	1		*GLASS ASSY-REAR WINDOW	Not Necessary	447.00 FL	*- FL
12	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
13	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
14	1		*COVER-RR BUMPER	Dented	651.00 FL	*651.00 FL
15	1		*COVER-RR BUMPER LWR 5 Pcs	Broken (1 Pc only)	1,205.00 FL	*241.00 FL
16	1		*COVER-RR BUMPER UNDER,LH	Not Necessary	33.00 FL	*- FL
17	1		*COVER-RR BUMPER FOG LAMP,LH	Cut	19.00 FL	*19.00 FL
18	1		*LAMP ASSY-SIDE T-SIGNAL,LH	Broken	181.00 FL	*181.00 FL
19	1		*BRACKET-RR BEAM UPR MTG,LH	Not Necessary	9.00 FL	*- FL
20	1		*BRACKET-RR BEAM UPR MTG,RH	Not Necessary	9.00 FL	*- FL
21	1		*BRACKET-RR BEAM LWR,CTR	Not Necessary	6.00 FL	*- FL
22	1		*BRACKET-RR BEAM LWR MTG	Not Necessary	6.00 FL	*- FL
23	1		*BEAM-RR BUMPER	Not Necessary	318.00 FL	*- FL
24	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 FL	*- FL
25	1		*STAY-RR BUMPER,LH	Not Necessary	65.00 FL	*- FL
26	1		*STAY-RR BUMPER,RH	Not Necessary	65.00 FL	*- FL
27	1		*BRACKET ASSY-RR BPR SIDE UPR,L	Broken	25.00 FL	*25.00 FL
28	1		*BRACKET ASSY-RR BPR SIDE UPR,R	Not Necessary	31.00 FL	*- FL
29	1		*FILM-ANTI CHIPPG LH	Necessary	27.00 FL	*27.00 FL
30	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
31	1		*C&C EMBLEM	Necessary	50.00 FS	*40.00 FS
32	1		*EXTN WIRING ASSY-BWS	Broken	207.00 FL	*207.00 FL
33	1		*GLASS & MOULDING ASSY-QUARTER	Necessary	252.00 FL	*252.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,079.00	6,115.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,795.80	1,211.00
Total Parts (\$)	7,283.20	4,904.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER,BOOT,REAR LH FENDER & AFFECTED AREA	New	2,000.00	1,600.00
2	PAINT WORK ON REAR BUMPER,REAR LH FENDER & BOOT	New	1,050.00	1,050.00
3	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	120.00
4	REMOVE & INSTALL BOOT COMPARTMENT FOR FACILITATE	New	120.00	0.00
5	REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR	New	120.00	120.00
6	REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR	New	400.00	400.00
7	REMOVE & INSTALL REAR WINDSCREEN GLASS	New	240.00	240.00
8	TO APPLY WINDSCREEN SEALANT	New	80.00	80.00
9	TO APPLY BODY SEALANT ON AFFECTED AREA	New	80.00	40.00
10	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
11	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
12	RENEW REAR END PANEL & LH TAIL LAMP HOUSING	New	800.00	800.00
13	SPRAY PAINT REAR END PANEL & TAIL LAMP HOUSING	New	525.00	525.00
Gross Labour Cost (\$\$)			5,685.00	5,125.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >