

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CC4/ASM21001191/Aps3q2	
	8 SHENTON WAY AXA TOWERSING		Date	: 08/03/2022	
	ATTN:LYNN KHON	IG	Code	e: ASM	
1.	I. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKU 1918E	Veh. Inspected	XE 3490M	
	Policy No.	P2414915	Coverage (\$)	0.00	
	Claim No.	S1M030Z5	Excess (\$)	0.00	
	Assign From		Assign Date	25/01/2021	
2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI FUSO	c.c	11967	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	FV51SJA20266	Colour	WHITE	
	Odometer	122456 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	295/80 R22.5	WOSEN	8 mm	
	L/H Front Tyre	295/80 R22.5	WOSEN	8 mm	
	R/H Rear Tyre	295/80 R22.5	YINBAO	8 mm	
	L/H Rear Tyre	295/80 R22.5	YINBAO	8 mm	
4.	. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	19/01/2021	Inspection Date	26/01/2021	
	Survey held at	1ST AUTO PRO PTE LTD			
		51 UBI AVENUE 1 #05-02 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
<u> </u>					