

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001193/KPS3Q2
Date: 17/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100271217
Claimant Vehicle No :	GBH3150P	Insured Vehicle No :	GBC2024D
Date of Loss:	20/01/2021	Nature of Claim:	TP
		Claim No:	3233971215SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH3150P		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KD2789059
Reg. Date:	17/04/2018 (Man. Year: 2018)	Chassis No:	JTFAT35Y80K209977
Colour:	Silver	Odometer:	45718 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Yokohama 7/7 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Yokohama 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,359.72	220.87	1,138.85	83.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	460.00	340.00	42.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,159.72	680.87	1,478.85	68.47
Approved Total (Overridden) (S\$)		550.00		

(S\$)	2,159.72	550.00	1,609.72	74.53
+ GST 7.00/7.00% (S\$)	151.18	38.50	112.68	74.53
Nett Amount (S\$)	2,310.90	588.50	1,722.40	74.53
+ Loss of Use (2.0 x S\$90.00/day) (S\$)		180.00		
Nett Liability (S\$)		768.50		
Global Sum Settlement (S\$)		750.00		

INSPECTION

Date of Assignment: 25/01/2021

Date Inspected: 30/03/2021

Inspected At:

City Auto Pte Ltd (Sin Ming) (HQ)
 Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est
 Singapore 575643

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE HINGE LH	Repair	168.70 FL	*- FL
2	1		*REAR END CORNER SUPPORT BRACKET LH	Bent	115.90 FL	*115.90 FL
3	1		*REAR END GATE SUPPORT BRACKET LH	Bent	98.60 FL	*98.60 FL
4	1		*LH TAILLAMP	Serviceable	767.20 FL	*- FL
5	1		*LH TAILLAMP PANEL	Repair	51.50 FL	*- FL
6	1		*STOPPER	Serviceable	24.40 FL	*- FL
7	1		*COMPANY STICKER	Necessary	180.00 FS	*50.00 FS
8	1		*STICKER -70KM/H	Necessary	10.00 FS	*10.00 FS
9	1		*REVERSE SENSOR	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,666.30	274.50
- List Item Discount on L Items 25.00/25.00% (\$)	306.58	53.63
Total Parts (\$)	1,359.72	220.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	300.00	180.00
2	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	500.00	280.00
Gross Labour Cost (\$\$)			800.00	460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >