



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2202909

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 19/05/2022  
Reference CC3/CTI21001194/Kpa3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 777B  
Insured Veh. SGW 4542Y  
Claim No. SNM21D200519/C02  
Policy No. DMPCSNW00009832100  
Accident Date 20/01/2021  
Inspection Date 22/01/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21001194/Kpa3q2 Date: 19/05/2022 Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SGW 4542Y	<b>Veh. Inspected</b>	SHD 777B
	<b>Policy No.</b>	DMPCSNW00009832100	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	SNM21D200519/C02	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>		<b>Assign Date</b>	22/01/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	RENAULT LATITUDE (A)	<b>c.c</b>	1995
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
	<b>Chassis No.</b>	VF1ABL15AUC283310	<b>Colour</b>	METALLIC WHITE/RED
	<b>Odometer</b>	463396 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	215/60 R16	SAILUN	9 mm
	<b>L/H Front Tyre</b>	215/60 R16	SAILUN	9 mm
	<b>R/H Rear Tyre</b>	215/60 R16	SAILUN	9 mm
	<b>L/H Rear Tyre</b>	215/60 R16	SAILUN	9 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	20/01/2021	<b>Inspection Date</b>	22/01/2021
	<b>Survey held at</b>	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>7 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 777B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	DOOR PANEL FRT RH	BENT	2,844.66	2,844.66
1	DOOR WEATHERSTRIP FRT RH	SERVICEABLE	410.27	-
1	DOOR HANDLE OUTER FRT RH	SERVICEABLE	477.76	-
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH	DISTORTED	505.19	505.19
1	DOOR REGULATOR MOTOR FRT RH	JAMMED	796.46	796.46
1	DOOR HINGE UPPER FRT RH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER FRT RH	TO REPAIR SEE LABOUR	300.55	-
1	CENTRE PILLAR OUTER	BENT	880.14	880.14
1	CENTRE PILLAR INNER	TO REPAIR SEE LABOUR	907.76	-
1	DOOR PANEL REAR RH	BENT	2,844.66	2,844.66
1	DOOR REGULATOR REAR RH	SERVICEABLE	450.60	-
1	DOOR REGULATOR MOTOR REAR RH	SERVICEABLE	758.10	-
1	DOOR HINGE UPPER REAR RH	SERVICEABLE	241.60	-
1	DOOR HINGE LOWER REAR RH	BENT	169.90	169.90
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	437.10	-
1	ROCKER PANEL OUTER RH	BENT	1,184.99	1,184.99
1	DOOR HARNESS WIRE FRT RH (ADDITIONAL)	SERVICEABLE	2,670.00	-
1	SET DOOR HARNESS WIRE REAR RH (ADDITIONAL)	CRACKED	2,670.00	2,670.00
	LESS 10% DISCOUNT		-2,042.80	-1,189.60
			18,385.22	10,706.40
1	DOOR WEATHERSTRIP REAR RH (SN) (50%)	CUT	311.60	155.80
	LESS 10% DISCOUNT		-31.16	-
			280.44	155.80

Report Ref No. CC3/CTI21001194/Kpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	DOOR TRIM CLIP (SN)	NOT NECESSARY	70.00	-
1	DOOR SEAL CLIP (SN)	NOT NECESSARY	65.00	-
1	DOOR MOULDING CLIP (SN)	NOT NECESSARY	70.00	-
1	DOOR STICKER TRANSCAB (SN)	NECESSARY	100.00	60.00
1	DOOR STICKER 65553333 (SN)	NECESSARY	100.00	60.00
1	DOOR STICKER CLASSIC (SN)	NECESSARY	100.00	15.00
			505.00	135.00
	<b><u>LABOUR</u></b>			
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		230.00	120.00
	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	120.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		1,400.00	1,100.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR HINGE UPPER FRT RH,DOOR HINGE LOWER FRT RH,CENTRE PILLAR INNER AND FENDER PANEL FRT RH .		2,000.00	1,000.00
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			4,360.00	2,360.00
<b>GRAND TOTAL</b>			<b>23,530.66</b>	<b>13,357.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>10,700.00</b>

Report Ref No. CC3/CTI21001194/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 777B

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 777B

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHD 777B

### RE-INSPECTION

