

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21001196/AGA3Q2**Date:** 15/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800155357
Claimant Vehicle No :	SLE8663R	Insured Vehicle No :	SJC5088E
Date of Loss:	21/01/2021	Nature of Claim:	TP
		Claim No:	7371122954SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE8663R	Engine No:	HIDDEN
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU1118041
Reg. Date:	01/08/2016 (Man. Year: 2016)	Odometer:	236658 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,983.30	5,230.48	6,752.82	56.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,010.00	1,990.00	1,020.00	33.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,993.30	7,220.48	7,772.82	51.84
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	14,993.30	5,700.00	9,293.30	61.98
+ GST 7.00/7.00% (S\$)	1,049.53	399.00	650.53	61.98
Nett Amount (S\$)	16,042.83	6,099.00	9,943.83	61.98
+ Loss of Use (8.0 x S\$50.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,506.45		
Global Sum Settlement (S\$)		6,500.00		

INSPECTION

Date of Assignment:	22/01/2021	Green Forest Automobile Pte Ltd (Kaki Bukit)
Date Inspected:	22/01/2021 Inspected At:	8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	1,020.00 F	*1,020.00 FL
2	2		*REAR BOOT LID HINGES	Not Necessary	310.40 F	*- FL
3	1		*REAR BOOT LID EMBLE LOGO	Not Necessary	55.00 F	*- FL
4	1		*REAR BOOT LID VEZEL LOGO	Necessary	38.10 F	*38.10 FL
5	2		*REAR BOOT LID SIDE REFLECTOR	N/S Cut / O/S Cracked	776.40 F	*776.40 FL
6	1		*REAR BOOT LID INNER RUBBER	Cut	237.00 F	*237.00 FL
7	1		*REAR BOOT LID INNER LOCK	Jammed	284.20 F	*284.20 FL
8	1		*REAR BOOT LID NUMBER PLATE	Dented	50.00 F	*50.00 FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	122.20 F	*- FL
10	1		*REAR BOOT LID CENTER MOULDING	Not Necessary	320.80 F	*- FL
11	10		*REAR BOOT LID INNER TRIM BOARD CLIPS	Necessary	50.00 F	*30.00 FL
12	1		*REAR BOOT LID INNER TRIM BOARD	Deformed	421.20 F	*295.00 FL
13	1		*REAR WINDSCREEN MOULDING	Necessary	158.00 F	*158.00 FL
14	1		*REAR WINDSCREEN INNER SEAL	Necessary	235.20 FS	*60.00 FS
15	2		*REAR TAIL LAMP	N/S Cut / O/S Cracked	830.40 F	*830.40 FL
16	1		*REAR END PANEL	Distorted	420.00 F	*420.00 FL
17	1		*REAR END PANEL TOP GARNISH	Deformed	188.00 F	*188.00 FL
18	1		*REAR BUMPER	Distorted	845.20 F	*765.00 FL
19	1		*REAR BUMPER LOWER COVER	Deformed	228.00 F	*228.00 FL
20	2		*REAR BUMPER SIDE BRACKET	Necessary	178.40 F	*75.00 FL
21	1		*REAR BUMPER REINFORCEMENT	Not Necessary	425.00 F	*- FL
22	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	132.00 F	*- FL
23	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
24	1		*REAR SIDE BUMPER	O/S Torn	510.00 F	*195.00 FL
25	8		*REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
26	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	736.00 F	*- FL
27	2		*REAR FENDER INNER COWLING	Not Necessary	576.00 F	*- FL
28	2		*REAR BUMPER SIDE RETAINER	Not Necessary	316.40 F	*- FL
29	2		*REAR MUD -SHIELD	Not Necessary	224.40 F	*- FL
30	1		*REAR EXHAUST ALUMINIUM COVER	Not Necessary	125.20 F	*- FL
31	1		*REAR SPARE TIRE PANEL SEALANT	Not Necessary	200.00 F	*- FL
32	1		*REAR SPARE TYRE WELL	Repair	252.20 F	*- FL
33	1		*REAR SPARE TYRE TOP BOARD	Deformed	577.60 F	*285.00 FL
34	1		*REAR SPARE TIRE PANEL TOP COVER	Not Necessary	452.00 F	*- FL
35	1		*TOOLS BOX SPONGE	Cracked	298.00 F	*298.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,983.30	6,473.10
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,242.62
Total Parts (\$)	11,983.30	5,230.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX CUSHION	New	120.00	80.00
2	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	GUM	New	50.00	50.00
4	TO REMOVE & REFIX REAR EXHAUST (NPA)	New	0.00	0.00
5	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
6	TUFF KOTE	New	120.00	60.00
7	TO CHECK WIRING SYSTEM	New	80.00	30.00
8	PANEL BEATING	New	1,200.00	800.00
9	SPRAY PAINTING	New	1,200.00	800.00
Gross Labour Cost (\$)			3,010.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >