Adjuster Report Page 1 of 3

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21001199/KTF3Q2

**Date:** 18/02/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070148879

Claimant
Vehicle No: SLP3424P

Insured Vehicle No: SLH340J

Date of Loss: 25/01/2021 Nature of Claim: TP Claim No: 5134504369SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLP3424P

 Make & Model:
 HONDA VEZEL, 1.5 X (A)
 Engine No:
 LEB5945370

 Reg. Date:
 31/05/2017 (Man. Year: 2017)
 Chassis No:
 RU31245352

 Colour:
 Metallic Grey
 Odometer:
 260636 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,640.00	2,175.60	464.40	17.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,145.00	1,325.00	820.00	38.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,785.00	3,500.60	1,284.40	26.84
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	4,785.00	2,800.00	1,985.00	41.48

**INSPECTION** 

Date of Assignment: 25/01/2021

Date Inspected: 29/01/2021 Inspected At: BLK 5038 ANG MO KIO INDUSTRIAL

PARK 2, #01-405

SINGAPORE 569541

REPAIRER: LIAN HER MOTORS

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR O/S FENDER	Bent/Buckled	950.30 FL	*950.30 FL
2	1		*REAR O/S FENDER ARCH GARNISH	Dented/Cut	175.20 FL	*175.20 FL
3	1		*REAR O/S FENDER INNERSHIELD	Distorted	105.10 FL	*105.10 FL
4	1		*REAR BUMPER	Mtg Cracked	955.60 FL	*725.60 FL
5	1		*REAR O/S SIDE BUMPER	Mtg Cracked	335.60 FL	*235.10 FL
6	1		*REAR O/S BUMPER SIDE RETAINER	Distorted	65.70 FL	*65.70 FL
7	1		*REAR O/S TYRE RIM	Dented	550.00 FS	*350.00 FS
8	10		*REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
F=Fra	nchise	part. S=SpcN	lett. L=ListItemDisc.			
				Sub Total (S\$)	3,157.50	2,627.00
	- List Item Discount on L Items 20.00/20.00% (S\$)			517.50	451.40	
				Total Parts (S\$)	2,640.00	2,175.60
	Report was unsubmitted during this print-out.					

Adjuster Report Page 3 of 3

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING	New	900.00	600.00
2	TO PUTTY AND SPRAY PAINT	New	900.00	600.00
3	CHECK & RECONNECT WIRING	New	45.00	15.00
4	REMOVE/REFIT ROOF LINING TO FACILITATE REPAIR	New	180.00	80.00
5	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	120.00	30.00
	Gross Labour Cost (S\$)		2,145.00	1,325.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >