

## Mechanical Inspection Report Request

Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>

Fri 22/1/2021 3:07 PM

To: Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>

Cc: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; Siew Ping TANG (SPF) <TANG\_Siew\_Ping@spf.gov.sg>; Stephanie CHEUNG (SPF) <Stephanie\_CHEUNG@spf.gov.sg>

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **3 vehicles** below on an **urgent basis**:

a. **Case IAFP-IB-20210119 - Mechanical Inspection of Motorcar, SKZ6635L (TP/IP/58069/2020)**

- On 29 December at about 1708hrs, the driver of SKZ6635L was travelling on lane 2 of 4-lane road along Serangoon Road towards Upper Serangoon Road when his vehicle veered to the right and he collided into 3 pedestrians and one lamp post. Head Investigation (TP) directed during morning panel, to send for vehicle inspection to rule out mechanical default.

- **Vehicle to be inspected:** SKZ6635L - Driver (Potential Defendant)

IO In-Charge: SIO Siew Ping

b. **Case IAFP-IB-20210119 - Mechanical Inspection of Van, GBD7996K (TP/IP/56369/2020)**

- On the 19/12/2020 at about 10.16 a.m., the driver was driving along Mount Faber Road towards Telok Blangah Road on the single lane down slope road which she claimed that the steering wheel was stiff, and its brakes were not functioning. She was unable to manoeuvre her vehicle while negotiating the bends nor brake to stop the vehicle which eventually collided into the green construction barriers and concrete walls along the road before coming to a stop. The driver claimed it was due to a mechanical fault to the vehicle. Therefore, a mechanical inspection is required to eliminate mechanical fault.

- **Vehicle to be inspected:** GBD7996K - Driver (Potential Defendant)

IO In-Charge: IO Stephanie Cheung

c. **Case IAFP-IB-20210119 - Mechanical Inspection of Motorcar, SJP5485Z (TP/IP/00087/2021)**

- On 2 January 2021 at about 4.39 a.m., the Deceased was believed to be driving straight along KJE (BKE), slip road into BKE (SLE) on lane 1 of the 3-lane road when he lost control of the motorcar and resulting it to skid to the left, mounted the left kerbside and collided into lamp post no. 70S10. After colliding into the said lamp post on the grass verge, the motorcar continued to drive into the grass verge and colliding into 8 portions of guard railings, before it overturned. Due to the collision, the Deceased's motorcar veered to the right, mounted a kerb and collided onto a lamppost located along the pavement. The Deceased sustained multiple injuries and he succumbed to his injuries. He was pronounced dead at scene, at 6.02 a.m. by the attending paramedic, Hakim.

- **Vehicle to be inspected:** SJP5485Z - Driver (Deceased)