

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG18004394/TPA3Q2-1**Date:** 01/07/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100121443-09000
Claimant Vehicle No : SBS6329P **Insured Vehicle No :** EE676P
 Date of Loss: 05/03/2018 Nature of Claim: TP Claim No: 4256953123SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS6329P**
 Make & Model: MERCEDES-BENZ CITARO O530, 6.4 D (A) Engine No: 90292600952018
 Reg. Date: 03/12/2012 (Man. Year: 2012) Chassis No: WEB62808323123796
 Colour: Green Odometer: 267698 km
 Engine Capacity: 6374 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
 Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8/8 mm
 Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	800.00	200.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,000.00	800.00	200.00	20.00
+ GST 7.00/7.00% (S\$)	70.00	56.00	14.00	20.00
Nett Amount (S\$)	1,070.00	856.00	214.00	20.00
+ Loss of Use (1.0 x S\$250.00/day) (S\$)		250.00		
		(S\$) 1,106.00		
Liabe Amount (50.00%) (S\$)		553.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		555.00		
Global Sum Settlement (S\$)		500.00		

INSPECTION

Date of Assignment: 06/03/2018
 Date Inspected: 20/03/2018 Inspected At: Tower Transit Singapore Pte Ltd (HQ)
 21 Bulim Drive, Bulim Bus Depot
 Singapore 648170
 Estimated Period of Repair: 1.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE/ REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING)	New	1,000.00	800.00
Gross Labour Cost (\$)			1,000.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >