

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001211/T1GS3Q2
Date: 18/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100414466
Claimant Vehicle No :	SLW3044R	Insured Vehicle No :	SKT9989C
Date of Loss:	25/01/2021	Nature of Claim:	TP
		Claim No:	8479125370SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW3044R	Engine No:	L15B5461267
Make & Model:	ADIVA AD1 200, 190cc 3W	Chassis No:	GK81201072
Reg. Date:	06/02/2018 (Man. Year: 2017)	Odometer:	67042 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,283.60	3,221.68	4,061.92	55.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,970.00	2,070.00	1,900.00	47.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,253.60	5,291.68	5,961.92	52.98
Approved Total (Overridden) (S\$)		4,200.00		

Nett Amount (S\$)	11,253.60	4,200.00	7,053.60	62.68
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,807.45		

INSPECTION

Date of Assignment: 26/01/2021

Date Inspected: 26/01/2021

Estimated Period of Repair: 6.0 days

Inspected At: Black Eagle Auto Pte Ltd (HQ)
25 KAKI BUKIT ROAD 4, #05-80
Singapore 417800

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,450.00 FL	*1,193.00 FL
2	1		*TAIL GATE INNER LOCK	Bent	238.00 FL	*187.50 FL
3	1		*TAIL GATE WEATHERSTRIP	Twisted	185.00 FL	*185.00 FL
4	1		*TAIL GATE CHROME GARNISH	Not Necessary	285.00 FL	*- FL
5	1		*TAIL GATE SHUTTLE EMBLEM	Necessary	78.00 FL	*78.00 FL
6	1		*TAIL GATE HONDA BADGE	Necessary	42.00 FL	*42.00 FL
7	2		*TAIL GATE REFLECTORS	Not Necessary	649.00 FL	*- FL
8	1		*TAIL GATE INNER BOARD	Not Necessary	560.00 FL	*- FL
9	1		*TAIL GATE LOCK ACTUATOR	Not Necessary	248.00 FL	*- FL
10	1		*REAR WINDSCREEN MOULDING	Necessary	185.00 FL	*185.00 FL
11	1		*REAR END PANEL	Bent	798.00 FL	*570.00 FL
12	1		*REAR END PANEL TOP GARNISH	Deformed	260.00 FL	*180.00 FL
13	1		*REAR SPARE TYRE PANEL	Repair	850.00 FL	*- FL
14	1		*REAR SPARE TYRE PANEL TOOLS GARNISH BOX	Not Necessary	520.00 FL	*- FL
15	1		*REAR BUMPER	Deformed	1,078.00 FL	*956.00 FL
16	2		*REAR BUMPER REFLECTORS	Not Necessary	144.80 FL	*- FL
17	2		*REAR BUMPER SIDE REFLECTOR GARNISH	Not Necessary	220.00 FL	*- FL
18	1		*REAR BUMPER SIDE RETAINER	O/S Not Necessary /N/SDeformed	76.20 FL	*38.10 FL
19	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
20	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
21	1		*REAR SPARE TYRE PANEL INSULATOR	Not Necessary	280.00 FS	*- FS
22	1		*REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
23	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	120.00 FS	*- FS
24	1		*REAR WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,857.00	3,944.60
- List Item Discount on L Items 20.00/20.00% (\$)	1,573.40	722.92
Total Parts (\$)	7,283.60	3,221.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS, PANEL BEAT & RESHAPE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,800.00	900.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS	New	1,400.00	900.00
3	TO REMOVE ,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER ELECTRICAL FUNCTION	New	150.00	30.00
4	TO REMOVE AND REPLACE REVERSE SENSOR AND CHECK FOR PROPER FUNCTION	New	100.00	30.00
5	TO REMOVE BOOT COMPARTMENT FITTINGS ,GARNISH ,TRIMS ETC SO AS TO FACILITATE REPAIRS AND REFIX /REPLACE THE SAME	New	200.00	60.00
6	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	180.00	30.00
7	TO REMOVE AND REFIX REAR WINDSCREEN	New	140.00	120.00
Gross Labour Cost (S\$)			3,970.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >