VEHICLE NO. SLW 3044R HONDA SHUTTLE

VEHICLE NO. SLW 3044R HONDA SHUTTLE					
QTY	DESCRIPTION	CONDITION	REPAIRER'S	SURVEYOR'S	
	PARTS (LIST ITEMS)		ESTIMATE(S\$)	ADJUSTMENT	
1	Tail Gate		1450.00	b+v	
1	Tail Gate Inner Lock		1450.00	pto photo	
1	Tail Gate Weatherstrip		238.00	bus	
1	Tail Gate Chrome Garnish		185.00	×	
1	Tail Gate SHUTTLE emblem		285.00	101-	
1	Tail Gate Honda Badge				
2	Tail Gate reflectors @324.50			New Y	
1	Tail Gate Inner Board		649.00		
1	Tail Gate lock actuator		560.00	-5-5-51	
1	Rear Windscreen moulding		248.00	A11.	
1	Rear End Panel		185.00		
1	Rear End Panel Top Garnish		798.00	bt phot.	
1	Rear spare tyre panel			de	
1			850.00	A SA	
1	Rear spare tyre panel tools garnish box Rear Bumper		520.00		
2			1078.00		
2	Rear Bumper reflectors @72.40		RHX 144.80		
2	Rear Bumper side reflector garnish@\$110		RHY 220.00		
2	Rear Bumper Side Retainer @ \$38.10		RHX 76.20		
		Δ	7867.00		
		less	20% 1573.40	12.40.00.00	
	CDECIAL NETT ITENAN		6293.60		
1+	SPECIAL NETT ITEMS				
	Rear Bumper Clips		60.00	3044	
1	Rear end panel sealant		100.00	4 oner	
1	Rear spare tyre panel insulator		280.00		
1	Reverse Sensor		280.00	20011/	
1	Rear spare tyre panel sealant		120.00	×	
1	Rear Windscreen Sealant		150.00	6 ones	
		TOTAL PARTS	7283.60		

VEHICLE NO. SLC 6711J HONDA JADE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs, panel beat & reshape affected areas and replace the damaged parts and components	1800.00	900
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	1400.00	900.
3	To remove, refix wiring system at accident damaged areas and check for proper electrical function	150.00	30
4	To remove and replace reverse sensor and check for proper function	100.00	30
5	To remove boot compartment fittings, garnish, trims etc so as to facilitate repairs and refix/replace the same	200.00	60.
6	To provide anti-rust treatment on affected areas	180.00	30
7	To remove and refix rear windscreen	140.00	120
	Labour Total :	3970.00	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

Taufin 17415749
WP 26/1/2101170
-6 days
1/4 Resum Afar repair
taufin @ [hhank.wm.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: