QTY	DESCRIPTION	CONDITION	REPAIRER'S	SURVEYOR'S
	PARTS (LIST ITEMS)	CONDITION	ESTIMATE(S\$)	ADJUSTMENT
1	Tail Gate	+	1	1.1.
1	Tail Gate Inner Lock		1193 1450.0	opti
1	Tail Gate Weatherstrip	1	187.50 238.00	ster photo
1	Tail Gate Chrome Garnish	1	185.00	TWIN
	Tail Gate SHUTTLE emblem		285.00	ואמןכ
	Tail Gate Honda Badge	\$		101-
	Tail Gate reflectors @324.50			new
	Tail Gate Inner Board		649.00	Xun
	Tail Gate lock actuator	1	560.00	1 X un
			248.00	TX nh
	Rear Windscreen moulding Rear End Panel		185.00	Nec
	Rear End Panel Top Garnish		570 798.00	
1	Rear spare tyre panel		180 260.00	de
1	Rear spare tyre panel tools		850.00	Rp
1	Rear spare tyre panel tools garnish box Rear Bumper		520.00	Xnn
	Rear Bumper reflectors @72.40	i i	956 1078.00	de
2 F	Rear Bumper side reflector garnish@\$110	1	R4x 144.80	LH-ZAM.
2 R	Rear Bumper Side Retainer @ \$38.10		RH x 220.00	LH-X nn
		3526.50	R4 x ~ 76.20	14-der 38.10
1	3614.60	3576.50	7867.00	25110
1	2891.68	128by Colless	20% 1573.40	20%
SI	PECIAL NETT ITEMS		6293.60	
set Re	ear Bumper Clips	1		
1 Re	ear end panel sealant	1	60.00	304aL
L Re	ear spare tyre panel insulator	1	100.00	30mac Honac
Re	everse Sensor		280.00	
	ar spare tyre panel sealant	1		20011
Re	ar Windscreen Sealant		120.00	
	- Son Scalarit			
			130.00	5 ones -
		TOTAL PARTS		

S/N	DESCRIPTION	REPAIRER'S	SURVEYOR'S			
	LABOUR	ESTIMATE (S\$)	ADJUSTMENT			
1	To remove the affected parts & fittings to commence repairs, panel beat & reshape affected areas and replace the damaged parts and components	1800.00	900			
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	1400.00	900.			
3	To remove, refix wiring system at accident damaged areas and check for proper electrical function	150.00	\$10.			
4	To remove and replace reverse sensor and check for proper function	100.00	20.			
5	To remove boot compartment fittings, garnish, trims etc so as to facilitate repairs and refix/replace the same	200.00	60			
6	To provide anti-rust treatment on affected areas	180.00	30			
7	To remove and refix rear windscreen	140.00	120			
	Labour Total :	3970.00	2070			
<u> </u>	TOTAL (PARTS & LABOUR):	11253.60				

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

Taufthi 97495749

28191.68

WP 26/1/710170

28191.68

2070

2070

2/4 Resign of a repair 15291.68

4 4200

4 4200

4 6 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature: Date: