

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001216/EVD3E2

Date: 22/02/2021

REFERENCE

Insured/Claimant: NIRMALA D/O SIVAGURU AYA DURAI

Policy No:

Date of Loss: 25/01/2021

Nature of Claim: OD Claim No: 6000431789SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS3199L	Engine No:	3A92UJL6340
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AKH004956
Reg. Date:	21/02/2020 (Man. Year: 2019)	Odometer:	14291 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$63,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,752.42	6,171.59	2,580.83	29.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,100.00	5,365.00	735.00	12.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,852.42	11,536.59	3,315.83	22.33
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	14,552.42	11,236.59	3,315.83	22.79
+ GST 7.00/7.00% (S\$)	1,018.67	786.56	232.11	22.79
Nett Amount (S\$)	15,571.09	12,023.15	3,547.94	22.79

INSPECTION

Date of Assignment: 26/01/2021

Date Inspected: 26/01/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 9.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*PANEL ASSY, FR END	Dented	1,055.00 FL	*1,055.00 FL
3	1		*PANEL, HEADLAMP SUPPORT, UPR	Broken	65.00 FL	*65.00 FL
4	1		*MOTOR, COOLING FAN	Not Necessary	479.00 FL	*- FL
5	1		*SHROUD, COOLING FAN	Broken	130.00 FL	*130.00 FL
6	1		*FAN, COOLING, LH	Not Necessary	77.00 FL	*- FL
7	1		*RADIATOR ASSY	Broken	967.00 FL	*967.00 FL
8	1		*PANEL, AIR GUIDE	Broken	112.00 FL	*112.00 FL
9	1		*CONDENSER ASSY, A/C REFRIGE	Bent	758.00 FL	*758.00 FL
10	1		*PANEL, AIR GUIDE, RH	Broken	11.00 FL	*11.00 FL
11	1		*PANEL, AIR GUIDE, LH	Broken	11.00 FL	*11.00 FL
12	1		*LLC 4L	Not Necessary	26.00 FL	*- FL
13	1		*HEADLAMP ASSY, LH	Broken	660.00 FL	*660.00 FL
14	1		*HEADLAMP ASSY, RH	Broken	660.00 FL	*660.00 FL
15	1		*MARK, THREE-DIA	Necessary	69.00 FL	*69.00 FL
16	1		*GRILLE, RADIATOR	Broken	554.00 FL	*554.00 FL
17	1		*BRACKET, FR BUMPER, LH	Broken	13.00 FL	*13.00 FL
18	1		*BRACKET, FR BUMPER, RH	Broken	13.00 FL	*13.00 FL
19	1		*GRILLE, FR UNDER	Broken	165.00 FL	*165.00 FL
20	1		*GARNISH-FR BUMPER, LH	Not Necessary	127.00 FL	*- FL
21	1		*GARNISH, FR BUMPER, RH	Not Necessary	127.00 FL	*- FL
22	1		*COVER, HEADLAMP SUPT PANEL	Broken	62.00 FL	*62.00 FL
23	6		*CLIP, FR BUMPER	Necessary	24.00 FL	*24.00 FL
24	1		*FACE, FR BUMPER	Broken	703.00 FL	*703.00 FL
25	1		*COVER, FR BUMPER	Missing	12.00 FL	*12.00 FL
26	1		*HOOD	Dented	734.00 FL	*734.00 FL
27	1		*HINGE, HOOD, LH	Bent	56.00 FL	*56.00 FL
28	1		*HINGE, HOOD, RH	Bent	56.00 FL	*56.00 FL
29	1		*INSULATOR, HOOD	Not Necessary	177.00 FL	*- FL
30	6		*CLIP, HOOD INSULATOR	Not Necessary	18.00 FL	*- FL
31	1		*LATCH, HOOD	Not Necessary	69.00 FL	*- FL
32	1		*FENDER, FR LH	Dented	497.00 FL	*497.00 FL
33	1		*FENDER, FR RH	Dented	497.00 FL	*497.00 FL
34	1		*EMBLEM ECO	Necessary	17.00 FS	*17.00 FS
35	1		*BODY KIT ATTRAGE	Not Necessary	1,643.00 FS	*- FS
36	1		*HORN	Not Necessary	79.00 FL	*- FL
37	1		*INSULATOR,RDTR SUPPORT,LWR (Supplementary)	Broken	13.00 FL	*13.00 FL
38	6		*RIVET,FR BUMPER (Supplementary)	Necessary	30.00 FL	*30.00 FL
39	10		*CLIP,FR BUMPER (Supplementary)	Necessary	40.00 FL	*40.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,856.00	8,004.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	2,103.58	1,832.41
Total Parts (\$\$)	8,752.42	6,171.59

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BUMPER, FRONT BODY KITS, RH FRONT FENDER, LH FRONT FENDER, REPAIR RH FRONT DOOR, REPAIR LH FRONT DOOR	New	2,250.00	2,025.00
2	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK	New	100.00	100.00
3	TOP UP AIR CON GAS AND CHECK A/CON GAS	New	80.00	80.00
4	REMOVE AND REPLACE FRONT BODY KITS	New	80.00	80.00
5	PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER FACE, FRONT BODY KITS, RH FRONT FENDER, LH FRONT FENDER, RH FRONT DOOR, LH FRONT DOOR AND AFFECTED PORTION	New	3,150.00	2,800.00
6	SUPPLY BODY SEALANT	New	120.00	40.00
7	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	PERFORM RUST PREVENTION	New	120.00	40.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
10	SUPPLY FRONT NUMBER PLATE WITH FRAME	New	50.00	50.00
Gross Labour Cost (\$\$)			6,100.00	5,365.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >