

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21001221/DQD3Q2

**Date:** 25/02/2021

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00188752000

**Claimant  
Vehicle No :** SML4487K

**Insured  
Vehicle No :** SLB3988C

Date of Loss: 23/01/2021

Nature of  
Claim: TP

Claim  
No: SNM21D200414/C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML4487K**

Make & Model: MAZDA 3, 1.5 (A)

Engine No: S530435132

Reg. Date: 21/05/2019 (Man. Year: 2019)

Chassis No: BMLFP101378

Colour: Silver

Odometer: 65157 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,125.44	859.68	4,265.76	83.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	430.00	2,170.00	83.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,725.44</b>	<b>1,289.68</b>	<b>6,435.76</b>	<b>83.31</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,000.00</b>		
<b>(S\$)</b>	7,725.44	1,000.00	6,725.44	87.06
<b>+ GST 7.00/7.00% (S\$)</b>	540.78	70.00	470.78	87.06
<b>Nett Amount (S\$)</b>	<b>8,266.22</b>	<b>1,070.00</b>	<b>7,196.22</b>	<b>87.06</b>

### INSPECTION

Date of Assignment: 26/01/2021

Date Inspected: 26/01/2021 Inspected At:

C.S. Ong Auto Pte Ltd (AMK)  
10 Ang Mo Kio Industrial Park 2A,  
#02-16, AMK Auto Point  
Singapore 568047

Estimated Period of Repair: 2.0 days

**Adjuster:** BRYAN TANI

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2021)
<b>Parts:</b>	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SML4487K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Not Necessary	1,476.30 FL	*- FL
2	2		*REAR BOOTLID NUMBER PLATE LAMP	Not Necessary	65.00 FL	*- FL
3	1		*REAR BOOTLID MAZDA EMBLEM	Not Necessary	87.40 FL	*- FL
4	1		*REAR BOOTLID AXELA EMBLEM	Not Necessary	46.50 FL	*- FL
5	1		*REAR BOOTLID SKYACTIV D EMBLEM	Not Necessary	58.30 FL	*- FL
6	1		*REAR BUMPER	Distorted	1,240.00 FL	*1,074.60 FL
7	2		*REAR BUMPER SIDE RETAINERS LH & RH	Not Necessary	116.00 FL	*- FL
8	2		*REAR BUMPER TOW HOOK COVER	Not Necessary	128.80 FL	*- FL
9	4		*REAR BUMPER REVERSE SENSOR	Not Necessary	1,263.20 FL	*- FL
10	4		*REAR BUMPER REVERSE SENSOR COVER	Not Necessary	150.40 FL	*- FL
11	1		*SET REVERSE SENSOR WIREHARNES	Not Necessary	672.90 FL	*- FL
12	1		*REAR BUMPER SPONGE	Not Necessary	197.30 FL	*- FL
13	1		*REAR END PANEL	Not Necessary	689.40 FL	*- FL
14	1		*REAR END PANEL TOP GARNISH	Not Necessary	215.30 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>6,406.80</b>	<b>1,074.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	1,281.36	214.92
<b>Total Parts (\$)</b>	<b>5,125.44</b>	<b>859.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS ON ALL FRONT AFFECTED AREAS TO FACILITATE REPAIR AND TO REPLACE ALL BACK ONCE REPAIR IS DONE	New	200.00	0.00
2	TO PANEL BEAT ALL AFFECTED AREAS,REPLACE NEW PARTS AND REALIGN ALL ABOVE	New	1,000.00	200.00
3	TO PUTTY AND RE-SPRAY NEW PAINTWORK ON ALL FRONT AFFECTED AREAS	New	1,000.00	200.00
4	TO CONDUCT WHEEL ALIGNMENT	New	100.00	0.00
5	TO CHECK ALL WIRING SYSTEMS ON ALL AFFECTED AREAS	New	150.00	30.00
6	TO APPLY ANTI-RUST AGENT & COATING ON ALL AFFECTED AREAS	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,600.00</b>	<b>430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >