

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001222/UPA3Q2**Date:** 07/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070006109
Claimant Vehicle No :	FBF3952C	Insured Vehicle No :	GBF6993P
Date of Loss:	16/01/2021	Nature of Claim:	TP
		Claim No:	1406689073SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBF3952C	Engine No:	KC11E2014629
Make & Model:	HONDA CBF150, 149cc (M)	Chassis No:	LALKC11A6A3347977
Reg. Date:	20/06/2011 (Man. Year: 2010)	Odometer:	18594 km
Colour:	Black		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90 -18	Rear Tyre Size:	90/80-18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,706.20	1,102.70	1,603.50	59.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	930.00	270.00	660.00	70.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,636.20	1,372.70	2,263.50	62.25
Approved Total (Overridden) (S\$)		1,050.00		
Nett Amount (S\$)	3,636.20	1,050.00	2,586.20	71.12
+ Loss of Use (3.0 x S\$25.00/day) (S\$)		75.00		
Nett Liability (S\$)		1,125.00		

INSPECTION

Date of Assignment:	26/01/2021	Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
Date Inspected:	26/01/2021 Inspected At:	1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
Estimated Period of Repair:	3.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Broken	70.00 FL	*70.00 FL
2	2		*FORK INNER TUBES	Bent	350.00 FL	*350.00 FL
3	2		*FORK OUTER TUBES	Serviceable	360.00 FL	*- FL
4	1		*FORK UNDER BRACKET	Serviceable	185.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Not Necessary	42.00 FL	*- FL
6	1		*HANDLE -BAR	Bent	125.00 FL	*125.00 FL
7	1		*HANDLE -BAR BALANCER -L/R/H	O/S Scratched	56.00 FL	*28.00 FL
8	1		*SET SIDE MIRROR	O/S Cut	100.00 FL	*50.00 FL
9	1		*TOP COWLING	Cracked	235.00 FL	*235.00 FL
10	1		*SET FRONT SIGNALS	O/S Serviceable	110.00 FL	*55.00 FL
11	2		*FRONT FOOTREST -L/R/H	Not Necessary	90.00 FL	*- FL
12	1		*EXHAUST ASSY	Repair	485.00 FL	*- FL
13	1		*EXHAUST COVER	Scratched	150.00 FL	*150.00 FL
14	1		*SET NUMBER PLATE	Serviceable	28.00 FS	*- FS
15	2		*FORK OILS	Necessary	30.00 FS	*30.00 FS
16	2		*FORK OIL SEALS	Necessary	56.00 FS	*56.00 FS
17	1		*SET STEERING CONE	Necessary	90.00 FS	*60.00 FS
18	1		*REAR BOX	Serviceable	280.00 FS	*- FS
19	1		*REAR BOX BRACKET	Not Necessary	100.00 FS	*- FS
					Sub Total (S\$)	2,942.00 1,209.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	235.80 106.30
					Total Parts (S\$)	2,706.20 1,102.70

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING	New	50.00	50.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO REPAIR BODY FRAME	New	380.00	0.00
4	TO PROVIDE LABOUR	New	420.00	220.00
Gross Labour Cost (\$\$)			930.00	270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >