



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 6845P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET	BUCKLED	1,380.97	1,380.97
1	BONNET INNER RUBBER	NECESSARY	63.79	63.79
2	BONNET HINGES @\$64.89	BENT / TWISTED	129.78	129.78
1	BONNET INSULATOR	NOT NECESSARY	205.30	-
1	FRONT GRILLE	NOT NECESSARY	322.10	-
1	FRONT BUMPER	DISTORTED	1,076.45	1,076.45
2	FRONT BUMPER SIDE RETAINERS @\$45.00	BENT / CRACKED	90.00	90.00
1	FRONT BUMPER BEAM	TO REPAIR SEE LABOUR	615.11	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER LOWER GARNISH	TORN	241.50	241.50
1	FRONT BUMPER CENTRE GRILLE	TORN	105.00	105.00
1	FRONT BUMPER FOG LAMP O/S	CRACKED	350.00	350.00
1	FRONT BUMPER SPONGE	TORN	162.30	162.30
1	FRONT FENDER O/S	DISTORTED	549.12	549.12
1	FRONT FENDER INNER SHIELD O/S (FRT)	TORN	145.30	145.30
1	FRONT FENDER INNER SHIELD O/S (REAR)	TORN	188.20	188.20
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NECESSARY	50.00	50.00
1	FRONT FENDER BRACKET O/S	BENT	62.50	62.50
1	FRONT FENDER INNER PANEL O/S	DENTED / TWISTED	699.20	699.20
1	FRONT FENDER OUTER GLASS MOULDING O/S	TWISTED	185.00	185.00
1	HEADLAMP O/S	BROKEN	2,009.71	2,009.71
1	HEADLAMP TOP PANEL O/S	BENT	199.00	199.00
1	FRONT DOOR O/S	TO REPAIR SEE LABOUR	1,122.00	-
1	FRONT SUPPORT PANEL	SERVICEABLE	495.00	-
1	FRONT SPORT RIM O/S	DAMAGED	800.00	800.00
1	FRONT KNUCKLE ARM O/S	BENT	425.00	425.00
1	FRONT KNUCKLE ARM BEARING O/S	NECESSARY	266.00	266.00
	LESS 10% DISCOUNT		-	-922.88
			11,988.33	8,305.94

Report Ref No. CS/TP21001224/Uqf3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	30.00
	TO SPRAY RUST PROOFING.		120.00	80.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	80.00
	TO DISMANTLE & REPLACED FRT UNDER CARRIAGE.		200.00	120.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	TO TRANSFER FRT DOOR MECHANISM.	NOT NECESSARY	100.00	-
	TO RESET & REPROGRAMME.		100.00	50.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER BEAM AND FRONT DOOR O/S.		1,280.00	1,000.00
	TO PUTTY & SPRAY PAINTING.		1,580.00	1,300.00
			3,700.00	2,660.00
	<b>GRAND TOTAL</b>		<b>15,688.33</b>	<b>10,965.94</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>8,800.00</b>

Report Ref No. CS/TP21001224/Uqf3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.