

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21001225/ATF3E2

Date: 28/05/2021

REFERENCE

Insured/Claimant:	CHUNG LYE PENG	Policy No:	1700016379		
Date of Loss:	25/01/2021	Nature of Claim:	OD	Claim No:	1247751643SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP6864H	Engine No:	CHZ345025
Make & Model:	AUDI Q2, 1.4 (A)	Chassis No:	WAUZZZGA3HA040768
Reg. Date:	14/06/2017 (Man. Year: 2017)	Odometer:	53751 km
Colour:	Red		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$84,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,895.00	7,612.00	11,283.00	59.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,484.00	4,204.00	7,280.00	63.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,379.00	11,816.00	18,563.00	61.10
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	29,979.00	11,416.00	18,563.00	61.92
+ GST 7.00/7.00% (S\$)	2,098.53	799.12	1,299.41	61.92
Nett Amount (S\$)	32,077.53	12,215.12	19,862.41	61.92

INSPECTION

Date of Assignment:	26/01/2021		
Date Inspected:	26/01/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,758.00 FS	*1,523.60 FS
2	1		*FRONT BUMPER CONNECTING PIECE-CENTER	Not Necessary	148.00 FS	*- FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	347.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	197.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	169.00 FS	*135.20 FS
6	1		*FRONT BUMPER END CAP - LH	Not Necessary	59.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Cut	299.00 FS	*238.80 FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	156.00 FS	*- FS
9	1		*FRONT WHEEL SPOILER - LH	Not Necessary	34.00 FS	*- FS
10	1		*FRONT ADAPTER - LH	Not Necessary	36.00 FS	*- FS
11	1		*RADIATOR GRILLE	Not Necessary	1,411.00 FS	*- FS
12	1		*RADIATOR GRILLE STRICKER PLATE	Not Necessary	124.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	723.00 FS	*- FS
14	1		*FRONT FOAM FILLER PIECE	Not Necessary	78.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION - LH	Cracked	36.00 FS	*28.32 FS
16	1		*FRONT BUMPER COVER	Not Necessary	100.00 FS	*- FS
17	1		*SIGN CAUTION STICKER	Not Necessary	14.00 FS	*- FS
18	1		*AIR CONDITIONER STICKER	Not Necessary	8.00 FS	*- FS
19	1		*HORN - LH	Not Necessary	286.00 FS	*- FS
20	1		*SPRING SHACKLE - LH	Not Necessary	31.00 FS	*- FS
21	1		*FRONT FENDER - LH	Dented	1,147.00 FS	*917.60 FS
22	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	40.00 FS	*- FS
23	1		*FRONT FENDER BRACKET - LH	Not Necessary	48.00 FS	*- FS
24	1		*FRONT FENDER LEDGE COVER - LH INNER	Not Necessary	16.00 FS	*- FS
25	1		*FRONT FENDER LEDGE COVER - LH OUTER	Not Necessary	16.00 FS	*- FS
26	1		*FRONT FENDER BRACE - LH	Bent	44.00 FS	*34.88 FS
27	1		*FRONT WHEEL HOUSING LINER - LH	Deformed	196.00 FS	*156.40 FS
28	1		*FRONT WHEEL HOUSING ATTACHMENT PARTS	Not Necessary	57.00 FS	*- FS
29	1		*FRONT HEADLIGHT MOUNTING	Cracked	118.00 FS	*94.40 FS
30	1		*LED HEADLIGHT - LH	Cracked	4,915.00 FS	*3,932.00 FS
31	1		*LED HEADLIGHT POWER MODULE - LH	Not Necessary	758.00 FS	*- FS
32	1		*LED WITH HEAT SINK - LH	Not Necessary	733.00 FS	*- FS
33	1		*LED HEADLIGHT CONTROL UNIT - LH	Not Necessary	557.00 FS	*- FS
34	1		*HOSE FOR HEADLIGHT WASHER SYSTEM	Not Necessary	30.00 FS	*- FS
35	1		*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM	Not Necessary	142.00 FS	*- FS
36	1		*CONNECTOR HOSE FOR HEADLIGHT WASHER SYSTEM	Not Necessary	182.00 FS	*- FS
37	1		*WASHER WATER RESERVOIR	Not Necessary	176.00 FS	*- FS
38	1		*FRONT LOCK CARRIER	Not Necessary	994.00 FS	*- FS
39	4		*RADIATOR COOLANT	Not Necessary	95.00 FS	*- FS
40	1		*FRONT AIR GUIDE - LH	Not Necessary	31.00 FS	*- FS
41	1		*REFRIGERANT LINER (A/C CONDENSER > CUT OFF POINT)	Not Necessary	619.00 FS	*- FS
42	2		*A/C SEAL RING	Not Necessary	14.00 FS	*- FS
43	2		*FRONT WHEEL COVER - LH / RH	N/S Cut / O/S Necessary	644.00 FS	*514.40 FS
44	1		*FRONT ALUMINIUM RIM - LH	Not Necessary	949.00 FS	*- FS
45	1		*FRONT NO. PLATE	Not Necessary	60.00 FS	*- FS
46	1		*SUNDRIES	Necessary	300.00 FS	*36.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 18,895.00 7,612.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	0.00
3	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
4	TO RENEW AIRCON CONDENSER REFRIGERANT PIPE	New	280.00	0.00
5	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR COVER	New	280.00	280.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,800.00	1,000.00
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR	New	3,300.00	1,650.00
8	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
9	TO CARRY OUT PRE / POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			11,484.00	4,204.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >