



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 5938D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RHS FRONT FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	860.00	-
1	RHS FRONT FENDER INNER SPLASH SHIELD (CONSISTENT)	CUT	298.00	156.50
1	RHS FRONT SHOCK ABSORBER (CONSISTENT)	NOT NECESSARY	592.00	-
1	RHS FRONT WHEEL HUB BEARING (CONSISTENT)	BENT	394.00	294.00
1	RHS FRONT WHEEL HUB (CONSISTENT)	BENT	450.00	350.00
1	RHS FRONT LOWER ARM (CONSISTENT)	NOT NECESSARY	342.00	-
1	FRONT BUMPER (CONSISTENT)	DEFORMED	880.00	880.00
1	FRONT BUMPER SPOILER (CONSISTENT)	NOT NECESSARY	780.00	-
1	FRONT BUMPER SIDE RETAINER (CONSISTENT)	NECESSARY	72.00	72.00
	LESS 10% DISCOUNT		-466.80	-
	LESS 20% DISCOUNT		-	-350.50
			4,201.20	1,402.00
<u>SPECIAL NETT ITEMS</u>				
1	LHS FRONT FENDER SPLASH SHIELD CLIPS (SN) (CONSISTENT)	NECESSARY	60.00	10.00
			60.00	10.00
<u>LABOUR</u>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.INCLUSIVE OF THE REPAIR OF RHS FRONT FENDER .		800.00	300.00
	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS .		800.00	400.00
	TO REMOVE AND REPLACE RHS FRONT UNDERCARRIAGE PARTS AND SUSPENSION SYSTEM.		200.00	120.00
	TO CHECK WIRING AT ACCIDENT DAMAGED AREAS AND REFIX OR REPLACE AS NECESSARY .		80.00	30.00
	TO REMOVE AND REFIX SENSORS TO FRONT BUMPER AND CHECK FOR PROPER FUNCTION .	NOT NECESSARY	100.00	-
	TO CONDUCT FULL COMPUTERISED WHEEL ALIGNMENT TEST .		150.00	80.00

Report Ref No. CC4/ASM21001227/T1ba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED PARTS REPLACED .		150.00	30.00
			2,280.00	960.00
	GRAND TOTAL		6,541.20	2,372.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00

Report Ref No. CC4/ASM21001227/T1ba3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.