

VEHICLE NO. SLV5938D

Honda Shuttle

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT		
	<u>PARTS (LIST ITEMS)</u>					
1	RHS front fender		860.00	Rx		
1	RHS front fender inner splash shield		298.00	X out		
1	RHS front shock absorber		592.00	X		
1	RHS front wheel hub bearing		394.00	?		
1	RHS front wheel hub		450.00	?		
1	RHS front lower arm		342.00	X		
1	Front bumper		880.00	del		
1	Front bumper spoiler		780.00	X		
1	Front bumper side retainer		72.00	del		
			4668.00			
		less	10%	466.80	10%	0.00
				4201.20		0.00
	<u>SPECIAL NETT ITEMS</u>					
1	LHS front fender splash shield clips		60.00	X 10.		
	Total Parts		4261.20			

VEHICLE NO. SLV5938D Honda Shuttle

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	800.00	300.
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	800.00	400.
3	To remove and replace RHS front undercarriage parts and suspension system	200.00	✓120? photo.
4	To check wiring at accident damaged areas and refix or replace as necessary	80.00	30
6	To remove and refix sensors to front bumper and check for proper function	100.00	X
7	To conduct full computerised wheel alignment test	150.00	80.
8	To perform anti-rust treatment on affected parts replaced	150.00	*30.
	Labour Total :	2280.00	
TOTAL (PARTS & LABOUR):		6541.20	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts and labour

Taufik 97495449
 'wp' 28/1/21 @ 1115
 c/s Resurvey after repair
 taufik @ lkkauto.com.
 3-4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name SLV 5938 D

Date 2021-January-16 02:19p.m.

Honda : Shuttle : GK8

Left Front					Right Front			
Actual	Before	Specified Range			Actual	Before	Specified Range	
-0°02'	-1°00'	1°00'	Camber	-1°00'	1°00'
.	4°00'	6°00'	Caster	4°00'	6°00'
-0°03'	-0°09'	0°09'	Toe	-0°09'	0°09'
.	SAI
.	Included Angle
.	Turning Angle Diff.

	Front		
	Actual	Before	Specified Range
Cross Camber	1°00' 1°00'
Cross Caster
Total Toe	-0°17' 0°17'

Left Rear					Right Rear			
Actual	Before	Specified Range			Actual	Before	Specified Range	
-2°06'	-2°45'	-0°45'	Camber	-1°57'	-2°45'	-0°45'
0°03'	0°00'	0°17'	Toe	0°12'	0°00'	0°17'

	Rear		
	Actual	Before	Specified Range
Total Toe	0°15'	0°00' 0°34'
Thrust Angle	-0°05'