



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---------------------------|------------------------------------|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 | Cust No/Name | LCV11495/KAMSANI BIN JANTAN |
| | Reg No/Reg Date | SMQ3930C / 14/11/201 |
| | Date In/Mileage | 26/01/2021/ 0 |
| | Chassis No | KNAF5416MK5051851 |
| | Engine No | G4FGKH748537 |
| | Make/Model | KIA/CERATO 1.6 A GT LINE H171 |
| | Colour/Trim | ABP AURORA BLACK / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|--|--------------------------------|-------------------|-----|-------------------|--------|------------|-------|---------|
| LAX00000 | Credit | 26/01/2021/ 12:27 | QUK | 282 / Kevin Leong | 28077 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 REPLACE FRONT BUMPER PANEL,SUPPORT PANEL & AFFECTED AREA | | | | | | | | 1200.00 |
| E PNT98000 PAINT WORK ON FRT BUMPER PANEL | | | | | | | | 700.00 |
| E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR | | | | | | | | 120.00 |
| M SUNDRY TO TOP UP AIRCON GAS | | | | | | | | 80.00 |
| A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM | | | | | | | | 30.00 |
| A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | | | | | | | | 120.00 |
| M SUNDRY TO SUPPLY FRONT NUMBER PLATE WITH FRAME | | | | | | | | 50.00 |
| M SUNDRY SUNDRIES | | | | | | | | 50.00 |
| M | LAMP ASSY-HEAD,RH | | | | 1.00 | 2210.00 | 20.00 | 1768.00 |
| M | CARRIER ASSY-FRONT END MODULE | | | | 1.00 | 675.00 | 20.00 | 540.00 |
| M | BEAM COMPLETE-FR BUMPER | | | | 1.00 | 497.00 | 20.00 | 397.60 |
| M | COVER-FR BUMPER | | | | 1.00 | 633.00 | 20.00 | 506.40 |
| M | GRILLE-FRONT BUMPER | | | | 1.00 | 485.00 | 20.00 | 388.00 |
| M | COVER-FR BUMPER FOG LAMP,RH | | | | 1.00 | 15.00 | 20.00 | 12.00 |
| M | LAMP ASSY-FRONT FOG,RH | | | | 1.00 | 303.00 | 20.00 | 242.40 |
| M | MOULDING-FRONT BUMPER,RH | | | | 1.00 | 216.00 | 20.00 | 172.80 |
| M | LAMP ASSY-SIDE REPEATER,RH | | | | 1.00 | 143.00 | 20.00 | 114.40 |
| M | AIR DUCT-FR BUMPER,RH | | | | 1.00 | 14.00 | 20.00 | 11.20 |
| M | ABSORBER-FRONT BUMPER ENERGY | | | | 1.00 | 84.00 | 20.00 | 67.20 |
| M | STIFFNER-FR BPR LWR | | | | 1.00 | 114.00 | 20.00 | 91.20 |
| M | BRACKET-FR BUMPER UPR SIDE MTG | | | | 1.00 | 22.00 | 20.00 | 17.60 |
| M | GRILLE ASSY-RADIATOR | | | | 1.00 | 328.00 | 20.00 | 262.40 |
| M | GARNISH-RADIATOR GRILLE | | | | 1.00 | 38.00 | 20.00 | 30.40 |
| M | WIRING ASSY-BUMPER EXTENSION | | | | 1.00 | 207.00 | 20.00 | 165.60 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---------------------------|------------------------------------|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 | Cust No/Name | LCV11495/KAMSANI BIN JANTAN |
| | Reg No/Reg Date | SMQ3930C / 14/11/201 |
| | Date In/Mileage | 26/01/2021/ 0 |
| | Chassis No | KNAF5416MK5051851 |
| | Engine No | G4FGKH748537 |
| | Make/Model | KIA/CERATO 1.6 A GT LINE H171 |
| | Colour/Trim | ABP AURORA BLACK / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---------------------------------|------------|-------------------|------------|-------------------|--------|------------|-------|--------|
| LAX00000 | Credit | 26/01/2021/ 12:27 | QUK | 282 / Kevin Leong | 28077 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| M | ULTRASONIC | SENSOR | ASSY-P.A.S | | 1.00 | 163.00 | 20.00 | 130.40 |
| M | ULTRASONIC | SENSOR | ASSY-P.A.S | | 1.00 | 163.00 | 20.00 | 130.40 |

Estimate

Confirm & accepted by

| | | |
|----------------------|----------------|-----------------|
| | Nett | 7,398.00 |
| 7% GST on | 7398.00 | 517.86 |
| Total Payable | | 7,915.86 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.