

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21001242/NVF3E2

**Date:** 04/05/2021

### REFERENCE

Insured/Claimant:	KOH CHERN HUA EUGENE	Policy No:	2070135064	
Date of Loss:	14/01/2021	Nature of Claim:	OD	Claim No: 6635141741SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR898H	Engine No:	H336E0092028
Make & Model:	YAMAHA CZD300A / XMAX300, 292cc	Chassis No:	MH3SH084XLK012448
Reg. Date:	15/09/2020 (Man. Year: 2020)	Odometer:	6791 km
Colour:	Black		
Engine Capacity:	292 cc		
Market Value/New Car Price:	S\$21,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	120/70 R15	Rear Tyre Size:	140/70 R14
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,557.10	6,084.60	2,472.50	28.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	1,080.00	1,100.00	50.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,737.10</b>	<b>7,164.60</b>	<b>3,572.50</b>	<b>33.27</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,750.00</b>		
<b>- Excess (\$\$)</b>	300.00	300.00	0.00	0.00
<b>(\$\$)</b>	10,437.10	5,450.00	4,987.10	47.78
<b>+ GST 7.00/7.00% (\$\$)</b>	730.60	381.50	349.10	47.78
<b>Nett Amount (\$\$)</b>	<b>11,167.70</b>	<b>5,831.50</b>	<b>5,336.20</b>	<b>47.78</b>

### INSPECTION

Date of Assignment:	26/01/2021		
Date Inspected:	04/02/2021	Inspected At:	Bike Production (HQ) No 610 Serangoon Road Singapore 218216
Estimated Period of Repair:	4.0 days		

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Deformed	140.00 FL	*140.00 FL
2	1		*RIGHT FRONT FORK	Bent	820.00 FL	*750.00 FL
3	1		*LEFT FRONT FORK	Bent	820.00 FL	*750.00 FL
4	1		*FRONT WHEEL SHAFT	Bent	95.00 FL	*95.00 FL
5	1		*FRONT BRAKE DISK	Serviceable	275.00 FL	*- FL
6	1		*STEERING STEM	Serviceable	255.00 FL	*- FL
7	2		*STEERING STEM BEARINGS	Necessary	90.00 FL	*90.00 FL
8	1		*CENTRE BODY INNER COVER	Cracked	195.00 FL	*150.00 FL
9	1		*BLACK FRONT UPPER COVER	Cracked	145.00 FL	*145.00 FL
10	1		*BLACK FRONT LOWER COVER	Cracked	135.00 FL	*135.00 FL
11	1		*RIGHT BRAKE LEVER	Scratched	65.00 FL	*65.00 FL
12	1		*LEFT BRAKE LEVER	Serviceable	65.00 FL	*- FL
13	1		*LEFT BALANCER	Serviceable	45.00 FL	*- FL
14	1		*HANDLE BAR	Bent	185.00 FL	*150.00 FL
15	1		*LEFT FAIRING	Cracked	145.00 FL	*145.00 FL
16	1		*RIGHT FAIRING	Cracked	145.00 FL	*145.00 FL
17	1		*LEFT VIEW MIRROR	Deformed	125.00 FL	*125.00 FL
18	1		*RIGHT VIEW MIRROR	Deformed	125.00 FL	*125.00 FL
19	2		*YAMAHA EMBLEM	Necessary	90.00 FL	*60.00 FL
20	1		*LOWER LEFT COVER	Deformed	135.00 FL	*135.00 FL
21	1		*LOWER RIGHT COVER	Deformed	135.00 FL	*135.00 FL
22	1		*BELLY PAN	Cracked	155.00 FL	*155.00 FL
23	1		*FRONT WINDSHIELD ASSY	Missing	145.00 FL	*145.00 FL
24	1		*RIGHT BOX HOLDER ASSY	Deformed	195.00 FL	*180.00 FL
25	1		*RADIATOR ASSY	Deformed	475.00 FL	*450.00 FL
26	1		*RIGHT LOWER COVER	Serviceable	145.00 FL	*- FL
27	1		*RIGHT FLOOR STEP	Scratched	135.00 FL	*135.00 FL
28	1		*LEFT FLOOR STEP	Deformed	135.00 FL	*135.00 FL
29	1		*CENTER INNER COVER	Deformed	185.00 FL	*160.00 FL
30	1		*FRONT SPORT RIM	Serviceable	650.00 FS	*- FS
31	1		*RADIATOR FAN ASSY (Supplementary)	Jammed	120.00 FL	*120.00 FL
32	1		*CENTER V COVER (Supplementary)	Cracked	75.00 FL	*75.00 FL
33	1		*HEADLAMP ASSY (Supplementary)	Cracked	485.00 FL	*450.00 FL
34	1		*HEADLAMP LOWER COVER (Supplementary)	Deformed	75.00 FL	*75.00 FL
35	1		*CENTER SMALL COVER (Supplementary)	Deformed	65.00 FL	*65.00 FL
36	1		*HEADLAMP BRACKET (Supplementary)	Bent	255.00 FL	*255.00 FL
37	2		*RIGHT SIDE SMALL COVER (Supplementary)	Deformed	85.00 FL	*85.00 FL
38	1		*FRONT MUDGUARD LEFT COVER (Supplementary)	Cracked	65.00 FL	*65.00 FL
39	1		*LEFT WINDSHIELD BRACKET (Supplementary)	Bent	85.00 FL	*85.00 FL
40	4		*WINDSHIELD SCREW (Supplementary)	Necessary	28.00 FL	*28.00 FL
41	1		*RIGHT BALANCER (Supplementary)	Scratched	45.00 FL	*45.00 FL
42	1		*EXHAUST HEAT SHIELD (Supplementary)	Scratched	95.00 FL	*95.00 FL
43	1		*EXHAUST ASSY (Supplementary)	Serviceable	580.00 FL	*- FL
44	1		*EXHAUST REAR COVER (Supplementary)	Scratched	95.00 FL	*95.00 FL
45	1		*LEFT POCKET ASSY (Supplementary)	Deformed	195.00 FL	*180.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	2		<b>*WINDSHIELD COVER</b> (Supplementary)	Missing	76.00 FL	*76.00 FL
47	2		<b>*FASTENER</b> (Supplementary)	Necessary	20.00 FL	*20.00 FL
48	1		<b>*FRONT RIGHT SIGNAL</b> (Supplementary)	Missing	125.00 FL	*125.00 FL
49	1		<b>*RIGHT POCKET CLAMP</b> (Supplementary)	Missing	55.00 FL	*55.00 FL
50	1		<b>*RIGHT SWITCH ASSY</b> (Supplementary)	Serviceable	275.00 FL	*- FL
51	1		<b>*REAR NUMBER PLATE</b> (Supplementary)	Bent	30.00 FS	*30.00 FS
52	1		<b>*LOT COOLANT</b> (Supplementary)	Necessary	48.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,427.00</b>	<b>6,754.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	869.90	669.40
<b>Total Parts (\$\$)</b>	<b>8,557.10</b>	<b>6,084.60</b>

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	<b>TOWING CHARGES</b> (Seperate claim)	New	120.00	0.00
2	<b>REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM</b>	New	700.00	600.00
3	<b>TO REPLACE AND BALANCE FRONT WHEEL RIM</b>	New	150.00	0.00
4	<b>TO KNOCK, STRAIGHTEN CHASSIS &amp; BODY BALANCING</b>	New	380.00	0.00
5	<b>RESET METER</b>	New	120.00	50.00
6	<b>TO REPLACE AND REFIT AND ALIGN FRONT FORKS</b>	New	180.00	180.00
7	<b>SPRAY PAINTING</b>	New	350.00	250.00
8	<b>LABOUR FOR DISMANTLING AND ASSEMBLY SUPPLEMENTARY ITEMS</b> (Supplementary)	New	180.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,180.00</b>	<b>1,080.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >