

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21001246/UGA3Q2
Date: 10/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900113325
Claimant Vehicle No :	FBN5682B	Insured Vehicle No :	SMM3900K
Date of Loss:	16/01/2021	Nature of Claim:	TP
		Claim No:	2539673461SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN5682B	Engine No:	SK80C1600118
Make & Model:	KYMCO XCITING 400I, 399cc	Chassis No:	RFBD62000J1600113
Reg. Date:	03/11/2018 (Man. Year: 2018)	Odometer:	35641 km
Colour:	Blue		
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120/70 R15	Rear Tyre Size:	150/70 R14
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,210.80	5,615.40	7,595.40	57.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	700.00	430.00	38.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,340.80	6,315.40	8,025.40	55.96
Approved Total (Overridden) (S\$)		5,000.00		

Nett Amount (S\$)	14,340.80	5,000.00	9,340.80	65.13
+ Loss of Use (7.0 x S\$20.00/day) (S\$)		140.00		
Nett Liability (S\$)		5,140.00		

INSPECTION

Date of Assignment: 26/01/2021

Date Inspected: 27/01/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WINDSHIELD	Scratched	245.00 FL	*245.00 FL
2	1		*WINDSHIELD INNER COWLING	Cracked	280.00 FL	*250.00 FL
3	1		*FRONT COLWING -L/R/H	N/S Broken	480.00 FL	*240.00 FL
4	1		*METER OUTER MOULDING	Cracked	360.00 FL	*360.00 FL
5	1		*HEADLAMP ASSY	Cracked	1,050.00 FL	*825.00 FL
6	1		*FRONT INNER COWLING -L/R/H	N/S Cut	440.00 FL	*205.00 FL
7	1		*FRONT FENDER	Serviceable	180.00 FL	*- FL
8	1		*FRONT FORK ASSY	Serviceable	2,040.00 FL	*- FL
9	1		*FRONT RIM	Not Necessary	380.00 FL	*- FL
10	1		*FRONT RIM SHAFT	Not Necessary	68.00 FL	*- FL
11	1		*FRONT RIM BEARING	Not Necessary	45.00 FL	*- FL
12	2		*FRONT BRAKE DISC -L/R/H	Not Necessary	680.00 FL	*- FL
13	1		*LOWER SIDE COWLING BLUE -L/R/H	N/S Cut	430.00 FL	*215.00 FL
14	1		*LOWER SIDE COWLING MATT BLACK -L/R/H	N/S Cut	430.00 FL	*190.00 FL
15	1		*FOOTSTEP PANEL -L/H	Cut	185.00 FL	*165.00 FL
16	1		*BRAKE LEVER (LH)	Cracked	180.00 FL	*85.00 FL
17	2		*SET SIDE MIRROR	Cut	480.00 FL	*360.00 FL
18	1		*HANDLE -BAR	Serviceable	210.00 FL	*- FL
19	2		*HANDLE -BAR BALANCER	Not Necessary	48.00 FL	*- FL
20	2		*HAND GRIP	Not Necessary	58.00 FL	*- FL
21	1		*SIDE STAND	Cut	48.00 FL	*48.00 FL
22	1		*MAIN STAND	Cut	158.00 FL	*158.00 FL
23	2		*REAR SIDE COVER -L/R/H	Cut	520.00 FL	*520.00 FL
24	2		*REAR FOOTREST	Serviceable	220.00 FL	*- FL
25	1		*AIR FILTER	Not Necessary	360.00 FL	*- FL
26	1		*AIR FILTER BOX COVER	Cut	180.00 FL	*180.00 FL
27	1		*DROVE BELT COVER	Cut	470.00 FL	*470.00 FL
28	1		*REAR HANDLE -L/R/H	N/S Cut	530.00 FL	*225.00 FL
29	1		*EXHAUST ASSY	Repair	1,780.00 FL	*- FL
30	1		*EXHAUST PROTECTOR -FRONT	Distorted	63.00 FL	*63.00 FL
31	1		*EXHAUST COVER CENTRE	Distorted	86.00 FL	*86.00 FL
32	1		*EXHAUST END CAP COVER	Cut	58.00 FL	*58.00 FL
33	1		*COMPARTMENT BOX (FRT)	Cracked	580.00 FL	*578.00 FL
34	1		*LOWER BELLY PANEL -R/H	Cut	370.00 FL	*280.00 FL
35	1		*SET NUMBER PLATE (FRT)	Scratched	28.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*FORK OIL	Not Necessary	30.00 FS	*- FS
37	2		*FORK OIL SEAT	Not Necessary	75.00 FS	*- FS
38	1		*SET STEERING CONE	Not Necessary	185.00 FS	*- FS
39	1		*REAR BOX	Cut	420.00 FS	*380.00 FS
40	1		*REAR BOX BRACKET	Serviceable	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,580.00	6,196.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,369.20	580.60
Total Parts (S\$)	13,210.80	5,615.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE (LOD)	New	50.00	50.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO SPRAY PAINT	New	480.00	350.00
4	TO PRIVIDE LABOUR	New	520.00	300.00
Gross Labour Cost (\$\$)			1,130.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >