

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21001247/UPS3Q2
Date: 09/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070153174
Claimant Vehicle No :	YN3366E	Insured Vehicle No :	GBD8643Y
Date of Loss:	24/01/2021	Nature of Claim:	TP
		Claim No:	1218332334SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN3366E	Engine No:	4M42A91253
Make & Model:	MITSUBISHI FE83BE6SRDEA, 3.0 D (A)	Chassis No:	FE83BEA20920
Reg. Date:	10/12/2012 (Man. Year: 2012)	Odometer:	404318 km
Colour:	White		
Engine Capacity:	2977 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	7.00 R16	Rear Tyre Size:	7.00 R16 (D)
Front Left Side:	OHTSU 6 mm	Rear Left Side:	OHTSU 6/6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	OHTSU 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,190.00	6,310.00	8,880.00	58.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,200.00	1,580.00	56.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,970.00	7,510.00	10,460.00	58.21
Approved Total (Overridden) (S\$)		6,000.00		

(S\$)	17,970.00	6,000.00	11,970.00	66.61
+ GST 7.00/7.00% (S\$)	1,257.90	420.00	837.90	66.61
Nett Amount (S\$)	19,227.90	6,420.00	12,807.90	66.61
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,022.00		
Global Sum Settlement (S\$)		7,000.00		

INSPECTION

Date of Assignment: 26/01/2021

Date Inspected: 26/01/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE WOODEN	Cracked	3,800.00 FS	*2,000.00 FS
2	2		*REAR TAILGATE WOODEN BRACKETS	Bent	500.00 FS	*400.00 FS
3	1		*REAR TAILGATE WOODEN STEEL PLATE	Repair	800.00 FS	*- FS
4	1		*SET REAR TAILGATE 60KM/H & 24 PAX STICKER	Necessary	20.00 FS	*20.00 FS
5	1		*SET REAR TAILGATE WOODEN COMPANY STICKER	Necessary	680.00 FS	*400.00 FS
6	1		*REAR TAILGATE LOWER WOODEN	Serviceable	1,200.00 FS	*- FS
7	1		*TAILLAMP N/S	Cracked	190.00 FS	*190.00 FS
8	1		*REAR STEP WOODEN CENTRE	Cracked	1,000.00 FS	*500.00 FS
9	1		*REAR CHASSIS WOODEN N/S	Cracked	3,200.00 FS	*2,000.00 FS
10	1		*REAR CHASSIS WOODEN BRACKET N/S	Serviceable	500.00 FS	*- FS
11	1		*REAR STEP LOWER BRACKET	Bent	1,500.00 FS	*800.00 FS
12	1		*REAR SAFETY BAR	Not Necessary	1,800.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)
15,190.00
6,310.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	50.00	0.00
3	TO LIFT UP CARGO DECK FOR REPLACED CHASSIS WOODEN }	New	800.00	800.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS }	New	1,200.00	0.00
5	TO PUTTY & SPRAY PAINTING	New	680.00	380.00
Gross Labour Cost (S\$)			2,780.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >