

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21001251/ABA3Q2  
**Date:** 19/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700016379
<b>Claimant Vehicle No :</b>	SLH2161X	<b>Insured Vehicle No :</b>	SLP6864H
Date of Loss:	25/01/2021	Nature of Claim:	TP
		Claim No:	1247751643SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLH2161X</b>	Engine No:	CNC176494
Make & Model:	AUDI Q5, 2.0 (A)	Chassis No:	WAUZZZ8R1HA041311
Reg. Date:	26/10/2016 (Man. Year: 2016)	Odometer:	79714 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,846.00	11,558.40	8,287.60	41.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,172.00	6,942.00	8,230.00	54.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>35,018.00</b>	<b>18,500.40</b>	<b>16,517.60</b>	<b>47.17</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,451.26</b>	<b>1,295.03</b>	<b>1,156.23</b>	<b>47.17</b>

<b>Nett Amount (S\$)</b>	<b>37,469.26</b>	<b>19,795.43</b>	<b>17,673.83</b>	<b>47.17</b>
<b>+ Loss of Use (8.0 x S\$100.00/day) (S\$)</b>		800.00		
<b>Nett Liability (S\$)</b>		<b>20,595.43</b>		

INSPECTION

Date of Assignment: 26/01/2021

Date Inspected: 26/01/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Premium Automobiles Pte Ltd (HQ)  
55 UBI ROAD 1  
Singapore 408699**Adjuster:** ADRIAN LING**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER -RH	Dented	1,002.00 FS	*801.60 FS
2	1		*FRONT FENDER ATTACHMENT PARTS-RH	Not Necessary	67.00 FS	*- FS
3	1		*FRONT FENDER BRACE -RH	Not Necessary	88.00 FS	*- FS
4	1		*FRONT FENDER CLOSING ELEMENT -RH	Not Necessary	105.00 FS	*- FS
5	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	264.00 FS	*- FS
6	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	104.00 FS	*- FS
7	1		*FRONT DOOR -RH	Dented	4,085.00 FS	*3,268.00 FS
8	1		*FRONT DOOR OUTER SEAL -RH OUTER	Necessary	205.00 FS	*164.00 FS
9	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
10	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
11	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
12	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	129.00 FS	*- FS
13	1		*FRONT DOOR CATCH -RH	Not Necessary	146.00 FS	*- FS
14	1		*FRONT DATE PLATE FOR TYRE PRESSURE	Necessary	30.00 FS	*24.00 FS
15	1		*FRONT DOOR HINGE-RH UPPER /LOWER	Not Necessary	150.00 FS	*- FS
16	1		*FRONT DOOR COVER -RH	Necessary	511.00 FS	*408.80 FS
17	1		*REAR DOOR	Deformed	4,085.00 FS	*3,268.00 FS
18	1		*REAR DOOR OUTER SEAL-RH	Necessary	205.00 FS	*164.00 FS
19	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
20	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
21	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
22	1		*STONE CHIP PROTECTION FILM -RH INNER	Necessary	78.00 FS	*62.16 FS
23	1		*REAR DOOR ATTACHMENT PARTS-RH	Not Necessary	124.00 FS	*- FS
24	1		*REAR DOOR CATCH -RH	Damaged	146.00 FS	*116.40 FS
25	1		*REAR SILL PANEL SEAL -RH	Not Necessary	222.00 FS	*- FS
26	1		*REAR DOOR SEAL INNER -RH	Not Necessary	205.00 FS	*- FS
27	1		*REAR DOOR COVER -RH	Necessary	409.00 FS	*326.80 FS
28	1		*REAR WHEEL HOUSING LINER-RH	Not Necessary	264.00 FS	*- FS
29	1		*REAR BUMPER	Torn	1,798.00 FS	*1,438.40 FS
30	1		*REAR BUMPER FIXING PARTS	Not Necessary	166.00 FS	*- FS
31	1		*REAR BUMPER SPOILER	Not Necessary	866.00 FS	*- FS
32	1		*REAR BUMPER GUIDE SECTION -RH	Not Necessary	54.00 FS	*- FS
33	1		*TAIL LIGHT -RH	Not Necessary	299.00 FS	*- FS
34	1		*FRONT ALUMINIUM RIM -RH	Not Necessary	1,652.00 FS	*- FS
35	1		*REAR ALUMINIUM RIM -RH	Cut	1,652.00 FS	*1,321.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
36	1		<b>*SUNDRIES</b>	Necessary	300.00 FS	*47.04 FS	
37	1		<b>*FRONT FENDER LINING -RH</b>	Deformed	185.00 FS	*147.60 FS	
					<b>Total Parts (\$)</b>	<b>19,846.00</b>	<b>11,558.40</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS ,OUTSIDE TEMPERA TURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	800.00	500.00
3	TO DISMANTLE FRONT BUMPER ,RHS FRONT FENDER ,RHS FRONT DOOR AND RHS REAR DOOR .TO RENEW RHS FRONT FENDER ,RHS FRONT DOOR AND RHS REAR DOOR .TO REPAIR RHS REAR FENDER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	4,400.00	2,000.00
4	TO RESPRAY RHS FRONT FENDER ,RHS FRONT DOOR ,RHS REAR DOOR ,DOOR COVERS ,DOOR HANDLES ,RHS REAR FENDER	New	5,100.00	2,600.00
5	TO REMOVE AND REINSTALL REAR PARKING AID CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
6	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
7	TO RESPRAY REAR BUMPER AND REAR BUMPER SPOILER	New	2,400.00	550.00
8	TO RENEW RHS FRONT RIM AND RHS REAR RIM .TO CARRY OUT WHEEL ALIGNMENT	New	320.00	320.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>15,172.00</b>	<b>6,942.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >