

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI21001257/KTF3Q2
Date: 31/03/2021

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No: ML000183	
Claimant Vehicle No : SMX4062P	Insured Vehicle No : GBD8221G	
Date of Loss: 21/01/2021	Nature of Claim: TP	Claim No: M2100440

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX4062P	Engine No:	2ZR2G79410
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU703091409
Reg. Date:	11/01/2021 (Man. Year: 2020)	Odometer:	1215 km
Colour:	Metallic Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Dunlop 9 mm	Rear Left Side:	Dunlop 9 mm
Front Right Side:	Dunlop 9 mm	Rear Right Side:	Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,453.60	2,611.30	1,842.30	41.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	1,300.00	2,290.00	63.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,043.60	3,911.30	4,132.30	51.37
+ GST 7.00/7.00% (S\$)	563.05	273.79	289.26	51.37
Nett Amount (S\$)	8,606.65	4,185.09	4,421.56	51.37

INSPECTION

Date of Assignment:	27/01/2021	
Date Inspected:	25/01/2021	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2021)
Parts: 144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX4062P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Reference	Amount
1	1	*FRONT FENDER EMBLEM LH	Serviceable	54.60 FL	-	*- FL
2	1	*COVER SUB-ASSY,FRONT PILLAR,UPR LH	Burnt	100.40 FL	-	*100.40 FL
3	1	*MIRROR ASSY-OUTER REAR VIEW,LH	Burnt	1,339.30 FL	-	*1,339.30 FL
4	1	*MOULDING,FRONT DOOR WINDOW FRAME,FRONT LH	Burnt	38.60 FL	-	*38.60 FL
5	1	*MOULDING,FRONT DOOR WINDOW FRAME,REAR LH	Burnt	56.50 FL	-	*56.50 FL
6	1	*MOULDING,FRONT DOOR WINDOW FRAME,REAR RH	Burnt	56.50 FL	-	*56.50 FL
7	1	*MOULDING ASSY,FRONT DOOR BELT,LH	Burnt	92.00 FL	-	*92.00 FL
8	1	*MOULDING ASSY,FRONT DOOR BELT,LH	Repeated	92.00 FL	-	*- FL
9	1	*WEATHERSTRIP,FRONT DOOR FIX WINDOW,LH	Serviceable	76.40 FL	-	*- FL
10	1	*HANDLE ASSY,FRONT DOOR OUTSIDE,LH	Serviceable	390.60 FL	-	*- FL
11	1	*MOULDING,REAR DOOR WINDOW FRAME,REAR LH	Burnt	38.60 FL	-	*38.60 FL
12	1	*MOULDING,REAR DOOR WINDOW FRAME,FRONT LH	Burnt	56.50 FL	-	*56.50 FL
13	1	*MOULDING,REAR DOOR WINDOW FRAME,FRONT RH	Burnt	56.50 FL	-	*56.50 FL
14	1	*MOULDING ASSY,REAR DOOR BELT,LH	Burnt	113.50 FL	-	*113.50 FL
15	1	*MOULDING ASSY,REAR DOOR BELT,LH	Repeated	113.50 FL	-	*- FL
16	1	*WEATHERSTRIP,REAR DOOR QUARTER WINDOW,LH	Serviceable	49.30 FL	-	*- FL
17	1	*HANDLE ASSY,REAR DOOR OUTSIDE,LH	Serviceable	97.40 FL	-	*- FL
18	1	*MOULDING ASSY,BODY ROCKER PANEL,LH	Burnt	594.80 FL	-	*594.80 FL
19	1	*MOULDING,REAR DOOR WINDOW FRAME,REAR LH	Serviceable	38.60 FL	-	*- FL
20	1	*LENS & BODY ,REAR COMBINATION LAMP ,LH	Burnt	339.60 FL	-	*339.60 FL
21	1	*COVER ,REAR BUMPER	Burnt	485.60 FL	-	*485.60 FL
22	1	*FENDER CLIP	Not Necessary	65.00 FS	-	*- FS
23	1	*FENDER LINER CLIP	Not Necessary	65.00 FS	-	*- FS
24	1	*FRT BUMPER CLIP	Not Necessary	65.00 FS	-	*- FS
25	1	*SEAM SEALANT	Not Necessary	200.00 FS	-	*- FS
26	1	*TAIL LAMP CLIP	Necessary	70.00 FS	-	*20.00 FS
27	1	*FRONT PILLAR GARNISH CLIP	Not Necessary	60.00 FS	-	*- FS
28	2	*SET DOOR WEATHERSTRIP CLIP	Not Necessary	130.00 FS	-	*- FS
29	1	*FRT DOOR STICKER TRANSCAB	Not Necessary	100.00 FS	-	*- FS
30	1	*HUB CAP	Serviceable	423.00 FS	-	*- FS
31	1	*SET CLIP ,ROCKER PANEL MOULDING	Necessary	65.00 FS	-	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,523.80	3,453.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,070.20	842.10
Total Parts (\$\$)	4,453.60	2,611.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,400.00	400.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	880.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (S\$)			3,590.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >