

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001258/EQF3E2

Date: 21/04/2021

REFERENCE

Insured/Claimant:	WEN DECHANG WAYNE	Policy No:	1900085689		
Date of Loss:	26/01/2021	Nature of Claim:	OD	Claim No:	2615772416SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK6066J		
Make & Model:	CITROEN C4, 1.2 1.2 PURETECH EAT6 (A)	Engine No:	10XTA41128501
Reg. Date:	17/04/2019 (Man. Year: 2018)	Chassis No:	VF73AHNYTJJ789406
Colour:	Red	Odometer:	0 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	S\$92,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,199.60	11,040.80	3,158.80	22.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,135.00	5,915.00	3,220.00	35.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,334.60	16,955.80	6,378.80	27.34
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	23,034.60	16,655.80	6,378.80	27.69
+ GST 7.00/7.00% (S\$)	1,612.42	1,165.91	446.51	27.69
Nett Amount (S\$)	24,647.02	17,821.71	6,825.31	27.69

INSPECTION

Date of Assignment: 27/01/2021

Date Inspected: 26/01/2021 Inspected At:

Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)
209 PANDAN GARDENS
Singapore 609339

Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
2	1		*FRONT BUMPER	Broken	1,022.00 FL	*1,022.00 FL
3	1		*BUMPER BRACKET	Broken	327.00 FL	*327.00 FL
4	1		*BUMPER MOULDING	Broken	206.00 FL	*206.00 FL
5	1		*BUMPER MOULDING	Broken	206.00 FL	*206.00 FL
6	1		*BUMPER MOULDING	Necessary	225.00 FL	*225.00 FL
7	1		*BMPR RUBBR BOOT	Broken	274.00 FL	*274.00 FL
8	1		*GUARD GRILLE INFERIEUR	Broken	308.00 FL	*308.00 FL
9	1		*BADGE SUPPORT	Broken	203.00 FL	*203.00 FL
10	1		*CHEVRON EMBLEM SUPERIEUR	Cut	147.00 FL	*147.00 FL
11	1		*CHEVRON EMBLEM INFERIEUR	Cut	147.00 FL	*147.00 FL
12	1		*SET BRACKET	Broken	124.00 FL	*124.00 FL
13	1		*BUMPER MOULDING	Not Necessary	171.00 FL	*- FL
14	1		*BRACKET SET LAT	Broken	124.00 FL	*124.00 FL
15	1		*SET ABSORBERS	Not Necessary	91.00 FL	*- FL
16	1		*BUMPER BRACKET	Bent	511.00 FL	*511.00 FL
17	1		*BUMPER BRACKET	Broken	192.00 FL	*192.00 FL
18	1		*PLUG LH	Not Necessary	95.00 FL	*- FL
19	1		*REAR DUCT RH	Broken	118.00 FL	*118.00 FL
20	1		*REPAIR SET	Not Necessary	92.00 FL	*- FL
21	1		*FACE CROSSMEMBER SUP	Broken	224.00 FL	*224.00 FL
22	1		*FACE CROSSMEMBER INF ASS	Not Necessary	80.00 FL	*- FL
23	1		*AIR BULKHEAD LH	Not Necessary	107.00 FL	*- FL
24	1		*AIR BULKHEAD RH	Crushed	107.00 FL	*107.00 FL
25	1		*AIR BULKHEAD	Broken	152.00 FL	*152.00 FL
26	1		*BRACKET CROSSME LH ASS	Bent	64.00 FL	*64.00 FL
27	1		*BRACKET CROSSME RH ASS	Bent	65.00 FL	*65.00 FL
28	1		*FACING SUPPORT LH ASS	Not Necessary	98.00 FL	*- FL
29	1		*FACING SUPPORT RH ASS	Not Necessary	80.00 FL	*- FL
30	1		*FR MIN BPR FIX	Necessary	250.00 FL	*250.00 FL
31	1		*FRONT WING LH ASS	Repair	566.00 FL	*- FL
32	1		*FRONT WING RH ASS	Dented	566.00 FL	*566.00 FL
33	1		*MUDGUARD LH ASS	Not Necessary	192.00 FL	*- FL
34	1		*MUDGUARD RH ASS	Not Necessary	157.00 FL	*- FL
35	1		*ENGINE BONNET ASS	Dented	1,033.00 FL	*1,033.00 FL
36	1		*BONNET HINGE LH	Not Necessary	80.00 FL	*- FL
37	1		*BONNET HINGE RH	Not Necessary	117.00 FL	*- FL
38	1		*SOUND PROOFING	Crushed	233.00 FL	*233.00 FL
39	1		*BONNET LOCK	Not Necessary	54.00 FL	*- FL
40	1		*LOCKING HOOK	Not Necessary	50.00 FL	*- FL
41	1		*SPACETOURER 2018 - BODY KIT (NPA)	Not Necessary	0.00 FL	*- FL
42	1		*FRONT LIGHT LH	Not Necessary	405.00 FL	*- FL
43	1		*FRONT LIGHT RH	Not Necessary	405.00 FL	*- FL
44	1		*HEADLIGHT ASSY LH	Broken	712.00 FL	*712.00 FL
45	1		*HEADLIGHT ASSY RH	Broken	712.00 FL	*712.00 FL
46	1		*RADIATOR NEW	Bent	680.00 FL	*680.00 FL
47	1		*FIXING BRACKET	Necessary	19.00 FL	*19.00 FL
48	1		*FIXING BRACKET	Necessary	21.00 FL	*21.00 FL
49	1		*FAN CONTROL	Not Necessary	149.00 FL	*- FL
50	1		*DISTRIB CHAMBER	Not Necessary	833.00 FL	*- FL
51	1		*DIST CHB BRACKT	Not Necessary	43.00 FL	*- FL
52	1		*CONDENSER	Bent	1,165.00 FL	*1,165.00 FL
53	1		*CONDENS BRACKET	Broken	57.00 FL	*57.00 FL
54	1		*COND DEFLECTOR	Not Necessary	71.00 FL	*- FL
55	1		*HEAT SHIELD PARTIE AV	Dented	51.00 FL	*51.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*DEFLECTOR (Supplementary)	Broken	97.00 FL	*97.00 FL
57	1		*BUMPER DEFLECTOR (Supplementary)	Broken	171.00 FL	*171.00 FL
58	1		*FIXING CLAMP DIAM 90 (Supplementary)	Necessary	117.00 FL	*117.00 FL
59	1		*FREON TUBE 3MM (Supplementary)	Bent	329.00 FL	*329.00 FL
60	1		*CATALYST MUFFLR TR PSA K675 (Supplementary)	Bent	2,370.00 FL	*2,370.00 FL
61	1		*FREON TUBE (Supplementary)	Bent	220.00 FL	*220.00 FL
62	1		*FREON TUBE (Supplementary)	Bent	179.00 FL	*179.00 FL
63	2		*COOLING LIQUID DRUM 2L PAE-35 (Supplementary)	Necessary	48.00 FL	*48.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,742.00	13,796.00
- List Item Discount on L Items 20.00/20.00% (\$)	3,542.40	2,755.20
Total Parts (\$)	14,199.60	11,040.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT SUPPORT, BONNET, LHF FENDER & RHF FENDER. REPAIR RHF WHEELHOUSE & RHF DOOR	New	4,000.00	2,000.00
2	RESPRAY FRT BUMPER, FRT SUPPORT, BONNET, LHF FENDER, RHF FENDER, RHF WHEELHOUSE, RHF DOOR & FRT BUMPER BODY KIT	New	3,040.00	1,900.00
3	RENEW AC CONDENSER & RADIATOR	New	100.00	100.00
4	TOP UP AIRCON GAS	New	550.00	550.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	50.00	50.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	225.00	225.00
7	SUPPLY FRT NUMBER PLATE WITH CASING	New	50.00	50.00
8	REMOVE & REFIT FRT PARKING ASSIST SENSOR	New	80.00	80.00
9	SUPPLY FRT PARKING ASSIST SENSOR	New	380.00	380.00
10	APPLY ANTI CORROSION ON AFFECTED AREA	New	80.00	40.00
11	SUPPLY BODY PNL SEALANT	New	80.00	40.00
12	ENGINE MOTOR DRIVEN FAN (NPA)	New	0.00	0.00
13	RENEW TURBO CHARGER HEATSHIELD, EXHAUST CATALYST MUFFLER AND AIRCON FREON TUBE (Supplementary)	New	500.00	500.00
Gross Labour Cost (\$\$)			9,135.00	5,915.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >