



CYCLE & CARRIAGE

AIG - OD CLAIM
SURVEY: 26/01/21
LKK - STEVE

VEHICLE NO : SMK6066J

MODEL : CIT/GRAND C4 1.2 pupetech

WIP : 16144

Material	:	\$	<u>11,020.80</u>
Labour	:	\$	<u>5,935.00</u>
Sub-Total	:	\$	<u>16,955.80</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>16,655.80</u>
GST 7%	:	\$	<u>1,165.91</u>
Grand Total	:	\$	<u>17,821.71</u>
Finalise By/Date : <u>Amey on 15/03/21</u>			



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 10 WORKING DAYS + 4 days (2 wk ends)

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Cust No/Name /WEN DECHANG WAYNE Reg No/Reg Date SMK6066J / 17/04/2019 Date In/Mileage 28/01/2021/ 33780 Chassis/Package VF73AHNYTJJ789406 /CS5P Engine No 10XTA41128501 Make/Model CIT/GRAND C4 SPACETOURE 1.2 PURETECH 13 Colour/Trim PYM ROUGE RUBI / 8LP TISSU MILAZZO G



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No		
FA000001	Credit	12/03/2021/ 09:32	BLE	884 / Lauro Songcuan	16144	0		
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
RENEW FRONT BUMPER, FRONT SUPPORT, BONNET & RH FRONT FENDER, REPAIR LH FRONT FENDER & RH FRONT DOOR								
E PNT98000								1900.00
SPRAY PAINT FRONT BUMPER, BONNET, LH FRONT FENDER, RH FRONT FENDER AND RH FRONT DOOR								
A 25000001								550.00
VACUUM & TOP UP AIRCON GAS								
A 54900099								50.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								225.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
E PNT88000								80.00
REMOVE & REFIT FRONT PARKING ASSIST SENSOR								
M SUNDRY								40.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								40.00
SUPPLY BODY PANEL SEALANT								
M SUNDRY								20.00
SUNDRIES								
E PNT88000								100.00
RENEW AIRCON CONDENSER AND RADIATOR ASSY								
S SPECIALISTJOB								50.00
SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)								
A 33900099								500.00
RENEW TURBO CHARGER HEATSHIELD , EXHAUST CATALYST MUFFLER AND AIRCON FREON TUBE					1.00	1022.00	20.00	817.60
S SPECIALISTJOB								380.00
SUPPLY 4 PCS PARKING REVERSE SENSOR WITH INDICATOR (C4)								
X EXC								-300.00
EXCESS								
X FRONT BUMPER								

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

PRO-FORMA INVOICE

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

Invoice Name & Address

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #09-16
AIG BUILDING
SINGAPORE 079120
Contact No 6419 1000

Owner Name & Vehicle Info

Cust No/Name /WEN DECHANG WAYNE
Reg No/Reg Date SMK6066J / 17/04/2019
Date In/Mileage 28/01/2021/ 33780
Chassis/Package VF73AHNYTJJ789406 /CS5P
Engine No 10XTA41128501
Make/Model CIT/GRAND C4 SPACETOURER 1.2 PURETECH 13
Colour/Trim PYM ROUGE RUBI / 8LP TISSU MILAZZO G

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No	
PTAX00001	Credit	12/03/2021/ 09:32	BLE	884 / Lauro Songcuan	16144	0	
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	BUMPER BRACKET ✓			1.00	327.00	20.00	261.60 ✓
X	BUMPER MOULDING ✓			1.00	206.00	20.00	164.80 ✓
X	BUMPER MOULDING ✓			1.00	206.00	20.00	164.80 ✓
X	BUMPER MOULDING ✓			1.00	225.00	20.00	180.00 ✓
X	BMPR RUBBR BOOT ✓			1.00	274.00	20.00	219.20 ✓
X	GUARD GRILLE INFERIEUR ✓			1.00	308.00	20.00	246.40 ✓
X	BADGE SUPPORT ✓			1.00	203.00	20.00	162.40 ✓
X	CHEVRON EMBLEM SUPERIEUR ✓			1.00	147.00	20.00	117.60 ✓
X	CHEVRON EMBLEM INFERIEUR ✓			1.00	147.00	20.00	117.60 ✓
X	BRACKET SET ?			1.00	124.00	20.00	99.20
X	BRACKET SET LAT ✓			1.00	124.00	20.00	99.20 ✓
X	BUMPER BRACKET ✓			1.00	511.00	20.00	408.80 ✓
X	BUMPER BRACKET ?			1.00	192.00	20.00	153.60
X	FACE CROSSMEMBR SUP ✓			1.00	224.00	20.00	179.20 ✓
X	AIR BULKHEAD RH ✓			1.00	107.00	20.00	85.60 ✓
X	AIR BULKHEAD ✓			1.00	152.00	20.00	121.60 ✓
X	BRACKET CROSSME LH ASS ✓			1.00	64.00	20.00	51.20 ✓
X	BRACKET CROSSME RH ASS ✓			1.00	65.00	20.00	52.00 ✓
X	FR MIN BPR FIX ✓			1.00	250.00	20.00	200.00 ✓
X	FRONT WING RH ASS ✓			1.00	566.00	20.00	452.80 ✓
X	ENGINE BONNET ASS ✓			1.00	1033.00	20.00	826.40 ✓
X	SOUND PROOFING ✓			1.00	233.00	20.00	186.40 ✓
X	HEADLIGHT ASSY LH ?			1.00	712.00	20.00	569.60
X	HEADLIGHT ASSY RH ✓			1.00	712.00	20.00	569.60 ✓
X	RADIATOR NEW ✓			1.00	680.00	20.00	544.00 ✓
X	FIXING BRACKET ✓			1.00	19.00	20.00	15.20 ✓
X	FIXING BRACKET ✓			1.00	21.00	20.00	16.80 ✓
X	CONDENS BRACKET ✓			1.00	57.00	20.00	45.60 ✓
X	HEAT SHIELD PARTIE AV ✓			1.00	51.00	20.00	40.80 ✓
X	CONDENSER ✓			1.00	1165.00	20.00	932.00 ✓
X	DEFLECTOR → Supp			1.00	97.00	20.00	77.60
X	REAR DUCT RH ?			1.00	118.00	20.00	94.40
X	BUMPR DEFLECTOR → Supp			1.00	171.00	20.00	136.80

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Cust No/Name /WEN DECHANG WAYNE Reg No/Reg Date SMK6066J / 17/04/2019 Date In/Mileage 28/01/2021/ 33780 Chassis/Package VF73AHNYTJJ789406 /CS5P Engine No 10XTA41128501 Make/Model CIT/GRAND C4 SPACETOURE 1.2 PURETECH 13 Colour/Trim PYM ROUGE RUBI / 8LP TISSU MILAZZO G

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
PAF000001	Credit	12/03/2021/ 09:32	BLE	884 / Lauro Songcuan	16144	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X FIXING CLAMP DIAM 90	1.00	117.00	20.00	93.60 X
X FREON TUBE 3MM	1.00	329.00	20.00	263.20 X
X CATALYST MUFFLER TR PSA K675	1.00	2370.00	20.00	1896.00 X
X FREON TUBE	1.00	220.00	20.00	176.00 X
X FREON TUBE	1.00	179.00	20.00	143.20 X
X COOLING LIQUID DRUM 2L PAE -35	2.00	24.00	20.00	38.40 X
Z TEXT				
OD CLAIM - AIG				
SURVEY: STEVE (LKK) 27.01.2021				
DOA: 26.01.2021				
10 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	11,020.80	Nett	16,655.80
Labour	5,405.00	7% GST on	1165.91
Standard Menu	0.00		
Specialist Job	430.00	Total Payable	17,821.71
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	-200.00	Total Due	17,821.71
Total(w/o GST)	16,655.80		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMK 6066 J

<u>Materials</u>		<u>Cost \$</u>
1	Deflector	97.00 / BR
2	Bumper Deflector	171.00 / BR
3	Fixing Clamp Diam 90	117.00 / nec
4	Freon Tube 3mm	329.00 / BT
5	Catalyst Mufflr TR PSA K675	2,370.00 / BT
6	Freon Tube	220.00 / BT
7	Freon Tube	179.00 / BT
8	Cooling Liquid Drum 2L PAE- 35 (2 pcs)	48.00 / nec
		3,531.00
20% Discount		706.20
		2,824.80
<u>Labour</u>		
1	Renew Turbo Charger Heatshield, Exhaust Catalyst Muffler and Aircon Freon Tube	500.00 /
Labour & Materials		3,324.80
7% GST		232.74
Total		3,557.54

Thank You.

Yours faithfully
CYCLE & CARRIAGE FRANCE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SMK6066JWIP: 16144

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Turbocharger heat shield	? / SUPP		/ BT	98 070 529 80 40.80
2	Exhaust catalyst muffler	? / SUPP		/ BT Steve	98 124 936 80 (TBA) 43.60
3	Exhaust system clamp	? / SUPP		/ RC Steve 29/11/91	98 091 486 80 263.20
4	Air conditioned freon tube.	? / SUPP		/ BT	98 199 185 80 (TBA)
5	Air conditioned freon tube	? / SUPP		/ BT	98 082 518 80 (TBA)
6	Air conditioned freon tube	? / SUPP		/ BT	98 082 517 80 (TBA)
7	AIR INLET NECK WATER DEFLECTOR	? / SUPP		/ BR	98 890 141 80 77.60
8	FR BUMPER AIR VENTILAT BR DUT RM	? / SUPP		(Intercom) / BR	98 142 079 80 94.40
9	BUMPER BRACKET SET	? / SUPP		(Front panel inner) / BR	16 101 943 80 153.60
10	HL LH	? / SUPP		(Head lamp) / BR	98 020 415 80 569.60
11	FR bumper DEFLECTOR	? / SUPP		(Chrome Headlamp bezel) / BR	98 063 684 80 136.80
12		? / SUPP			
13	RENEW TURBOCHARGER HEAT SHIELD,	? / SUPP			
14	BRASS CATALYST MUFFLER \$	? / SUPP	\$ 500		
15	AIRCON FREON TUBE	? / SUPP			
16		? / SUPP			
17	Set bumper MAT Replacement	? / SUPP			16 175 368 XT
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	8/2/21	Steve
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: C4SURVEYOR: STEVE

User: DA11572

Vehicle : C4 PICASSO C4 SPACETOURER/C4

SPACETOURER (B78)

VIN: VF73AHNYTJJ789406

Reg no: SMK6066J
Before using DIAGBOX to check all the fault

Print date : Monday, 1 March 2021 18:37:43

Start of vehicle session : 01/03/2021 - 18:35

Tool version : 09.87



Global test

Expert/Global test

Vehicle\menu_tgref.s : 81_02

FAMILY NO.

CONTROL UNIT

18



Built-in systems interface

BSI2010_EV (18 Faults)

U1F32 87

Fault: absence of communication with the driver's door control pad

Properties

Cause

Local

Status

Intermittent

Features

-

B181A 87

Fault in the response from the electric steering lock to the request for locking/unlocking

Properties

Cause

Local

Status

Intermittent

Features

No reply

B1808 87

Fault in the unlocking of the immobiliser by the engine management ECU

Properties

Cause

Local

Status

Intermittent

Features

Request missing

B132C 1B

Exterior temperature sensor fault

Properties

Cause

Local

Status Intermittent

Features Resistance too high

B1166 15 Front right direction indicator control fault

Properties

Cause Local

Status Intermittent

Features Open circuit or short circuit to positive

B1167 15 Front left direction indicator control fault

Properties

Cause Local

Status Intermittent

Features Open circuit or short circuit to positive

B1137 15 Front right dipped headlamp control fault

Properties

Cause Local

Status Intermittent

Features Open circuit or short circuit to positive

B1138 15 Front left dipped headlamp control fault

Properties

Cause Local

Status Intermittent

Features Open circuit or short circuit to positive

B117C 12 Exterior lateral lighting control fault

Properties

Cause Local

Status Present

Properties

Status

Permanent

Characterisation of the fault

Configuration incorrect or not carried out

B174E 11

Motorised tailgate lock closing to second notch status switch signal fault

Properties

Status

Intermittent

Characterisation of the fault

Short circuit to earth



Additional heating

Communication error



Hands full access ECU, right-hand side or rear

BAAST



Touch screen

★ **EMF_DGT_LVDS_BD**

Important, ECU present on the vehicle but configured absent




Urea ECU

Not present




Engine wiring housing

Not present



Trailer relay unit

Not present



External CD player

Not present



Audio amplifier

Not present



Multifunction video camera (CMF)

Not present



Anti-theft alarm

Not present




Intrusion alarm siren

Not present



Vehicle Distance Assistance

Not present



Seat driver position memory module.

Not present



Right-hand reversible seat belt inertia reel

Not present



Left-hand reversible seat belt inertia reel

Not present




Dynamic headlamp height adjuster

Not present




Supplies protection and management unit

Not present



Hands-free unit

Not present



Service module / Independent telematic unit

Not present



Diesel additive pump

Not present



Panoramic visual assistance ECU

Not present



Driver's seat comfort ECU

Not present

Help

User: DA11572

Vehicle : C4 PICASSO C4 SPACETOURER/C4

SPACETOURER (B78)

VIN: VF73AHNYTJJ789406

Reg no. SMKG665
after can update to see all the save
Job Done

Print date : Monday, 1 March 2021 18:57:48

Start of vehicle session : 01/03/2021 - 18:35

Tool version : 09.87



Global test

Expert/Global test

Vehicle\menu_tgref.s : 81_02

FAMILY NO.

CONTROL UNIT

1



Built-in systems interface

BSI2010_EV (1 Faults)

B1003 00

Configuration fault (warning, this fault may be a phantom fault)

Properties

Cause

Local

Status

Intermittent

Features

-



Engine management ECU

VD46



Anti-lock Braking System (ABS) or
Electronic Stability Program (ESP)

ESP90



Automatic or piloted manual
gearbox

BVA_AM6_AT6_UDS



Controls under the steering wheel

★ ECU not recognised

Down-grade mode: this information is
not guaranteed



Controls on the steering wheel /
integral controls steering wheel

VCI



Left-hand windscreen wiper motor MOTEV_UDS



Right-hand windscreen wiper
motor

MOTED_UDS



Air conditioning

★ BCC

Important, ECU present on the vehicle
but configured absent

	Instrument panel	CIROCCO
	Rain and brightness sensor	PLUIE_LUMINOSITE_UDS
	Airbags and pretensioners ECU	RBG_UDS
	Battery charge status control unit	BECB_GEN2
	Multifunction control panel	★ <i>ECU not recognised</i> Down-grade mode: this information is not guaranteed
	Parking assistance	★ <i>ECU not recognised</i> Down-grade mode: this information is not guaranteed
1 	Telematic unit (RTx) or audio-navigation	★ <i>ECU not recognised (1 Faults)</i> Down-grade mode: this information is not guaranteed

B1003 55

ECU not recognized : select the "Fault reading" menu to access the description of the fault code

Properties

Status

Permanent

Characterisation of the fault

No configuration



Electronic key reader

Communication error



Electric steering lock

AVE



Signalling fuse box

BSG_S



Driver's door module

PDPC_UDS



Automatic gearbox electric control ECU

COMELEC2



Power steering

DAE_BVH2



Voltage maintaining device

★ **DMTR_DTC3B**

*Important, ECU present on the vehicle
but configured absent*

1



Motorised Boot Unit

VERINS_MOTORISES (1 Faults)

B1003 55

Configuration fault

Properties

Status

Permanent

Characterisation of the fault

Configuration incorrect or not carried out



Additional heating

Communication error



**Hands full access ECU, right-hand
side or rear**

BAAST



Touch screen


★ **EMF_DGT_LVDS_BD**

*Important, ECU present on the vehicle
but configured absent*



Urea ECU

Not present



Engine wiring housing

Not present



Trailer relay unit

Not present



External CD player

Not present




Audio amplifier

Not present



Multifunction video camera (CMF)

Not present



Anti-theft alarm

Not present



Intrusion alarm siren

Not present




Vehicle Distance Assistance

Not present



Seat driver position memory module.

Not present



Right-hand reversible seat belt inertia reel

Not present




Left-hand reversible seat belt inertia reel

Not present




Dynamic headlamp height adjuster

Not present



Supplies protection and management unit

Not present



Hands-free unit

Not present



Service module / Independent telematic unit

Not present



Diesel additive pump

Not present



Panoramic visual assistance ECU

Not present



Driver's seat comfort ECU

Not present

Help