

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21001261/KQD3N2**Date:** 13/10/2021REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29142363QMX

Claimant Vehicle No : SJZ6567L**Insured Vehicle No :** SGM1006B

Date of Loss: 16/01/2021

Nature of Claim: TP

Claim No: 633316

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJZ6567L**

Make & Model: VOLKSWAGEN SCIROCCO, 1.4 TSI (A)

Engine No: CAV234436

Reg. Date: 16/12/2010 (Man. Year: 2010)

Chassis No: WVVZZZ13ZBV015975

Colour: Metallic Black

Odometer: 179676 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40 R18

Rear Tyre Size: 235/40 R18

Front Left Side: Goodyear 8 mm

Rear Left Side: Goodyear 8 mm

Front Right Side: Goodyear 8 mm

Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,161.00	1,091.07	69.93	6.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	550.00	450.00	100.00	18.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,711.00	1,541.07	169.93	9.93
+ GST 7.00/7.00% (S\$)	119.77	107.87	11.90	9.94
Nett Amount (S\$)	1,830.77	1,648.94	181.83	9.93

INSPECTION

Date of Assignment: 26/01/2021

Date Inspected: 27/01/2021 Inspected At:

Chew Goon Motor (AMK)

Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 &

17, AMK Autopoint

Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Oct 2021)
Parts:	144	VOLKSWAGEN SCIROCCO 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ6567L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Dented	1,200.00 FL	*1,122.30 FL
2	8		*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
3	1		*REAR NUMBER PLATE	Scratched	45.00 FS	*45.00 FS
					Sub Total (S\$)	1,285.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	124.00
					Total Parts (S\$)	1,161.00
						1,091.07

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER REAR REVERSE SENSORS.REBORE SENSOR HOLD & REWIRING ETC	New	80.00	50.00
2	LABOUR CHARGE-PANEL BEATING,REPAIRING OF REAR BUMPER REINFORCEMENT,BRACKETS AND PARTS REPLACEMENT	New	220.00	200.00
3	TO RESPRAY AFFECTED AREAS	New	250.00	200.00
Gross Labour Cost (\$\$)			550.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >