



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2103338

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 12/05/2021
Reference CC6/CTI21001263/Ars3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SGF 6650U
Insured Veh. GBK 3700L
Claim No. SNM21D200409/LKKDS
Policy No. DMCVSNA00053312000
Accident Date 21/01/2021
Inspection Date 25/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21001263/Ars3q2 Date: 12/05/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 3700L	Veh. Inspected	SGF 6650U	
Policy No.	DMCVSNA00053312000	Coverage (\$)	0.00	
Claim No.	SNM21D200409/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	25/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI COLTPLUS	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JMYLTZ23W6Z000428	Colour	BLACK	
Odometer	295733 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	DAYTON	6 mm	
L/H Front Tyre	195/55 R15	DAYTON	6 mm	
R/H Rear Tyre	195/55 R15	DAYTON	6 mm	
L/H Rear Tyre	195/55 R15	DAYTON	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/01/2021	Inspection Date	25/01/2021	
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGF 6650U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	REAR NUMBER PLATE LAMP @\$45.00	O/S CRACKED	90.00	45.00
1	REAR BUMPER	DEFORMED	592.00	592.00
2	REAR BUMPER SIDE HOLDER @\$25.00	NECESSARY	50.00	50.00
2	REAR BUMPER REFLECTOR @\$27.00	NOT NECESSARY	54.00	-
1	REAR END PANEL	DENTED	342.00	342.00
1	REAR END PANEL TOP GARNISH	DEFORMED	166.00	166.00
2	TAILLAMP @\$485.00	CRACKED	970.00	970.00
1	TAILGATE	DISTORTED	835.00	835.00
1	TAILGATE LOCK	DAMAGED	374.00	374.00
1	TAILGATE WEATHERSTRIPE	CUT	162.00	162.00
1	TAILGATE OUTER MOULDING	DEFORMED	131.00	131.00
1	TAILGATE INNER TRIM BOARD	CRACKED	274.00	274.00
2	TAILGATE REFLECTOR @\$268.00	CRACKED	536.00	536.00
1	TAILGATE WIPER MOTOR	DAMAGED	374.00	374.00
1	TAILGATE GLASS MOULDING	NECESSARY	68.00	68.00
1	MITSUBISHI LOGO	NECESSARY	38.00	38.00
1	COLT PLUS WORDING	NECESSARY	69.00	69.00
2	REAR FENDER INNER TRIM BOARD @\$179.00	NOT NECESSARY	358.00	-
1	SPARE TYRE PANEL TOP COVER	DEFORMED	494.00	494.00
1	REAR EXHAUST PIPE	NOT NECESSARY	364.00	-
1	REAR EXHAUST PIPE MOUNTING	NOT NECESSARY	38.00	-
	LESS 10% DISCOUNT		-637.90	-552.00
			5,741.10	4,968.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	BENT	30.00	30.00
1	REAR NUMBER PLATE HOLDER (SN)	DEFORMED	30.00	30.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
1	SET REVERSE SENSOR (SN)	DAMAGED	280.00	200.00

Report Ref No. CC6/CTI21001263/Ars3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR CAMERA (SN)	DAMAGED	480.00	380.00
1	SET TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	50.00	30.00
1	SET TAILGATE GLASS SEALANT (SN)	NECESSARY	60.00	60.00
2	SETS REAR FENDER INNER TRIM BOARD CLIPS @ \$30.00 (SN)	NOT NECESSARY	60.00	-
			1,120.00	840.00
	LABOUR			
	PANEL BEATING ,REMOVE AND REFIT PARTS.		1,200.00	1,000.00
	SPRAY PAINTING TO AFFECTED AREA.		1,200.00	900.00
	WIRING CHECK .		50.00	30.00
	TO APPLY TUFF COAT.		150.00	60.00
	TO REMOVE REVERSE SENSOR .		100.00	50.00
	TO REMOVE REAR CAMERA.		100.00	50.00
	TO REMOVE UPHOLSTERY .		150.00	60.00
	TO TRANSFER TAILGATE FITTINGS .		150.00	80.00
	TO REMOVE TAILGATE GLASS .		180.00	120.00
	TO REMOVE EXHAUST PIPE .	NOT NECESSARY	150.00	-
			3,430.00	2,350.00
GRAND TOTAL			10,291.10	8,158.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,500.00

Report Ref No. CC6/CTI21001263/Ars3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGF 6650U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGF 6650U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

