

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21001266/KPS3Q2**Date:** 06/09/2021REFERENCE

| | | | |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer: | India International Insurance Pte Ltd | Policy No: | D20MFL0005826 |
| Claimant Vehicle No : | SMX3266A | Insured Vehicle No : | SMV495K |
| Date of Loss: | 23/01/2021 | Nature of Claim: | TP |
| | | Claim No: | MFL2021D0002100 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SMX3266A | Engine No: | HIDDEN |
| Make & Model: | TOYOTA PRIUS, 1.8 HYBRID CVT (A) | Chassis No: | JTDKB3FU903092514 |
| Reg. Date: | 23/01/2021 (Man. Year: 2021) | Odometer: | 4705 km |
| Colour: | Metallic Red | | |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition: | | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 195/65 R15 | Rear Tyre Size: | 195/65 R15 |
| Front Left Side: | Dunlop 9 mm | Rear Left Side: | Dunlop 9 mm |
| Front Right Side: | Dunlop 9 mm | Rear Right Side: | Dunlop 9 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 2,212.03 | 280.88 | 1,931.15 | 87.30 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 5,100.00 | 60.00 | 5,040.00 | 98.82 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 7,312.03 | 340.88 | 6,971.15 | 95.34 |
| + GST 7.00/7.00% (S\$) | 511.84 | 23.86 | 487.98 | 95.34 |

| | | | | |
|--|-----------------|---------------|-----------------|--------------|
| Nett Amount (S\$) | 7,823.87 | 364.74 | 7,459.13 | 95.34 |
| | | | | |
| + Car Rental (1.0 x S\$65.00/day) (S\$) | | 65.00 | | |
| + Doc/Search Fee (S\$) | | 7.45 | | |
| | | | | |
| Nett Liability (S\$) | | 437.19 | | |
| Global Sum Settlement (S\$) | | 430.00 | | |

INSPECTION

Date of Assignment: 27/01/2021

Date Inspected: 27/01/2021

Estimated Period of Repair: 0.5 days

Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 30 Aug 2021) |
| Parts: 144 | TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SMX3266A) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|-----|-----|----------|--------------------------------------|---------------|--|-----------------|---------------|
| 1 | 1 | | *COVER ,REAR BUMPER | Serviceable | 485.60 FL | *- FL | |
| 2 | 1 | | *GUARD ,REAR BUMPER CENTER | Dented / Cut | 374.51 FL | *374.51 FL | |
| 3 | 1 | | *REINFORCEMENT SUB-ASSY ,REAR BUMPER | Repair | 332.70 FL | *- FL | |
| 4 | 1 | | *SEAL ,REAR BUMPER SIDE ,LH | Serviceable | 118.30 FL | *- FL | |
| 5 | 1 | | *RETAINER ,REAR BUMPER SIDE ,LH | Serviceable | 132.60 FL | *- FL | |
| 6 | 1 | | *REFLECTOR ASSY ,REFLEX ,LH | Serviceable | 39.00 FL | *- FL | |
| 7 | 1 | | *REAR BUMPER SIDE CLIP | Not Necessary | 60.00 FS | *- FS | |
| 8 | 1 | | *SET PARKING AID | Serviceable | 700.00 FS | *- FS | |
| 9 | 1 | | *SET REAR BUMPER CLIP | Not Necessary | 85.00 FS | *- FS | |
| 10 | 1 | | *REAR BUMPER PROTECTOR | Not Necessary | 180.00 FS | *- FS | |
| 11 | 1 | | *REAR BUMPER RETAINER CLIP | Not Necessary | 75.00 FS | *- FS | |
| | | | | | Sub Total (\$\$) | 2,582.71 | 374.51 |
| | | | | | - List Item Discount on L Items 25.00/25.00% (\$\$) | 370.68 | 93.63 |
| | | | | | Total Parts (\$\$) | 2,212.03 | 280.88 |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|--------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS | New | 240.00 | 0.00 |
| 2 | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR | New | 380.00 | 0.00 |
| 3 | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME | New | 1,600.00 | 60.00 |
| 4 | TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 380.00 | 0.00 |
| 5 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 1,600.00 | 0.00 |
| 6 | TO REINSTALL REAR BUMPER PARKING SENSOR | New | 170.00 | 0.00 |
| 7 | TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING | New | 170.00 | 0.00 |
| 8 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | 0.00 |
| 9 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 0.00 |
| 10 | TO REMOVE AND REFIT OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| | | | Gross Labour Cost (S\$) | 5,100.00 |
| | | | | 60.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >