

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21001271/GPS3Q2  
**Date:** 19/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100342583
<b>Claimant Vehicle No :</b>	SHA2990D	<b>Insured Vehicle No :</b>	SKK1320G
Date of Loss:	26/01/2021	Nature of Claim:	TP
		Claim No:	3499437121SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHA2990D</b>		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU295297
Reg. Date:	26/06/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU164326
Colour:	Blue	Odometer:	134022 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	851.12	433.60	417.52	49.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	640.00	140.00	17.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,631.12</b>	<b>1,073.60</b>	<b>557.52</b>	<b>34.18</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>114.18</b>	<b>75.15</b>	<b>39.03</b>	<b>34.18</b>

<b>Nett Amount (S\$)</b>	<b>1,745.30</b>	<b>1,148.75</b>	<b>596.55</b>	<b>34.18</b>
<b>+ Loss of Use (2.5 x S\$50.00/day) (S\$)</b>		125.00		
<b>+ Car Rental (2.5 x S\$125.19/day) (S\$)</b>		312.98		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,588.73</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,580.00</b>		

INSPECTION

Date of Assignment: 27/01/2021

Date Inspected: 27/01/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)  
 59 Loyang Drive  
 Singapore 508969

**Adjuster:** XING GUO QIANG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -RR BUMPER	Repair	459.40 FL	*- FL
2	10		*BUMPER COVER CLIP REAR	Necessary	22.00 FL	*22.00 FL
3	1		*MOULDING ASSY -RR BUMPER C	Deformed	451.25 FL	*451.25 FL
4	1		*NO PLATE (S) WITH TRIM COV	Cracked	55.00 FS	*55.00 FS
5	1		*PROTECTOR MAT	Not Necessary	50.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	1,037.65 528.25
					- List Item Discount on L Items 20.00/20.00% (\$\$)	186.53 94.65
					Total Parts (\$\$)	851.12 433.60

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT ON AFFECTED AREA	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>780.00</b>	<b>640.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >