

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG21001276/APS3Q2

**Date:** 29/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100398007

**Claimant Vehicle No :** SMF5066S **Insured Vehicle No :** ES8818X

Date of Loss: 09/01/2021 Nature of Claim: TP Claim No: 6816861012SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMF5066S</b>		
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Engine No:	FB20YE43346
Reg. Date:	15/11/2018 (Man. Year: 2018)	Chassis No:	JF1SJ5KC5JG112232
Colour:	White	Odometer:	32549 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/60R17	Rear Tyre Size:	225/60R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,062.31	982.31	80.00	7.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	910.00	450.00	460.00	50.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>1,972.31</b>	<b>1,432.31</b>	<b>540.00</b>	<b>27.38</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,100.00</b>		
<b>Nett Amount (\$\$)</b>	<b>1,972.31</b>	<b>1,100.00</b>	<b>872.31</b>	<b>44.23</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (\$\$)</b>		300.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>1,407.45</b>		

### INSPECTION

Date of Assignment: 22/01/2021

Date Inspected: 22/01/2021 Inspected At:

Sin Hwee Motor Pte Ltd (HQ)  
Blk 3023A, Ubi Road 1, #01-59  
Singapore 408717

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	582.12 FL	*582.12 FL
2	1		*REINFORCEMENT	Bent	395.77 FL	*395.77 FL
3	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
					<b>Sub Total (S\$)</b>	<b>1,257.89</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>195.58</b>
					<b>Total Parts (S\$)</b>	<b>982.31</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO INSTALL AND CALIBRATE REVERSE SENSOR	New	60.00	50.00
2	TO REPLACE,INSTALL AND ALIGN REPLACED PARTS TO SYMMETRICAL SPEC	New	450.00	200.00
3	TO SPRAY PAINT REAR BUMPER	New	400.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>910.00</b>	<b>450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >