

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21001281/R1QF3Q2  
**Date:** 22/03/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00196242000
Claimant Vehicle No :	SGX3066G	Insured Vehicle No :	SLN3655A
Date of Loss:	25/01/2021	Nature of Claim:	TP
		Claim No:	SNM21D200424/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGX3066G	Engine No:	PE31047070
Make & Model:	MAZDA BIANTE, 2.0 (A)	Chassis No:	JM6CC1071H0110904
Reg. Date:	25/05/2017 (Man. Year: 2017)	Odometer:	36263 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,880.30	4,349.90	3,530.40	44.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,710.00	6,200.00	7,510.00	54.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>21,590.30</b>	<b>10,549.90</b>	<b>11,040.40</b>	<b>51.14</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,511.32</b>	<b>738.49</b>	<b>772.83</b>	<b>51.14</b>
<b>Nett Amount (S\$)</b>	<b>23,101.62</b>	<b>11,288.39</b>	<b>11,813.23</b>	<b>51.14</b>

### INSPECTION

Date of Assignment:	27/01/2021		
Date Inspected:	22/02/2021	Inspected At:	Trans Eurokars Pte Ltd (Ubi) 5 Ubi Close Singapore 408605
Estimated Period of Repair:	8.0 days		

**Adjuster:** MOHD RASUL

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2021)
<b>Parts:</b>	M1-MPV	MAZDA BIANTE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGX3066G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,170.50 FS	*1,170.50 FS
2	1		*RETAINER LHS	Serviceable	48.80 FS	*- FS
3	1		*RETAINER RHS	Serviceable	48.80 FS	*- FS
4	2		*GROMMET,REAR BUMPER	Necessary	6.40 FS	*6.40 FS
5	2		*RIVET,REAR BUMPER	Necessary	7.60 FS	*7.60 FS
6	2		*FASTENER,REAR BUMPER	Necessary	6.40 FS	*6.40 FS
7	1		*PIN LOCATOR,REAR BUMPER	Necessary	4.20 FS	*4.20 FS
8	2		*GROMMET,REAR BUMPER	Necessary	9.40 FS	*9.40 FS
9	1		*CAP,REAR BUMPER	Serviceable	3.50 FS	*- FS
10	2		*TAPE PROTECTOR,REAR BUMPER	Necessary	7.00 FS	*7.00 FS
11	1		*REFLECTOR LHS,REAR BUMPER	Serviceable	124.50 FS	*- FS
12	1		*REFLECTOR LHS,REAR BUMPER	Serviceable	124.50 FS	*- FS
13	1		*STRIPE LHS,REAR BUMPER	Necessary	86.00 FS	*86.00 FS
14	1		*STRIPE LHS,REAR BUMPER	Necessary	86.00 FS	*86.00 FS
15	1		*STRIPE CENTER,REAR BUMPER	Necessary	130.10 FS	*130.10 FS
16	1		*TAILGATE	Bent	1,699.70 FS	*1,699.70 FS
17	1		*WEATHERSTRIP,TAILGATE	Serviceable	218.30 FS	*- FS
18	2		*VALVE ONEWAY,TAILGATE	Necessary	24.00 FS	*24.00 FS
19	3		*FASTENER,TAILGATE	Necessary	16.80 FS	*16.80 FS
20	1		*LOCK,TAILGATE	Jammed	264.60 FS	*264.60 FS
21	1		*PIN STUD,REAR WINDSCREEN	Necessary	11.10 FS	*11.10 FS
22	1		*SPACER,REAR WINDSCREEN	Necessary	18.80 FS	*9.40 FS
			(4 Pcs )			
23	5		*SPACER,REAR WINDSCREEN	Necessary	64.00 FS	*64.00 FS
24	2		*FASTENER,REAR WINDSCREEN	Necessary	16.40 FS	*16.40 FS
25	2		*FASTENER,REAR WINDSCREEN	Necessary	5.60 FS	*5.60 FS
26	3		*FASTENER,REAR WINDSCREEN	Necessary	18.60 FS	*18.60 FS
27	1		*FINISHER,TAILGATE	Serviceable	2,018.60 FS	*- FS
28	1		*CHROME,TAILGATE	Serviceable	555.30 FS	*- FS
29	1		*GARNISH LHS,FINISHER	Serviceable	18.20 FS	*- FS
30	1		*GARNISH RHS,FINISHER	Serviceable	18.20 FS	*- FS
31	1		*ORNAMENT,SKYACTIV	Necessary	117.10 FS	*117.10 FS
32	1		*TRIM,END PANEL	Serviceable	122.30 FS	*- FS
33	1		*NUMBER PLATE	Not Necessary	140.00 FS	*- FS
34	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
35	1		*REAR END PANEL	Bent	303.20 FS	*303.20 FS
36	1		*ANTENNA	Cracked	265.80 FS	*265.80 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>7,880.30</b>	<b>4,349.90</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER AND TAILGATE.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	3,780.00	1,320.00
2	TO RESPRAY REAR BUMPER AND TAILGATE	New	4,800.00	1,260.00
3	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	560.00	560.00
4	TO SUPPLY SEALER ON THE WINDSCREEN GLASS	New	120.00	120.00
5	TO TRANSFER REVERSE SENSOR (WITH REVERSE SENSOR)	New	660.00	330.00
6	TO TRANSFER REVERSE CAMERA (WITH REVERSE CAMERA)	New	660.00	0.00
7	TO TRANSFER TAILGATE MECHANISM	New	330.00	330.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
9	TO CARRY-OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CAOUTCHouc)	New	250.00	0.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
11	TO REPLACE END PANEL	New	1,320.00	1,320.00
12	TO RESPRAY END PANEL	New	630.00	630.00
<b>Gross Labour Cost (\$\$)</b>			<b>13,710.00</b>	<b>6,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >